CCX-2000-0115

## The Standard AIRCRAFT LOG

ASA-SA-1

Air	rcraft Record General Information
Manufacturer: Oklahoma Fat Tire F	lyers LLC Model: CCX-2000
Aircraft Serial Number: CCX-2000-0115	Registration Number: N58QT
Date of Manufacture:	
Engine Currently Installed:	
Manufacturer: Lycoming Mo	odel Number: CC363i (YIO-360-EXP128) S/N: CC363i-2110
Propeller Currently Installed:	
Manufacturer: Hartzell Mo	odei Number: HC-C2YR-1NW/NG8301W S/N: NS5606B
	(P\$A () 4) A
	grand state

Dei ameran nas (	peen painted according to the fol	lowing paint specifications:
Paint Theme:	Signature	N# Location: E4
Main Color:	923995	Titan Grey
Base Color:	35027	Metallic Silver
Trim Color 1:	TBD	TBD
Trim Color 2:	TBD	
		TBD
-		

YEAR 20	TOTAL TIME IN	Current Weigh	nt and Balance Inf	formation	
DATE	SERVICE	Empty Weight	Empty CG	Useful Load	Remarks
					*

YEAR 20	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Te	sts, Repairs and Alterations e, Rating and Certificate Number of Technician or
D			SERVICE	The state of charles with I wall	e, having and Certificate Number of Technician or
• TI w • TI w Deta Date Altim	he ATC Transpo ith Part 43, App	onder test rendix F.  ormed are of the control of t	required by 1 on file under	4 CFR Part 91.411 has been performed 4 CFR Part 91.413 has been performed Work Order #OO(764)  Transponder Model: GTX3  Transponder S/N: 3EHY2  Certificate #CCRO  Certified R  4CCI	in accordance
N#: N	58QT		S/N: 0	CCX-2000-0115	CUBCRAFTERS
have a nspecte	ssembled this ed and found to	aircraft to be in co	from plans ondition fo	and materials supplied by CubCra or safe operation within the scope a A.J. Howerlow Print Name	afters Inc. This aircraft has been ground tester and detail of 14 CFR Part 43, Appendix D.  03/17/2021 Date

\*

RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME SERVI	N	Description of Insperentials of Insperentials must be endorsed Repair Facility. (See back	ed with Name, Rati	ing and Ce	rtificate Numbe	ns er of Techn	ician or
#: N58QT				: CCX-2000-0115			`	AFTERS	
ext Condition Insp	ection is du	ie: 3	me	2022					
		> 6	343	336361	GANCEY	FRAN	18	mard	1021
	5		3 <b>43</b> )AR#		Print Name	FRAN	L 18	Date	102 (
	5				Print Name	FRAN	L /8	Date	102 (
ignature					Print Name	FRAN	1 / 2	Date	DQL (
	5				Print Name	FRAN	1 / 8	Date O	DQL (

0_08	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician Repair Facility. (See back pages for other specific entries.)
	De Da	with Part 4 The ATC 1 with Part 4 etails of wo ate:	3, Appendix	Certificate # YCCRO16C  Cubcraftes  Certificate # YCCRO16C  Certified Repair Station 4CCR016C
			-	
		-		

R E	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	Tail#: Make: I certify control be exe	lable thro cuted, ha	ters prescribed f ughout its n s no hazard	Model: CCX-2000  S/N: CCX-2300-0115  Right test has been completed and the aircraft is normal range of speeds and throughout all maneuvers to dous operating characteristics or design features, and is is complete for this aircraft and is operating in Phase II.  ense #3793156  Charlin Hadium II.
				2KSB003 NC CCX/K-S000 CCX-S

Airframe opened/depaneled to facilitate an Experimental Category ANNUAL / CONDITION INSPECTION IAW and following all applicable checks included in the CubCrafters Maintenance Manual Appendix A and FAR Part 43 Appendix D, as applicable. In addition to all inspection points covered on the Appendix A form, accomplished the following work:

- 1) Replaced the IBBS battery with customer supplied new IBBS battery.
- 2) Replaced front pilot seat with new seat provided by Cub Crafters due to seat bottom fabric failure.
- 3) Repaired left wing fuel tubing leak by removal of the pilot sidewall panel and re-positioning available fuel tubing to allow for an additional useable tubing length at the wing fitting. Re-connected fitting and tubing, tightened and filled left wing tank with fuel. No leaks noted. Re-installed left wing root access panel.
- 4) Performed a Kannad ELT op's. check IAW Kannad instructions and an ELT functional test IAW FAR 91.207 (d) 1-4. Operation and functional checks are normal. Battery due date on ELT battery is 5/27.
- 5) Performed a pitot heat check op's check was good. Pitot / static system recertification is due on or before 4/30/23.
- 6) Re-located fuel caps to correct orientation with vent tubes facing forward.
- 7) Researched CubCrafters online Support site for applicable manufacturer's Mandatory SB's and FAA issued AD's none found as of this date applicable to the model and S/N of subject aircraft, engine or propeller.

This airframe has completed an Annual / Condition Inspection, was found to be in an airworthy condition and is returned for service on this date.

Date: 4/2/22

PO No: verbal

James P. Stiles A&P 3412843 IA

PO No

Airfram the Cut A form

1) IBBS

Ignit
 Perfi

normal 4) Perfi

5) Rese the mo

6) See o Annual This air

Date:

Integrity Airmotive, LLC Tach: 160.4 Hangar 54 Hobbs: Hefrer - Easley Airport TTAF: 160.4 Wagoner, DK Model: CCX-2000 FX3 (918)-640-7817 S/N: CCX-2000-0115 Reg. No: N58QT **Customer: Tony Howerton** Furframe opened/depaneled to facilitate an Experimental Category ANNUAL / CONDITION INSPECTION IAW and following all applicable checks included in PO No: verbal the CubCrafters Maintenance Manual Appendix A and FAR Part 43 Appendix D, as applicable. In addition to all inspection points covered on the Appendix A form, accomplished the following work this date: 1) IBBS battery has been ordered and will be replaced by the owner as soon as received. 2) Ignition back-up battery has been ordered and will be replaced by the owner as soon as received. 3 Performed a Kannad ELT op's. check IAW Kannad instructions and an ELT functional test IAW FAR 91.207 (d) 1-4. Operation and functional checks are normal. Battery due date on ELT battery is 5/27. 4 Performed a pitot heat check - op's check was good. Pitot / static system recertification is scheduled for week of 5/8/23. 5] Researched CubCrafters online Support site for applicable manufacturer's Mandatory SB's and FAA issued AD's - none found as of this date applicable to me model and S/N of subject aircraft, engine or propeller. See completed CubCrafters inspection form Appendix A pages 5 - 14 dated 5/5/23 in the aircraft files for all inspection points signed-off at this This airframe has completed an Annual / Condition Inspection, was found to be in an airworthy condition and is returned for service on this date. James P. Stiles A&P 3412843 IA Date: 5/5/23 NA DY AF SN CCK-5 CCX/K-5000 NC 2K-2B003 CCX-5

**Airframe** 

YEAR 20 Date _	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and A Entries must be endorsed with Name, Rating and Certific Repair Facility. (See back pages for other specific entries	ate Number of Technician or
	wo: RS	SWO_1934	17	FORWARDVUE	Airframe - page 1 of 1
	Fo	orwardVue	Aviation - 19	AVIATION 9502 E Rogers Post Rd - Claremore, OK 74019 - 918-236-0	093 - CRS#: 3FVR712D
	N58Q Engine	<b>T</b> e: 152.8		Carbon Cub, FX3, S/N: CCX-2000-0115 TTAF: 160.7	May 11, 2023
	2. R	e-calibrat	ted Garmir	c / Transponder (IFR) Certification tests per Work Orden G5. ed in aircraft records.	r#193417 CRS 3FVR712[
	includin	g data co	rresponde	and static system tests required by 14 CFR Part 9 nce, required by Part 91.413, have been performed as E and F.	
		END			
	Forward	N/ua Avia	tion CDS 9	BFVR712D Wale Wall	

¥

YEAR 20 <u>23</u> DATE 10 / 3	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
0/10	162.9	×	171.3	Replaced both main tires and fail wheel
				tire w/factory replacement tives
				provided by Alaska Bushwheel, Inc.
				Torqued main hubs to 105 in/165 and
				tail wheel hub to 90 in/165. Inflated
				mains to 14 psi or tail to 20 psi.
				Airplane is retryred topservice this date
				10/10/23 James 11/4 3412843 IA
	-			
	_			
				2K-2B003 NC CCX/K-5000 CCX-5

CUBCRAFTERS

1920 South 16th Ave - Yakima, WA 98903 (KYKM) Phone: (509) 248-1025

Fax: (509) 853-2783

03/17/2025

Oklahoma Fat Tire Flyers LLC

CCX-2000

SN CCX-2000-0115

N58QT

TH: 209.3

Lycoming Hartzell

CC363i

SN CC363i-2110

EH: 197.6

ETT: 197.6

HC-C2YR-1NW SN NS5606B Assembled aircraft with the following new components: RH Wing assembly SK310100-104; Stall warning horn assy VP7201-001; Both landing light lens SC31062-001, Wing tie down rings SK30300-001; Aileron assemblies PC33500-01 & -002; Both flap assemblies XC35000-001 & -002; Both flap rod assemblies XC32300-001; Both fwd wing root fairings SC31068-001 & -002; Both rear wing root fairings SC31069-001 & -002; Both wing root interface fairings SC23212-001 & -002; 8 ea 5" round inspection covers TC9101-001; Fwd RH lift strut assembly SK37100-002; Aft RH lift strut assembly SK37200-002; 4 ea lift strut forks XC37102-001; Fwd Jury strut SK37301-001; Aft Jury strut SC37301-001; Jury strut spacer SK37301-003; Both flap assemblies XC35000-001 & -002; Both flap gap seals SC31057-001; Elevator assembly XC80100-002; RH elevator trim tab SC81031-002; Fwd liner tube XC15008-001; Aft liner tube XC15009-001; Windshield SP10500-001; Both side windows assemblies SC23200-001 & -002; Both D-Windows PC27001-001; Skylight assembly SC23020-003; Fuel tank bay covers SC30200-001 & -002; Scupper rings TC9004-012; Both fuel sight gauges SP60300-001; NAV lights SP34101-101, SP34102-101, SP34203-001; Turtle deck assembly SC26002-001; RH landing gear leg XC41010-104; Cabane Vee XC41600-001: 2 ea ACME Pro Series Black Ops shocks SP41501-007; 1 ea 29" ABI heavy tread tire VP1006-009; Safety Cable kit Safe-Cable-3X; Torque tube assembly SC92201-001; Misc. placards as needed. Assembled aircraft with the following repaired components: LH Wing SK30100-103. Installed repaired Hartzell Propeller, HC-C2YR-1NW, SN NS5606B, PTT: 197.6, repaired by NW Propeller under work orders 8WC10836 & 8WC10846. Aircraft assembled with new hardware. Weighed aircraft. Equipment list, weight and balance updated. I certify that the work specified above was carried out in accordance with Cub Crafters drawings, policies, procedures, process specs, and FAA airworthiness regulations. Aircraft assembled using new hardware. Work performed under Cub Crafters Service's job #

----Continued on next page--

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Entries must b	of Inspections, Te be endorsed with Name v. (See back pages for o	e, Rating and	Certificate Numb	<b>ns</b> er of Tecl	hnician or
				Continued to	trom previous page				
Appendix inspected registration VP5642-0 inspected harness who noted; SK seals to cuaircraft har found to be facility of the culture of the c	A. Replaced ELT IAW 14 n due 01/203 05; SK-SB0 iury strut braires, routed c -SB011 Revurrent configurations a beau increase.	Lycon Hartze onditiona the follow CFR 91.2 1. CW the 05 Rev No cket rivets orrectly, r NC, Insper	linspection in the control of the co	Elyers LLC CCX-2000 CC363i HC-C2YR-1NW in accordance with new: Backup iscrepancies not Cub Crafters Ser fuel fitting for lancies noted, du bies noted, du bies noted, SK-5 of Beringer mas drun and leak control to the manufacture.	SN CCX-2000-0115 SN CC363i-2110	N58QT bon Cub, EX l; induction for 15/2027. Transport of discrepance of the control of the contr	insponder cert due NC, installed 62 ies noted; SK-SE NC, inspected I stick clearance, r lev NC, installed overnor RPM's s procedure on 03/	intenance 01. Teste 03/2027 micron 3007 Rev H wing no discrep window set. I cert	7. Federal fuel filter NC, root audio pancies and door tify that this
						CCX-2	CCX/K-2000	NC	2K28003



Model\_


CCX-2000

Registration#\_

N58QT Hildebrand

<b>5</b>	ervices		S/N of Aircraft		Inspector SERVICE ALERTS	Hildebrand		
SA	Rev	Model	Effectivity	Description	Method of Compliance	Date & Hours	Next Due	Signature and Number
SK-SA001	NC	CC11 CCX-1865 CCX/K-2000 CCX-2300	CC11-160-0433 thru -0435 SN Prior to CCX-1865-0031 SN Prior to CCK-2000-0056 SN Prior to CCX-2000-0113 SN Prior to CCX-2300-0020	GSU 25C Isolator Bushings	Install Isolator Bushing for Garmin GSU 25C.			NA by AF SN
2144	В	CCX-1865 CCX-2000- CCX-2300	CCX-1865-0001 thru -0031 CCX-2000-0001 thru -0113 CCX-2300-0001 thru -0020	GSU 25C Isolator Bushings	Install Isolator Bushing for Garmin GSU 25C.			NA by AF SN
				CCX/K 2000 S	SERVICE BULLETINS			
SB	Rev	Model	Effectivity ,	Description	Method of Compliance	Date & Hours	Next Due	Signature and Number
SK-SB001	NC	CCX-2000	CCX-2000-0001 thru 0010 & - 0016	Elevator Cable Pulley Retrofit Installation	Install Elevator Control Pulley			NA by AF SN
SK-SB002	NC	CCX/K-2000	CCX-2000-0002 thru -0034 CCX-2000-0036 thru -0043 CCK-2000 with engine kits shipped prior to 02/01/2019	Timing Ring Inspection	Inspect timing ring for secure hardware			NA by AF SN
SKSB003	NC	CCX/K-2000	CCX-2000-0001 and on CCK-2000-0001 and on	Inspection and Replacement of fuel filter	Replace fuel filter with 62 micron filter assembly	03/17/2025 EH 197.6		Todd Hildebrand A&P 3089718 IA
SK-SB004	NC	CCX/K-2000	CCK-2000-0001 thru -0057 CCX-2000-0001 thru -0065	Aft Seat Inspection	Inspect aft seat for minimum of 6 threads per inch			NA by AF SN
SK-SB005	NC	CCK/X-1865 CCK/X-2000	All CCK/X-1865/2000	Fuel Fitting Inspection	Inspect fuel line fittings for leaks	03/17/2025 EH 197.6		Todd Hildebrand A&P 3089718 IA
SK-SB007	NC	CCK/X-1865 CCK/X-2000	All CCK/X-1865/2000	Jury Strut Bracket Rivets	Inspect for loose rivets Replaced all rivets with screws	03/17/2025 EH 197.6	Each Pre Flight	Todd Hildebrand A&P 3089718 IA
SK-SB008	NC	CCK/X-1865 CCK/X-2000	All CCK/X-1865/2000	LH Wing Root Audio Harness Wires	Inspect for clearance	03/17/2025 EH: 197.6		Todd Hildebrand A&P 3089718 IA
SK-SB009	NC	CCK/X-1865 CCK/X-2000	All CCK/X-1865/2000	Rear Stick Clearance	Inspect and modify stick as needed	03/17/2025 EH: 197.6		Todd Hildebrand A&P 3089718 IA
SK-SB010	NC	CCK/X-2000	CCX-2000-0001-0114 CCK-2000-0001 and on	Inspection & Replacement of Ignition Coil Connectors	Inspect for loose 90* connectors. Replace with straight connectors if needed			NA by AF SN
SK-SB011	NC	CCX/K-2000	CCX/K-2000-0001 and on with Beringer Brakes installed	Inspection & Tightening of Beringer Master Cylinder Jam Nuts	Inspect and tighten master cylinder jam nut	03/17/2025 EH 197.6		Todd Hildebrand A&P 3089718 IA
SK-SB012	NC	CCX-2000	CCX-2000-0001 thru -0114	Ignition Coil Bracket Replacement	Replace weldment if needed			NA by AF SN

	r				RVICE INSTRUCTIONS  Method of Compliance	Date & Hours	Next Due	Signature and Number
SI	Rev	Model	Effectivity	Description	Wethod of Compilance	Date & Hours	Next Due	Olghatare and Hamber
SK-SI001	NC	CCK/X-2000	CCK/X-2000-0001 thru -0072	Propeller Lever Spring Retrofit Instructions	Install Propeller Control Spring			NA by AF SN
SK-SI002	NC	CCK/X-2000	CCK-2000-0001 thru -0057 CCX-2000-0001 thru -0052	Fuel Filter Relocation	Relocate Fuel Filter Assembly			NA by AF SN
SK-S1003	NC	CCK/X-2000	CCK/X-2000-0001 and on	Mixture Cable Replacement	Replace mixture control cable to provide smooth operation, changed with Vernier mixture control cable			Not required at this time
SK-SI004	NC	CCK/X-2000	CCK-2000-0001 thru -0057 CCX-2000-0001 thru -0105	Bridle Cable Clamp Replacement	Replace Bridle Cable Clamps			NA by AF SN
SK-SI006	NC	CCK/X-2000	CCK/X-2000-0001 thru -0114	Ignition Coil Bracket Replacement	Replace Bracket to Install new model coils.			NA by AF SN
SK-SI008	NC	ССХ	CCX-2000-0001 and on	Door and Window Seal	Install door and window seals	03/17/2025		Todd Hildebrand A&P 3089718 IA
OK Globs	1,10			Installation	as needed	EH: 397.3	\$12.00E-20.00E-20.00E-20.00E-20.00E-20.00E-20.00E-20.00E-20.00E-20.00E-20.00E-20.00E-20.00E-20.00E-20.00E-20.0	70097 TO IA
CK-SI001	NC	CCK/X-1865 CCK/X-2000	All aircraft withH3R Extinguishers	Increased Fire Extinguisher Inspection	Inspect and or replace fire extinguisher			NA by Configuration A344 Extinguisher installed
SI0039	NC	CCX-1865 CCX-2000	CCX-1865 All CCX-2000 Ali	Beringer Brakes	Install Beringer wheels and brakes at owner discretion			Installed during aircraft build
SI0040	NC	CCX-1865 CCX-2000	CCX-1865 prior to -0039 CCX-2000 prior to -0179	Wig Wag Flasher	Replace flasher if needed			Not required at this time
				CCX/K 200	0 SERVICE LETTER	**************************************		
SK-SL002	NC	CCK/X-2000	CCK/X-2000-0001 and on	Ignition Coil 90* Connectors	Inspect and replace connectors as needed			Superseded by SK-SB010



YEAR 20 Date	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations  Entries must be endorsed with Name, Rating and Certificate Number of Technician o Repair Facility. (See back pages for other specific entries.)
-				
	1			
				rior to 02/01/2019