THE AIRCRAFT AIRCRAFT MAINTENANCE MAINTENANCE RECORDKEEPING SYSTEM

AIRFRAME MAINTENANCE RECORDS

			rada No.
DATE	101AL TIME IN SERVICE	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
		TOTAL brought	t forward from previous page
B735 SOL TULSA, (N27682 LEFT LYC RIGHT L' COMPLE 12/30/1 PERFOR COMPLI INSPEC COMPLI INSPEC FOUND PERFOL P	COMING TIC YCOMING LE YCOMING LE TED ANNUAL ETED ANNUAL BY AS A GUIE MED AIRWOR ED WITH AD 8 ISPECTION DU IED WITH AD 2 TION DUE 6/20 TION DUE 346 FOR AND 12 MON RMED 10 HO DRMED 100 H	WAY DDEL PA31-350 SN: D-540-J28D SN: L-1 TIO-540-J28D SN: L-1 THINESS DIRECTIVE S L-2-7-13 R2, FLAP EX L-2-7-13 R2, FLAP L-2-7-13 R	AIRFRAME LOG BOOK ENTRY 13 JUNE 2023 31-7852105 ACFT TT: 11,070.8 ACFT HOBBS: 3369.0 1253-61A ENG TSN: 3611.4 ENG TSMOH: 1615.2 1-2610-68A ENG TSN: 8668.4 ENG TSMOH: 889.4 PIPPER AIRCRAFT PA31-350 NAVAJO ANNUAL/100 HOUR INSPECTION CHECKLIST DATED SEARCH USING AVANTEX DISC 2023-10. TENSION SYSTEM INSPECTION, TRANSMISSION FREE PLAY, PER SB494B, NO FAULT FOUND.

10/13/2023, Hobbs 3385.8, Total Time 11,087.6, Heater Hobbs 750.6

N27682 Airframe Log Entry

. CM AD 2009-13-06 R1 by inspection of nose baggage door latch, locking components and lubrication as outlined in Piper SB# 1194A Part II. The operational check was good. No defects were noted. Could not find required specified flight manual supplement in the AFM. Printed page 11 of MSB 1194A and inserted to AFM. Next inspection is due at 3485.8 Hobbs and life limited parts replacement next due at 3730.8 Hobbs.

William Dorothy A&P 3504028 IA

ame Log Entry system and found ed system with 3.3 ice. Installed New

e good.

SUB-TOTAL this page

TOTAL-Carry forward to next page

4900 Old Phoenix Ave. Fort Smith, AR 72903	Date: 5/10/2	.022		
	W/O#: 125	50 —		
Logbook Entry			G WORK	
egistration: N27682 Make/Model: Piper PA-31-350	S/N: 31-			
emoved Century Flight Systems autopilot computer P/N 1D7 C927-847 s/n 436. Each unit was repaired by Autopilots Cenested for correct performance. All test appear normal.				TINE ST
		_		
This aircraft is approved for return to service in accordant the Federal Aviation Administration with respect to wo		ations		
Signed: A	5/10/2 Date:	2022		
7				
Summit Aviation LLC 2440 SW A /2022, Hobbs 3277.0, Total Time 10978.8	viation St. Bentonville, A		rframe Log Entr	
ressure fitting adapters and valve cores. Re-serviced system vis Reynolds A&P 3731240	with freon. Operational a	and leak checks w	ere good.	()
				. 1
				. 1
SUB-TOTAL this page				

DATE

TOTAL TIME IN SERVICE TACH OR RECORDING METER TIME

DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK

TOTAL brought forward from previous page

RIVERSIDE AVIATION

8735 SOUTH AIRPORT WAY

AIRFRAME LOG BOOK ENTRY

TULSA, OK 74132 1 MAY 2022

ACET IT: 10.062 6 ACET

N27682 NAVAJO MODEL PA31-350 SN: 31-7852105 ACFT TT: 10,962.6 ACFT HOBBS: 3260.8 LEFT LYCOMING TIO-540-J2BD SN: L-11253-61A ENG TSN: 3503.2 ENG TSMOH: 1507.0 RIGHT LYCOMING LTIO-540-J2BD SN: L-2610-68A ENG TSN: 8560.6 ENG TSMOH: 781.2

COMPLETED ANNUAL INSPECTION USING PIPER AIRCRAFT PA31-350 NAVAJO ANNUAL/100 HOUR INSPECTION CHECKLIST DATED 12/30/1994 AS A GUIDE.

PERFORMED AIRWORTHINESS DIRECTIVE SEARCH USING AVANTEX DISC 2022-08.

COMPLIED WITH AD 82-27-13 R2, FLAP EXTENSION SYSTEM INSPECTION, TRANSMISSION FREE PLAY, PER SB494B, NO FAULT FOUND. NEXT INSPECTION DUE 3360.8 ACFT HOBBS.

COMPLIED WITH AD 2003-24-07, RUDDER TORQUE TUBE AND RIB INSPECTION, BY VISUAL INSPECTION, NO CORROSION FOUND. NEXT INSPECTION DUE 05/2023.

COMPLIED WITH AD 2013-10-4C, ENGINE EXHAUST SYSTEM INTEGRITY INSPECTION, BY VISUAL INSPECTION, NO FAULT FOUND. NEXT INSPECTION DUE 3310.8 ACFT HOBBS.

FOUND ALL OTHER AD'S PREVIOUSLY COMPLIED WITH OR NOT APPLICABLE.

PERFORMED 12 MONTH CABIN HEAT AND AIR DUCT INSPECTION, NEXT DUE 05/2023.

PERFORMED 12 MONTH ELT OPERATION CHECK, NEXT DUE 02/2021. NEXT ELT BATTERY REPLACEMENT DUE 09/2025.

PERFORMED 12 MONTH SEAT BELT AND SHOULDER HARNESS INSPECTIONS, NE DEFECTS NOTED. NEXT INSPECTION DUE 05/2023.

PERFORMED 12 MONTH MAIN WING SPAR CAP INSPECTION, NO DEFECTS NOTED. NEXT INSPECTION DUE 05/2023.

PERFORMED 12 MONTH BATTERY CAPACITY CHECK ON BOTH BATTERIES, BOTH PASSED. NEXT TEST DUE 05/2023.

PERFORMED 12 MONTH FIRE EXTINGUISHER INSPECTION, NEXT INSPECTION DUE 05/2023.

PERFORMED 12 MONTH HYDRAULIC FILTER REPLACEMENT BY INSTALLING NEW FILTERS AN6235-1A, NEXT REPLACEMENT DUE 05/2023.

PERFORMED 100 HOUR AND 300 HOUR AIRCRAFT LUBE REQUIREMENTS.

PERFORMED 100 HOUR REPLACEMENT OF AIR PUMP INLET SCREEN FILTERS, NEXT REPLACEMENT DUE AT 3360.8 ACFT HOBBS.

PERFORMED 100 HOUR INSPECTION OF WING SPICE PLATE AND SPAR, NEXT INSPECTION DUE AT 3360.8 ACFT HOBBS.

PERFORMED 100 HOUR INSPECTION OF FUEL SELECTOR CABLES, NEXT INSPECTION DUE AT 3360.8 ACFT HOBBS.

PERFORMED 100 HOUR INSPECTION OF AILERON SPROCKET AND CHAIN, NEXT INSPECTION DUE AT 3360.8 ACFT HOBBS.

PERFORMED 100 HOUR INSPECTION OF FLAP FLEXIBLE SHAFTS, NEXT INSPECTION DUE AT 3360.8 ACFT HOBBS.

PERFORMED 100 HOUR INSPECTION AND FREE PLAY OF FLAP TRANSMISSION, NEXT INSPECTION DUE AT 3360.8 ACFT HOBBS.

PERFORMED 3 YEAR REPLACEMENT OF BOTH ENGINES INDUCTION AIR FILTERS BY INSTALLING NEW FILTER PART NUMBER P10-6590, NEXT REPLACEMENT DUE 05/2025.

PERFORMED 5 YEAR REPLACEMENT OF BOTH ENGINE PNEUMATIC HOSES, NEXT REPLACEMENT DUE 05/2027.

PERFORMED 5 YEAR INSPECTION OF FUSELAGE AND WING FLUID LINES, NEXT INSPECTION DUE 05/2027.

ALL FLIGHT CONTROL RIGGING CHECKS PERFORMED PER MAINTENANCE MANUAL.

ALL LANDING GEAR CHECKS PERFORMED PER MAINTENANCE MANUAL.

REMOVED AND REPLACED RIGHT INNER GEAR DOOR HYDRAULIC ACTUATOR WITH NEWLY OVERHAULED UNIT PART NUMBER WTC2114-1 SERIAL NUMBER WTC3409. SERVICED AND BLED ENTIRE HYDRAULIC SYSTEM.

REMOVED, DISASSEMBLED, CLEANED, INSPECTED, AND REPLACED ALL O-RINGS IN LEFT AND RIGHT BRAKE CALIPERS.

REMOVED AND REPLACED RIGHT MAIN GEAR TIRE WITH NEW GOODYEAR FLIGHT CUSTOM III TIRE PART NUMBER 650C06-3.

REMOVED, DISASSEMBLED, SERVICED, AND REINSTALLED NOSE WHEEL SHIMMY DAMPNER.

REMOVED AND REPLACED BOTH ENGINES DRAIN BACK ALUMINUM TUBES THAT PASS THROUGH THE LOWER COWLINGS.

REMOVED, HAD TESTED AND INSPECTED, AND REINSTALLED ELEVATOR PITCH SERVO.

REMOVED AND REPLACED LEFT ENGINE INDUCTION INLET TUBE AND ALTERNATE AIRDOOR ASSEMBLY WITH NEW COMPLETE UNIT PART NUMBER 54916-02PN2.

REMOVED, DISASSEMBLED, REPLACED PARTS, REASSEMBLED AND REINSTALLED RIGHT ENGINE INDUCTION INLET TUBE AND ALTERNATE AIRDOOR ASSEMBLY.

REPAIRED AND LUBRICATED BOTH ALTERNATE AIRDOOR ACTUATOR CABLES.

I CERTIFY THAT THIS AIRFRAME HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND HAS BEEN DETERMINED TO BE IN AN AIRFORTHY CONDITION.

DAVER. LANDRETH A&P 2651512 IA

SUB-TOTAL this page

TOTAL-Carry forward to next page

2/9/2021, Hobbs 3119.4, Total Time 10,821.2, Heater Hobbs 677.3

N27682 Airframe Log Entry

- Performed Annual/100-hour inspection I/A/W FAR 43 App. D. All work was performed I/A/W Piper PA31-350 Maintenance Manual.
- Checked ADs through ATP revision dated 2/9/2021. See AD compliance report for recurring times.
- C/W AD 82-27-13 R2 by performing free play inspection of flap transmission I.A.W Piper service bulletin No. 494B. No defects noted. Next inspection due at 3219.4 Hobbs.
- C/W AD 2003-24-07 by visual inspection of rudder tube for corrosion per paragraph (e)(2) 12-month inspection I/A/W SB# 1105A, no defects or corrosion noted, next due in Feb. 2022.
- C/W AD 2009-13-06 R1 by inspection of nose baggage door latch, locking components and lubrication as outlined in Piper SB# 1194A table 2. Operational check was good. No defects noted. Next inspection is due at 3219.4 Hobbs and next life limited parts replacement next due at 3730.8 Hobbs.
- C/W AD 2013-10-4C Exhaust system inspection both engines by visual inspection as outlined in AD text. No defects noted. Next inspection due at 3179.4 Hobbs or July 2021.
- C/W AD 2015-19-07 by inspection of fuel injection lines both engines I/A/W Lycoming Engines Mandatory Service Bulletin No. 342G.
 No defects were noted, and all required clamps are in place. Next inspection due at 3219.4 Hobbs.
- Replaced left tire and tube W/New Goodyear FCIII 6.50x10 10Ply Tire P/N 650C06-3, S/N 52882265, and New Michelin Tube P/N 092-344-0. Torqued wheel bolts to 90 Inch LBS and serviced to 66 PSI. Reinstalled to aircraft. Leak checks were good.
- Troubleshooting of IN-OP propeller deice system found right propeller spinner has chafed wiring. Left propeller deice operational checks were good. Repaired chafed wires for right deice boots. Operational checks failed due to broken deice brush. Replaced all 3 deice brushes W/New (3 each) P/N RA1543-1 and cleaned slip ring. Operational checks were good.
- Replaced main aircraft battery W/New Concorde P/N RG24-20, S/N 41103150. Operational checks were good.
- Replaced nose gear torque link center pivot bolt W/New P/N AN4-12A.
- First operational check of flaps failed and smoked flap drive motor. Troubleshooting found right flap drive cable seized and damaged flap drive motor. Replaced flap drive motor W/Serviceable unit provided by owner. Replaced left and right flap drive flex cable assemblies W/New (2 each) P/N 486-597. Riggs flap system I/A/W Piper PA31-350 Maintenance manual page 1J11, 5-68 and SB739. Operational checks were good.
- · Replaced instrument air filters W/New (2 each) P/Ns AA2J4-6.
- Removed, inspected, and replaced right and left hydraulic system filters W/New (2 each) P/N AN6235-1A. Installed each W/New P/N MS28775-216 O-ring. Leak checks were good. Inspection of old filters noted no contaminates.
- Removed right inboard gear door actuator, replaced shaft seal W/New P/N 762-550 and reassembled W/New O-ring P/N MS28775-018. Serviced hydraulic power pack W/MIL-H-5606 fluid and performed several successful gear cycles. Leak and operational checks were good.
- Replaced right and left wing landing light lenes W/New (1 each) P/Ns 66000-7 Left and 66000-8 Right. Fitted, drilled, and sealed each W/White silicone.
- · Serviced brake reservoir W/MIL-H-5606 fluid.
- · I certify that this Aircraft was inspected I/A/W a 100 Hour/Annual Inspection and was determined to be in Airworthy Condition.

William Dorothy A&P 3504028 M

AIRFRAME N#:N27682 S/N #: 31-7852105 HOBBS: 3142.83

DATE: 3/02/21

ALL WORK PERFORMED PER PIPER PA 31-350 M/M. JACKED AIRCRAFT. SWUNG GEAR. GEAR INOP. TROUBLESHOT SYSTEM. FOUND RT MAIN INNER GEAR DOOR ACTUATOR LEAKING. REMOVED OLD ACTUATOR PT# WTC2114-1 SN# 2225. REPLACED WITH SERVICABLE ACTUATOR PT#WTC2114 SN#7387. SWUNG GEAR. OPS CHECKED GOOD. NO OTHER DISCREPANCIES FOUND AT THIS TIME. REMOVED FROM JACKS. RETURNED AIRCRAFT TO SERVICE PER WORK PERFORMED THIS DATE.----END-----

HENRY JAY NIGHTINGALE A&P 3732819

RIVERSIDE AVIATION 8735 SOUTH AIRPORT WAY

AIRFRAME LOG BOOK ENTRY 4 APRIL 2022

TULSA OK, 74132 4 APRIL 2022

N27682 NAVAJO MODEL PA31-350 SN: 31-7852105 ACFT TT: 10,962.6 ACFT HOBBS: 3260.8

LEFT LYCOMING TIO-540-J2BD SN: L-11253-61A ENG TSN: 3503.2 ENG TSMOH: 1507.0

RIGHT LYCOMING LTIO-540-J2BD SN: L-2610-68A ENG TSN: 8560.6 ENG TSMOH: 781.2

COMPLIED WITH 24 MONTH REQUIREMENT OF 14 CFR PART 91.411 ALTIMETER AND STATIC SYSTEM TEST AND PART 91.413 TRANSPONDER TEST. PERFORMED BY AIRELECTRIC INC. CRS# 9R1R958C REFERENCE WORK ORDER NUMBER 20220404. SEE AIRELECTRIC CERTIFICATION FORMS FOR DETAILS.

REMOVED AND REPLACED TRANSPONDER WITH SERVICIBLE UNIT GTX327 SERIAL NUMBER 83721970.

REMOVED AND REPLACED BROKEN STATIC RUBBER CONNECTION HOSE WITH NEW.

FOUND LOOSE AND TIGHTENED FITTING NUT FOR STATIC LINE BEHIND AFT BULKHEAD WALL.

DAVID R. LANDRETH 002651512 IA

DATE

RIVERSIDE AV 8735 SOUTH TULSA, OK 74 N27682 NAV LEFT LYCOMI

COMPLETED A 12/30/1994 A PERFORMED A

COMPLIED WI NEXT INSPECT COMPLIED WI INSPECTION D COMPLIED WI

PERFORMED 1

PERFORMED 1
PERFORMED 1
PERFORMED 1
PERFORMED 1
PERFORMED 1

PERFORMED 1 05/2023. PERFORMED 1 PERFORMED 1 PERFORMED 1 PERFORMED 1

PERFORMED 19 PERFORMED 19 PERFORMED 3 PERFORMED 3 NEXT REPLACES PERFORMED 5

PERFORMED 5 ALL FLIGHT COI ALL LANDING G REMOVED AND WTC2114-1 SER REMOVED, DISA

REMOVED AND REMOVED, DISA REMOVED AND REMOVED, HAD REMOVED AND PART NUMBER

REMOVED, DISA ALTERNATE AIR REPAIRED AND I CERTIFY THAT TO 85 IN AN AIR

DAVER LAND

DAVER R. LANDE

6/4/2020, Hobbs 2980.7, Total Time 10682.5

N27682 Airframe Log Entry

ABS Avionics, Inc. CRS#485R359D 4900 Old Phoenix Ave, Fort Smith, AR 72903 Logbook Entry Registration: N27682 Make/Model: Piper PA 31-350 S/N: 7852105 Compilled with Aspen Avionics Tech Note 2013-02 Rev B dated 2/04/2019 to correct slight pitch pumping when allitude hold mode. This aircraft is approved for return to service in accordance with current regulations of the Federal Aviation Administration with respect to work completed. Signed: Date: 6/30/2020 Summit Aviation LLC 2440 SW Aviation St. Bentonville, AR 72712 Signed: National Carlos Sig	, [David Westphal A&P 430554968			
A900 Old Phoenix Ave. Fort Smith, AR 72903 W/O#: 0800 Logbook Entry Registration: N27682 Make/Model: Piper PA 31-350 S/N: 7852105 Compilied with Aspen Avionics Tech Note 2013-02 Rev B dated 2/04/2019 to correct slight pitch pumping when altitude hold mode. This aircraft is approved for return to service in accordance with current regulations of the Federal Aviation Administration with respect to work completed. Signed: A John Signed	1				
Registration: N27682 Make/Model: Piper PA 31-350 S/N: 7852105 Compilied with Aspen Avionics Tech Note 2013-02 Rev B dated 2/04/2019 to correct slight pitch pumping when altitude hold mode. This aircraft is approved for return to service in accordance with current regulations of the Federal Aviation Administration with respect to work completed. Signed: Figure 10,737.7, Heater Hobbs 658.6 Summit Aviation LLC 2440 SW Aviation St. Bentonville, AR 72712 S/2020, Hobbs 3035.9, Total Time 10,737.7, Heater Hobbs 658.6 N27682 Airframe Log Entry (NA) Date: 10,737.7 Heater Hobbs 658.6 N27682 Airframe Log Entry (NA) Date: 10,737.7 Heater Hobbs 658.6 N27682 Airframe Log Entry (NA) Date: 10,737.7 Heater Hobbs 658.6 N27682 Airframe Log Entry (NA) Date: 10,737.7 Heater Hobbs 658.6 N27682 Airframe Log Entry (NA) Date: 10,737.7 Heater Hobbs 658.6 N27682 Airframe Log Entry (NA) Date: 10,737.7 Heater Hobbs 658.6 N27682 Airframe Log Entry (NA) Date: 10,737.7 Heater Hobbs 658.6 N27682 Airframe Log Entry (NA) Date: 10,737.7 Heater Hobbs 658.6 N27682 Airframe Log Entry (NA) Date: 10,737.7 Heater Hobbs 658.6 N27682 Airframe Log Entry (NA) Date: 10,737.7 Heater Hobbs 658.6 N27682 Airframe Log Entry (NA) Date: 10,737.7 Heater Hobbs 658.6 N27682 Airframe Log Entry (NA) Date: 10,737.7 Heater Hobbs 658.6 N27682 Airframe Log Entry (NA) Date: 10,737.7 Heater Hobbs 658.6 N27682 Airframe Log Entry (NA) Date: 10,737.7 Heater Hobbs 658.6 N27682 Airframe Log Entry (NA) Date: 10,737.7 Heater Hobbs 658.6 N27682 Airframe Log Entry (NA) Date: 10,737.7 Heater Hobbs 658.6 N27682 Airframe Log Entry (NA) Date: 10,737.7 Heater Hobbs 658.6 N27682 Airframe Log Entry (NA) Date: 10,737.7 Heater Hobbs 658.6 N27682 Airframe Log Entry (NA) Date: 10,737.7 Heater Hobbs 658.6 N27682 Airframe Log Entry (NA) Date: 10,737.7 Heater Hobbs 658.6 N27682 Airframe Log Entry (NA) Date: 10,737.7 Heater Hobbs 658.6 N27682 Airframe Log Entry (NA) Date: 10,737.7 Heater Hobbs 658.6 N27682 Airframe Log Entry (NA) Date: 10,737.7 Heater Hobbs 658.6 N27682		ABS Avionics, Inc. CRS#485R359D	Date:	6/30/2020	
Registration: N27682 Make/Model: Piper PA 31-350 S/N: 7852105 Compilied with Aspen Avionics Tech Note 2013-02 Rev B dated 2/04/2019 to correct slight pitch pumping when attitude hold mode. This aircraft is approved for return to service in accordance with current regulations of the Federal Aviation Administration with respect to work completed. Signed: Asigned: Asigned: Signed: Bate: 6/30/2020 Summit Aviation LLC 2440 SW Aviation St. Bentonville, AR 72712 S/2020, Hobbs 3035.9, Total Time 10,737.7, Heater Hobbs 658.6 N27682 Airframe Log Entry AVAD 2009-13-06 R1 by inspection of nose baggage door latch, locking components and lubrication as outlined in extilific limited parts replacement next due at 3730.8 Hobbs. AVAD 2013-10-4C Exhaust system inspection by visual inspection as outlined in AD text. No defects noted. Next inspection as outlined in AD text. No defects noted. Next inspection at 305.9 Hobbs or May 2020. AVAD 2015-19-07 by inspection I/A/W Lycoming Engines Mandatory Service Bulletin No. 342G. No defects were ofted, and all required clamps are in place. Next inspection due at 3135.9 Hobbs. Toubleshooting of wing tip lights being In-Op found circuit breaker switch for these lights has failed. New circuit breaker witch is on order.		기계 그는	W/O#:		
Compilied with Aspen Avionics Tech Note 2013-02 Rev B dated 2/04/2019 to correct slight pitch pumping when altitude hold mode. This aircraft is approved for return to service in accordance with current regulations of the Federal Aviation Administration with respect to work completed. Signed: Assigned: Assigned: Bate: 6/30/2020 Summit Aviation LLC 2440 SW Aviation St. Bentonville, AR 72712 Si2020, Hobbs 3035.9, Total Time 10,737.7, Heater Hobbs 658.6 N27682 Airframe Log Entry (In Inc.) Signed: Assigned as a service of the		Logbook Entry			
This aircraft is approved for return to service in accordance with current regulations of the Federal Aviation Administration with respect to work completed. Signed: 6/30/2020 Summit Aviation LLC 2440 SW Aviation St. Bentonville, AR 72712 Sizo20, Hobbs 3035.9, Total Time 10,737.7, Heater Hobbs 658.6 N27682 Airframe Log Entry WAD 2009-13-06 R1 by inspection of nose baggage door latch, locking components and lubrication as outlined in injer SB# 1194A table 2. Operational check was good. No defects noted. Next inspection is due at 3135.9 Hobbs and ext life limited parts replacement next due at 3730.8 Hobbs. WAD 2013-10-4C Exhaust system inspection by visual inspection as outlined in AD text. No defects noted. Next isspection due at 3035.9 Hobbs or May 2020. WAD 2015-19-07 by inspection I/AW Lycoming Engines Mandatory Service Bulletin No. 342G. No defects were oted, and all required clamps are in place. Next inspection due at 3135.9 Hobbs. Total Clamps are in place. Next inspection due at 3135.9 Hobbs. Total Clamps are in place. Next inspection due at 3135.9 Hobbs. Total Clamps are in place. Next inspection due at 3135.9 Hobbs. Total Clamps are in place. Next inspection due at 3135.9 Hobbs. Total Clamps are in place. Next inspection due at 3135.9 Hobbs. Total Clamps are in place. Next inspection due at 3135.9 Hobbs. Total Clamps are in place. Next inspection for these lights has failed. New circuit breaker witch is on order.		Registration: N27682 Make/Model: Piper PA 31-350		S/N: 7852105	
Signed:			d 2/04/2019 to	correct slight	
Signed:					
Signed:					
Signed:				3	
Signed:				jil .	
Signed:					
Signed:					
Signed:					
Summit Aviation LLC 2440 SW Aviation St. Bentonville, AR 72712 5/2020, Hobbs 3035.9, Total Time 10,737.7, Heater Hobbs 658.6 N27682 Airframe Log Entry WAD 2009-13-06 R1 by inspection of nose baggage door latch, locking components and lubrication as outlined in liper SB# 1194A table 2. Operational check was good. No defects noted. Next inspection is due at 3135.9 Hobbs and ext life limited parts replacement next due at 3730.8 Hobbs. WAD 2013-10-4C Exhaust system inspection by visual inspection as outlined in AD text. No defects noted. Next inspection due at 3095.9 Hobbs or May 2020. WAD 2015-19-07 by inspection I/A/W Lycoming Engines Mandatory Service Bulletin No. 342G. No defects were ofted, and all required clamps are in place. Next inspection due at 3135.9 Hobbs. roubleshooting of wing tip lights being In-Op found circuit breaker switch for these lights has failed. New circuit breaker witch is on order.		This aircraft is approved for return to service in accordance of the Federal Aviation Administration with respect to work	ce with curren	nt regulations	
5/2020, Hobbs 3035.9, Total Time 10,737.7, Heater Hobbs 658.6 N27682 Airframe Log Entry NW AD 2009-13-06 R1 by inspection of nose baggage door latch, locking components and lubrication as outlined in liper SB# 1194A table 2. Operational check was good. No defects noted. Next inspection is due at 3135.9 Hobbs and ext life limited parts replacement next due at 3730.8 Hobbs. NW AD 2013-10-4C Exhaust system inspection by visual inspection as outlined in AD text. No defects noted. Next inspection due at 3095.9 Hobbs or May 2020. NW AD 2015-19-07 by inspection I/A/W Lycoming Engines Mandatory Service Bulletin No. 342G. No defects were ofted, and all required clamps are in place. Next inspection due at 3135.9 Hobbs. Toubleshooting of wing tip lights being In-Op found circuit breaker switch for these lights has failed. New circuit breaker witch is on order.		Signed: Alange	Date:	6/30/2020	
5/2020, Hobbs 3035.9, Total Time 10,737.7, Heater Hobbs 658.6 N27682 Airframe Log Entry NW AD 2009-13-06 R1 by inspection of nose baggage door latch, locking components and lubrication as outlined in liper SB# 1194A table 2. Operational check was good. No defects noted. Next inspection is due at 3135.9 Hobbs and ext life limited parts replacement next due at 3730.8 Hobbs. NW AD 2013-10-4C Exhaust system inspection by visual inspection as outlined in AD text. No defects noted. Next inspection due at 3095.9 Hobbs or May 2020. NW AD 2015-19-07 by inspection I/A/W Lycoming Engines Mandatory Service Bulletin No. 342G. No defects were ofted, and all required clamps are in place. Next inspection due at 3135.9 Hobbs. Toubleshooting of wing tip lights being In-Op found circuit breaker switch for these lights has failed. New circuit breaker witch is on order.					
5/2020, Hobbs 3035.9, Total Time 10,737.7, Heater Hobbs 658.6 N27682 Airframe Log Entry NW AD 2009-13-06 R1 by inspection of nose baggage door latch, locking components and lubrication as outlined in liper SB# 1194A table 2. Operational check was good. No defects noted. Next inspection is due at 3135.9 Hobbs and ext life limited parts replacement next due at 3730.8 Hobbs. NW AD 2013-10-4C Exhaust system inspection by visual inspection as outlined in AD text. No defects noted. Next inspection due at 3095.9 Hobbs or May 2020. NW AD 2015-19-07 by inspection I/A/W Lycoming Engines Mandatory Service Bulletin No. 342G. No defects were ofted, and all required clamps are in place. Next inspection due at 3135.9 Hobbs. Toubleshooting of wing tip lights being In-Op found circuit breaker switch for these lights has failed. New circuit breaker witch is on order.		The second secon			
C/W AD 2009-13-06 R1 by inspection of nose baggage door latch, locking components and lubrication as outlined in liper SB# 1194A table 2. Operational check was good. No defects noted. Next inspection is due at 3135.9 Hobbs and ext life limited parts replacement next due at 3730.8 Hobbs. C/W AD 2013-10-4C Exhaust system inspection by visual inspection as outlined in AD text. No defects noted. Next inspection due at 3095.9 Hobbs or May 2020. C/W AD 2015-19-07 by inspection I/A/W Lycoming Engines Mandatory Service Bulletin No. 342G. No defects were oted, and all required clamps are in place. Next inspection due at 3135.9 Hobbs. Toubleshooting of wing tip lights being In-Op found circuit breaker switch for these lights has failed. New circuit breaker witch is on order.		Summit Aviation LLC 2440 SW Aviation St. Bent	tonville, AR 727	12	
C/W AD 2009-13-06 R1 by inspection of nose baggage door latch, locking components and lubrication as outlined in liper SB# 1194A table 2. Operational check was good. No defects noted. Next inspection is due at 3135.9 Hobbs and ext life limited parts replacement next due at 3730.8 Hobbs. C/W AD 2013-10-4C Exhaust system inspection by visual inspection as outlined in AD text. No defects noted. Next inspection due at 3095.9 Hobbs or May 2020. C/W AD 2015-19-07 by inspection I/A/W Lycoming Engines Mandatory Service Bulletin No. 342G. No defects were oted, and all required clamps are in place. Next inspection due at 3135.9 Hobbs. Toubleshooting of wing tip lights being In-Op found circuit breaker switch for these lights has failed. New circuit breaker witch is on order.	25/2020	Hobbs 2025 0 Total Time 10 737 7 Heater Hobbs 658 6		N27682 Airframe	Log Entry
	Piper SBi next life li C/W AD inspection C/W AD noted, an Troublesh switch is c	# 1194A table 2. Operational check was good. No defects noted mited parts replacement next due at 3730.8 Hobbs. 2013-10-4C Exhaust system inspection by visual inspection as a due at 3095.9 Hobbs or May 2020. 2015-19-07 by inspection I/A/W Lycoming Engines Mandatory diall required clamps are in place. Next inspection due at 3135.9 pooting of wing tip lights being In-Op found circuit breaker switch on order.	d. Next inspects s outlined in Service Bull Hobbs. for these ligh	ction is due at 313 AD text. No defection No. 342G. Notes has failed. New	o defects were
			The second second		

9/10/2020, Hobbs 3051.2, Total Time 10,753.0

N27682 Airframe Log Entry

- During test run, found alternator circuit breaker tripped. Reset circuit breaker, alternator returned to normal function.
- Removed left engine cowling, inspection found main alternator power feed wire loose at connection to noise suppression capacitor in engine compartment. Cleaned connector on capacitor and replaced ring terminal on wire W/New P/N 321598 and installed with new silicone boot P/N MS25171-25.
- Test ran aircraft. Operational and leak checks were good.
- Inspection of recognition lamps found circuit breaker switch to lights had failed. Installed New circuit breaker switch P/N W31-X2M1G-15. Operational check was good.
- Removed standard wing tip recognition lamps P/N GE4594 28V 100W and installed New (2 Each) Whelen Parmetheus Pro PAR 36 M/N LSM-SCD-042-1 LED Light bulbs. Modified mounting brackets as needed to accommodate new lamps. Adjusted alignment. Operational check was good.

David Westphal A&P 430554968

12/12/2019, Hobbs 2954.8, Total Time 10,656.6, Heater Hobbs 649.1

N27682 Airframe Log Entry

- Performed Annual/100-hour inspection I/A/W FAR 43 App. D. All work was performed I/A/W Piper PA31-350 Maintenance Manual.
- Checked ADs through ATP revision dated 12/11/2019. See AD compliance report for recurring times.
- C/W AD 82-27-13 R2 by performing free play inspection of flap transmission I.A.W Piper service bulletin No. 494B. No defects noted.
 Next inspection due at 3054.8 Hobbs.
- C/W AD 2003-24-07 by visual inspection of rudder tube for corrosion per paragraph (e)(2) 12-month inspection I/A/W SB# 1105A, no defects or corrosion noted, next due in Dec. 2019.
- C/W AD 2009-13-06 R1 by inspection of nose baggage door latch, locking components and lubrication as outlined in Piper SB# 1194A table 2. Operational check was good. No defects noted. Next inspection is due at 3054.8 Hobbs and next life limited parts replacement next due at 3730.8 Hobbs.
- C/W AD 2013-10-4C Exhaust system inspection by visual inspection as outlined in AD text. No defects noted. Next inspection due at 3014.8 Hobbs or May 2020.
- C/W AD 2015-19-07 by inspection I/A/W Lycoming Engines Mandatory Service Bulletin No. 342G. No defects were noted, and all
 required clamps are in place. Next inspection due at 3054.8 Hobbs.
- Replaced ELT W/New due to failure of installed Ameri-King AK451. Installed New ELT, KANNAD P/N S1851501-02, S/N LX1101046686 and KANNAD (Ameri-Kit Retrofit Kit) P/N 1202573, S/N LX1101068503, Manufacture Pack Kit P/N 1001627. Installed I/A/W KANNAD Installation Manual using New Antenna P/N AV-200. Hex ID Code is 2DC86B2A02FFBFF. Next battery replacement is due Sept. 2025.
- · Replaced Davtron clock battery W/New P/N 811-BATT, Operational check was good.
- Replaced instrument air and regulator filters W/New (2 each) P/Ns AA2J4-6 and ARB3-5-1.
- Removed, inspected and replaced right and left hydraulic system filters W/New (2 each) P/N AN6235-1A. Installed each W/New P/N MS28775-216 O-ring. Leak checks were good. Inspection of old filters noted no contaminates.
- Serviced hydraulic power pack W/5606 fluid, performed several successful gear cycles, leak and operational checks were good.
- Replaced right and left brake back plate rivets W/New due to loosely fitting brake linings to back plates. Installed 32 each P/N RA177-01600 to all right and left brake lining back plates.
- Removed left main gear lower strut assembly, disassembled cleaned and inspected. Reassembled W/New O-rings (1 each) P/Ns MS28775-236, MS28775-335 and valve core P/N 302DN. Reinstalled, serviced W/5606 fluid and nitrogen to proper 3.5 Inch extension. Leak check was good.
- · Replaced left and right alternate air door and springs W/New P/N 587-234.
- · Replaced broken roll pin at co-pilot seat back adjustment mechanism W/New and lubricated pivot points and rollers as needed.
- · Replaced fire extinguisher W/New P/N A344T.
- Replaced 18th Tachometer drive cable assembly W/New P/N 486-637, operational check was good.
- Replaced missing VGs as needed, one or right wing and 2 on left wing. VGs were supplied by owner. Installed each I/A/W manufacturer's instructions.
- I certify that this Aircraft was inspected I/A/W a 100 Hour/Annual Inspection and was determined to be in Airworthy Condition.

William Dorothy A&P 3504028 IA

		s, Inc. CRS#485R359D Ave. Fort Smith, AR 72903	Date: _ W/O#:	_	9/2020 0621
1000	old i illociliz	Logbook Entry	VV/OII.		0021
Registration:	N27682	Make/Model: Piper PA-31-350		S/N:	7852105
tested. Fun	ctions norma	I. Reseated connectors on pitch and t	rim servo.		
This pirers	ft is approv	ad for return to conside in accords	nce with co	rront	regulations
		ed for return to service in accordant			egulation



SB# 1273A. No nust be installed to defects noted to defects noted the limited parts inspection due at a number AA I01AT-

Log Entry

ance Manual.

. Kit P/N 88578-

SB# 1273A. No must be installed

lo defects noted.

V SB# 1105A, no

ned in Piper SB# life limited parts

inspection due at

ere noted, and all

ry replacement is

fuel flow option. n 8130-3 tracking isting Shadin Fuel formation to GPS.

ined.

Condition.

N27682 Model: PA31-350 Serial: 3 Date: 2/13/2019 Hobbs: 2896.5

Serial: 31-7852105

AVXINC & & MAINTENANCS

AD 2016-05-01 Vertical fin FWD spar to bulkhead attachment integrity. Complied with para. (h) modification by installing customer supplied Piper Kit PN: 764-028 (QTY 1) per Piper SB 1273B. This is a terminating action for this AD; no further action is required.

AD 2017-10-20 Fuselage station (FS) 332.00 bulkhead integrity. Complied with para. (g) (4) by installing customer supplied Piper kit PN: 88578-001 (QTY 1) per Piper SB 1289A. This is a terminating action for this AD; no further action is required.
 Repaired vertical stabilizer and rudder caps.

All maintenance completed in accordance with applicable sections of the manufacturer's maintenance manuals. All operational, rigging, and functional tests completed satisfactorily. Levify that The Maintenance identified above has been inspected and the items are approved for return to service. Pertinent details of the repairs are on file at this Agency under Work Order # 1147-01-2019.

Signed My St

Kyle Gilliam

For MIKE JONES AVIONICS AND MAINTENANCE, MURFREESBORO, TN 37129 CRS: 9JNR717B

TOTAL-Carry forward to next page

Summit Aviation LLC 2440 SW Aviation St. Bentonville, AR 72712

10/2/2018, Hobbs 2939.2, Total Time 10,641.0

N27682 Airframe Log Entry

 Removed standard bat style miniature toggle avionics master switch and replaced W/New locking style miniature toggle switch P 7401K2ZQE, Operational check was good.

Replaced right vacuum pump W/Overhauled unit P/N 442CW-6. Installed W/New provided gasket. Overhaul was performed by Ae
Accessories LLC on W/O I05C5-000, see FAA 8130-3 number AA 105C5-000 dated 29/Jan 2019. Operational check was good.

Removed center pedestal plastic cover jest left of elevator trim indicator, epoxy glued broken comer and reinstalled.

Reinstalled previously remove JPI EDM 760 P/N 760000-6C-O-A-F, S/N 06036 after repairs were performed by J. P. Instruments of W/O# RMA 57852, see FAA 8130-3 number R130919-7 dated 13/Sept/2019. Ramp testing had normal operation.

David Westphal A&P 430554968

ABS Avionics, Inc. CRS#485R359D 4900 Old Phoenix Ave. Fort Smith, AR 72903	Date: 12/2/2019 W/O#: 0635	_
Logbook Entry	VV/O#. 0033	-
Registration: N27682 Make/Model: Piper Pa-31-350	S/N: 782105	
tolerance. Tested the static pressure system, each altimeter in pressure altitude reporting system and found each to comply as required by FAR 91.411. The ATC transponder has been to FAR part 43 appendix (F) as required by FAR 91.413.	with FAR part 43 appendix (E)	
This aircraft is approved for return to service in accordar of the Federal Aviation Administration with respect to wo		

7/18/2018, Hobbs 2855.3, Total Time 10,557.1

N27682 Airframe Log Entry

- CW AD 2016-05-01 by visual inspection of vertical fin forward spar bulkhead at (FS) 317.75 for cracks I/AW Piper SB# 1273A, No cracks noted at this time. Configuration 2 is installed. Next inspection is due at 2955.3 Hobbs and kit P/N 764-028 must be installed before 3130.8 Hobbs.
- C/W AD 82-27-13 R2 by performing free play inspection of flap transmission I.A.W Piper service bulletin No. 494B. No defects noted. Next inspection due at 2955.3 Hobbs.
- C/W AD 2009-13-06 R1 by inspection of nose baggage door latch, locking components and lubrication as outlined in Piper SB# 1194A table 2. Operational check was good. No defects noted. Next inspection is due at 2955.3 Hobbs and next life limited parts replacement next due at 3730.8 Hobbs.
- C/W AD 2013-10-4C Exhaust system inspection by visual inspection as outlined in AD text. No defects noted. Next inspection due at 2915.3 Hobbs or Dec. 2018.
- C/W AD 2015-19-07 by inspection I/A/W Lycoming Engines Mandatory Service Bulletin No. 342G. No defects noted, and all required clamps are in place and no line defects noted. Next inspection due at 2955.3 Hobbs.
- CW AD 84-26-02 by replacing right and left engine air inlet paper filters W/New (2 each) P/N P10-6590. Next replacement is due at 3219.2 Hobbs.
- Replaced vacuum pump W/Overhauled unit P/N 441CC-7, S/N 01AT04. Installed W/New provided gasket and new inlet hose from firewall to left vacuum pump. Overhaul was performed by Aero Accessories Inc., see FAA Form 8130-3 tracking number AA ID1AT-0000 dated 27MAR2018. Operational check was good.

Manuel Burgos A&P 3231885

Summit Aviation LLC 2440 SW Aviation St. Bentonville, AR 72712

11/21/2018, Hobbs 2877.6, Total Time 10,579.4, Heater Hobbs 625.2

N27682 Airframe Log Entry

- Performed Annual/100-hour inspection I/AW FAR 43 App. D. All work was performed I/AW Piper PA31-350 Maintenance Manual.
- Checked ADs through ATP revision dated 11/20/2018. See AD compliance report for recurring times.
- AD 2017-10-20 is not C/W at this time and is due to be complied with no later than 3219.2 Hobbs or 10,921.0 AFTT, Kit P/N 88578. 001 is in owner's possession.
- CM AD 2016-05-01 by visual inspection of vertical fin forward spar bulkhead at (FS) 317.75 for cracks I/AW Piper SB# 1273A. No cracks noted at this time. Configuration 2 is installed. Next inspection is due at 2977.6 Hobbs and kit P/N 764-028 must be installed before 3130.8 Hobbs.
- C/W AD 82-27-13 R2 by performing free play inspection of flap transmission I.A.W Piper service bulletin No. 494B. No defects noted. Next inspection due at 2977.6 Hobbs.
- C/W AD 2003-24-07 by visual inspection of rudder tube for corrosion per paragraph (e)(2) 12-month inspection I/A/W SB# 1105A, no defects or corrosion noted, next due in Nov. 2019.
- . C/W AD 2009-13-06 R1 by inspection of nose baggage door latch, locking components and lubrication as outlined in Piper SB# 1194A table 2. Operational check was good. No defects noted. Next inspection is due at 2977.6 Hobbs and next life limited parts replacement next due at 3730.8 Hobbs.
- C/W AD 2013-10-4C Exhaust system inspection by visual inspection as outlined in AD text. No defects noted. Next inspection due at 2937.6 Hobbs or Apr. 2019.
- C/W AD 2015-19-07 by inspection I/A/W Lycoming Engines Mandatory Service Bulletin No. 342G. No defects were noted, and all required clamps are in place. Next inspection due at 2977.6 Hobbs.
- · Removed ELT and inspected I/AW FAR 91.207 (d). Reinstalled and operational check was good. Next ELT battery replacement is due Dec. 2025
- Removed JPI EDM 760 P/N 76000-6C-O-A, S/N 06036 Per owner's request for option up-grade to include fuel flow option. Reinstalled same EDM 760 after up-grades performed by J.P. Instruments on W/O #RMA 55341, see FAA Form 8130-3 tracking number R131118-11 dated 13/NOV/2018. P/N is now 760000-6C-O-A-F. Connected supplied wiring harness to existing Shadin Fuel Flow indicator to parallel existing Fuel Flow data, connected to Garmin GNS530W for GPS data from fuel flow information to GPS. Ramp testing had normal operation.
- · Replaced left engine shock mounts W/New (8 each) P/N J7763-1. Torqued original bolts to 40 FT LBS and cotter pined.
- Replaced left and right instrument air filters W/New (2 each) P/N AA2J4-6.
- Replaced SAM 302 stand-by unit battery W/New P/N 90177177 dated 7/18.
- · Replaced left and right brake linings W/New (16 each) P/N 066-06600.
- · Serviced hydraulic power pack W/MIL-5606-H fluid.
- Replaced right fuel strainer cup, lower seal W/New P/N 600-0115-5-16. Leak check was good.
- Replaced left wing inboard fuel drain valve W/New P/N CCA-1550. Leak check was good.
- · Serviced nose strut W/Nitrogen to proper pressure.
- I ceptify that this Aircraft was inspected I/A/W a 100 Hour/Annual Inspection and was determined to be in Airworthy Condition.

William Dorothy A&P 3504028 IA

N27682 Date: 2/13/2

1. AD 2016 customer required.

AD 2017 Piper kit T Repaired

All maintena rigging, and I are approved

Signed For MIKE/IC

10/2/2018, Ho

- · Removed star 7401K2ZQE,
- · Replaced righ Accessories L
- Removed cent
 - · Reinstalled pre W/O# RMA 57

DOLLA David Westphal

RS W1NR1050	000	FEET BY	3	IESTED TO 2	25,000	APPENDIX E. THE A _FEET BY	ILTIMETER WAS
6150 070		DATE 11-C	2-17	CRS WIN/10	186		
IGNED /	7	DATE	07 1 1	SIGNED		DATE 11-C	120-11
	0						
CALE CORRECT	TIONS	ALT SERIAL #	15-1618	SCALE CORRE	CTIONS	ALT SERIAL #	UDEEEN
ALTIMETER		ALTIMETER (10302	ALTIMETER	CHONS		434 PA-3
READS	UP	READS	UP	READS	UP	READS	UP
-1000	-10	12000	1-10_	-1000	-10	12000	-15
0	1-10	14000	1-10	0	-5	14000	- 35
1000	- 5	16000	1-10	500	-30	16000	-55
1500	-5	18000	0	1000	15	18000	-20
2000	0	22000	0	1500	+5	20000	1-10
3000	- 5	25000	-20.	3000	10	25000	1-30
4000	0	30000		4000	F15	30000	1
6000	0	35000		6000	0	35000	1
8000	10	40000_		8000	-5	40000	
10000	0	45000	/	10000	-20	45000	
		50000	/		J.	\$0000	
WINGS AVION	IICS, INC.	CRS WINRIOSO	7	WINGS AVION	ICS, INC.	CRS W1NR1050	17
W.O. 672		SNED B.	ye,	W. 0 168	DAT	ED 2.11 21	
H CA T COL	311	SHED TAKE	7	11 737400	51010	()	
oubleshootin itches and s eck found fu	ng of in-oper	Total Time 10 alional AMP met pressure clean ling was normal	0 ₁ 481.7	o SW Aviation St. E ntinuity of left and r bench checked go	ohi alternaio	N27682 A	irframe Log E ector switches. Ited harness. Op
oubleshootin itches and s eck found fu	ng of in-oper stub harness inctional test	Total Time 10 alional AMP met pressure clean ling was normal	0,481.7	of invite of left and	ohi alternaio	N27682 A	octor suitches
oubleshootin itches and s eck found fu	ng of in-oper stub harness inctional test	Total Time 10 ational AMP met s, pressure clean ling was normal	0,481.7 er found poor co- ed switches and	of invite of left and	ight alternato od. Reinstalle	N27682 Air	octor suitches
publeshootir itches and s eck found fu d Weslphal	ng of in-oper stub harness inclignal tesi A&P 430554	Total Time 10 ational AMP met pressure clean ting was normal 1968 Summit Av	o_481.7 er found poor coned switches and lation LLC 2440	ntinuity of left and r bench checked go	ight alternato od. Reinstalld entonville, AR	N27682 Airframe L	ector switches. In the sector switches. Operated harness. Operated harness. Operated harness.
bubleshooting tiches and seek found fur westprial westprial westprial Replaced FAA 8130. Serviced a	ng of in-oper stub harness inctional test A&P 430554 Hobbs 281	Total Time 10 alional AMP met be, pressure clean ling was normal, 1968 Summit Av 16.7, Total Tim or W/Overhauled orm dated 30/App or system W/18 O	o ₃ 481.7 er found poor coned switches and lation LLC 2440 e 10,518.5 unit P/N ALU-85 //2014, Operation	ntinuity of left and r bench checked go	ight alternato od. Reinstalle entonville, AR N27 See Aerotecl at this time.	N27682 Air r AMP meter select and reconnected and reconnected and reconnected are reconnected as a reconnected as a reconnected are reconnected as a reconnect	ector switches. In the sector switches. Operated harness. Operated harness. Operated harness.
bubleshooting tiches and seek found fur westprial westprial westprial Replaced FAA 8130. Serviced a	ng of in-oper stub harness inctional test A&P 430554 Hobbs 281 left alternate 3 tracking for	Total Time 10 alional AMP met be, pressure clean ling was normal, 1968 Summit Av 16.7, Total Tim or W/Overhauled orm dated 30/App or system W/18 O	o ₃ 481.7 er found poor coned switches and lation LLC 2440 e 10,518.5 unit P/N ALU-85 //2014, Operation	ntinuity of left and r bench checked go o SW Aviation St. B 521, S/N K060961. al check was good	ight alternato od. Reinstalle entonville, AR N27 See Aerotecl at this time.	N27682 Air r AMP meter select and reconnected and reconnected and reconnected are reconnected as a reconnected as a reconnected are reconnected as a reconnect	ector switches. In the sector switches. Operated harness. Operated harness. Operated harness.
bubleshooting tiches and seek found fur westprial westprial westprial Replaced FAA 8130. Serviced a	ng of in-oper stub harness inctional test A&P 430554 Hobbs 281 left alternate 3 tracking for	Total Time 10 alional AMP met be, pressure clean ling was normal, 1968 Summit Av 16.7, Total Tim or W/Overhauled orm dated 30/App or system W/18 O	o ₃ 481.7 er found poor coned switches and lation LLC 2440 e 10,518.5 unit P/N ALU-85 //2014, Operation	ntinuity of left and r bench checked go o SW Aviation St. B 521, S/N K060961. al check was good	ight alternato od. Reinstalle entonville, AR N27 See Aerotecl at this time.	N27682 Air r AMP meter select and reconnected and reconnected and reconnected are reconnected as a reconnected as a reconnected are reconnected as a reconnect	ector switches. In the sector switches. Operated harness. Operated harness. Operated harness.
bubleshooting tiches and seek found fur westprial westprial westprial Replaced FAA 8130. Serviced a	ng of in-oper stub harness inctional test A&P 430554 Hobbs 281 left alternate 3 tracking for	Total Time 10 alional AMP met be, pressure clean ling was normal, 1968 Summit Av 16.7, Total Tim or W/Overhauled orm dated 30/App or system W/18 O	o ₃ 481.7 er found poor coned switches and lation LLC 2440 e 10,518.5 unit P/N ALU-85 //2014, Operation	ntinuity of left and r bench checked go o SW Aviation St. B 521, S/N K060961. al check was good	ight alternato od. Reinstalle entonville, AR N27 See Aerotecl at this time.	N27682 Air r AMP meter select and reconnected and reconnected and reconnected are reconnected as a reconnected as a reconnected are reconnected as a reconnect	ector switches. In the sector switches. Operated harness. Operated harness. Operated harness.
bubleshooting tiches and seek found fur westprial westprial westprial Replaced FAA 8130. Serviced a	ng of in-oper stub harness inctional test A&P 430554 Hobbs 281 left alternate 3 tracking for	Total Time 10 alional AMP met be, pressure clean ling was normal, 1968 Summit Av 16.7, Total Tim or W/Overhauled orm dated 30/App or system W/18 O	o ₃ 481.7 er found poor coned switches and lation LLC 2440 e 10,518.5 unit P/N ALU-85 //2014, Operation	ntinuity of left and r bench checked go o SW Aviation St. B 521, S/N K060961. al check was good	ight alternato od. Reinstalle entonville, AR N27 See Aerotecl at this time.	N27682 Air r AMP meter select and reconnected and reconnected and reconnected are reconnected as a reconnected as a reconnected are reconnected as a reconnect	ector switches. In the sector switches. Operated harness. Operated harness. Operated harness. Operated harness.
bubleshooting tiches and seek found fur westprial westprial westprial Replaced FAA 8130. Serviced a	ng of in-oper stub harness inctional test A&P 430554 Hobbs 281 left alternate 3 tracking for	Total Time 10 alional AMP met be, pressure clean ling was normal, 1968 Summit Av 16.7, Total Tim or W/Overhauled orm dated 30/App or system W/18 O	o ₃ 481.7 er found poor coned switches and lation LLC 2440 e 10,518.5 unit P/N ALU-85 //2014, Operation	ntinuity of left and r bench checked go D SW Aviation St. B 521, S/N K060961. al check was good	ight alternato od. Reinstalle entonville, AR N27 See Aerotecl at this time.	N27682 Air r AMP meter select and reconnected and reconnected and reconnected are reconnected as a reconnected as a reconnected are reconnected as a reconnect	ector switches. In the sector switches. Operated harness. Operated harness. Operated harness. Operated harness.

Wings Avionics, Inc. 421 Ernest Lancaster Dr. Fayetteville, AR 72701 W1NR1050 LOG ID# 3981 02-November-2017 W0# 6726 REF# 6726 HOBBS 2776.0 PIPER PA-31-350 S/N 31-7852105 N27682

Pg 1/2

**** ITEM # 6726-1 PERFORM FAR 91.411 & 91.413 ****
DISCREPANCY: PERFORM FAR 91.411 AND 91.413 CERTIFICATION.
Model: EFD1000 Part#: 910-0001-001 Serial#: 121211
ACTION: CONNECTED RAMP TEST EQUIPMENT TO THE AIRCRAFT, AND FOUND THE ASPEN EFD1000 PFD AND THE SAM MD302 STANDBY ATTITUDE MODULE DID NOT COMPLY WITH FAR PART 43, APPENDIX E, BAROMETRIC SCALE ERROR TOLERANCES. SEE TASK ITEMS 2 AND 3 FOR ADDITIONAL DETAILS REGARDING AIR DATA CALIBRATION. AFTER AIR DATA CALIBRATION PROCEDURES WERE COMPLETED FOR THE EFD1000 AND THE MD302 UNDER ASSOCIATED TASK ITEMS, THE ASPEN AVIONICS EFD1000 PFD, P/N 910-0001-001, S/N 121211; THE STANDBY MID-CONTINENT SAM MD302, S/N D15-11218; THE COPILOT UNITED INSTRUMENTS 5934PA-3 PRESSURE ALTIMETER, S/N 435552; AND THE AIRCRAFT STATIC SYSTEM WERE CERTIFIED TO 25K FEET I/A/W FAR 91.411 REQUIREMENTS. THE GARMIN GTX327 XPDR, P/N 011-00490-00, S/N 8373590, WAS RAMP TESTED AND FOUND IN COMPLIANCE WITH FAR 91.413 REQUIREMENTS.

**** ITEM # 6726-2 CALIBRATE ASPEN EFD1000 ADC ****
DISCREPANCY: CALIBRATE ASPEN EFD1000 AIR DATA COMPUTER (ADC)-DOES NOT MEET FAR PART 43, APPENDIX E, BAROMETRIC SCALE ERROR REQUIREMENTS.
Model: EFD1000 part#: 910-0001-001 Serial#: 121211
ACTION: CALIBRATED ASPEN EFD1000 ADC I/A/W ASPEN TECH NOTE FOR AIR DATA CALIBRATION, TECH NOTE 2009-09, REV D, DATED 04-07-2016. RETESTED SYSTEM AND FOUND BAROMETRIC SCALE ERROR WAS LESS THAN 5 FEET IN ERROR FROM MASTER ALTIMETER. COMPLETED FAR 91.411 CERTIFICATION UNDER TASK ITEM 1.

**** ITEM # 6726-3 CALIBRATE SAM MD302 ADC **** DISCREPANCY: CALIBRATE MID-CONTINENT SAM MD302 AIR DATA COMPUTER (ADC)-DOES NOT MEET FAR PART 43, APPENDIX E, BAROMETRIC SCALE ERROR REQUIREMENTS.

Wings Avionics, Inc. 421 Ernest Lancaster Dr. Fayetteville, AR 72701 W1NR1050 LOG ID# 3981 02-November-2017 WO# 6726 REF# 6726 HOBBS 2776.0 PIPER PA-31-350 S/N 31-7852105

Pg 2/2

Model: MD302 Part#: MD302 Serial#: D15-11218
ACTION: CALIBRATED SAM MD302 ADC I/A/W MID-CONTINENT INSTRUMENTS SAM MD302 INSTALLATION MANUAL, P/N
9017782, REV 3, DATED 08-27-2015. RETESTED SYSTEM AND FOUND BAROMETRIC SCALE ERROR WAS LESS THAN 3
FEET IN ERROR FROM MASTER ALTIMETER. COMPLETED FAR 91.411 CERTIFICATION UNDER TASK ITEM 1.

MAINTENANCE RELEASE / RETURN TO SERVICE
THE AIRCRAFT, AIRFRAME, AIRCRAFT ENGINE, PROPELLER OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED
AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION AND IS
APPROVED FOR RETURN TO SERVICE.

WINR1050 BRADY N TERRY

11-02-2017

I CERTIFY THAT THE ALTIMETER SYSTEM AND ALTITTUDE REPORTING SYSTEM TEST AND INSPECTION REQUIRED BY FAR 91.411 HAS BEEN PERFORMED I/A/W PART 43, APPENDIX E. THE ALTIMETER WAS TESTED TO 25,000 FEET BY

CRS W1NR1050 W/O 6726 SIGNED

DATE_11-02-17

WINGS AVIONICS INC. 421 ERNEST LANCASTER DR. **FAYETTEVILLE, AR 72701**

I CERTIFY THAT THE TRANSPONDER INSPECTION REQUIRED BY FAR 91.413 HAS BEEN PERFORMED I/A/W PART 43, APPENDIX F.

TYPE GTX327 011-00490-00 S/N 83735390

CRS W1NR1050

W/0_07 SIGNED / DATE 11

SCALE CORREC	TIONS	ALT SERIAL # 121211			
ALTIMETER		ALTIMETER EFOLOOC			
READS	UP	READS	UP		
-1000	+10	12000	+15		
0	-10	14000	+10		
500	-5	16000	+15		
1000	0	18000	+25		
1500	5	20000	125		
2000	0	22000	+30		
3000	-5	25000	+45		
4000	0	30000	1		
6000	0	35000	1		
8000	O	40000	X		
10000	+10	45000			
	1	50000	/		

WINGS AVIONICS, INC. W.O. 6726 N 27682

CRS W1NR1050

DATE 11-02-17 SIGNED BAC

J IVIAL-Carry forward to next page

10/12/2017, Hobbs 2719.2, Total Time 10,421.0, Heater Hobbs 578.3

N27682 Airframe Log Entry



- Performed Annual/100 hour inspection I/A/W FAR 43 App. D. All work was performed I/A/W Piper PA31-350 Maintenance Manual.
- Checked ADs through ATP revision dated 10/11/2017. See AD compliance report for recurring times.
- AD 2017-10-20 is not C/W at this time and is due to be complied with no later than 500 hours from now, which is at 3219.2 Hobbs or 10,921.0 AFTT. Kit P/N 88578-001 is on order.
- C/W AD 2016-05-01 by visual inspection of vertical fin forward spar bulkhead at (FS) 317.75 for cracks I/A/W Piper SB# 1273A. No cracks noted at this time. Configuration 2 is installed. Next inspection is due at 2819.2 and kit P/N 764-028 must be installed before 3130.8 Hobbs.
- C/W AD 82-27-13 R2 by performing free play inspection of flap transmission I.A.W Piper service bulletin No. 494B. No defects noted.
 Next inspection due at 2819.2 Hobbs.
- C/W AD 2003-24-07 by visual inspection of rudder tube for corrosion per paragraph (e)(2) 12 month insp. I/A/W SB# 1105A, no defects or corrosion noted, next due in Oct.2018.
- C/W AD 2009-13-06 R1 by inspection of nose baggage door latch and locking components, lubrication and replacement of time limited parts W/New as outlined in Piper SB# 1194A table 2. Operational check was good. No defects noted. Next inspection is due at 2819.2 and next life limited parts replacement next due at 3730.8 Hobbs.
- C/W AD 2013-10-4C Exhaust system inspection by visual inspection as outlined in AD text. No defects noted. Next inspection due at 2779.2 Hobbs or Apr. 2018.
- C/W AD 2015-19-07 by inspection I/A/W Lycoming Engines Mandatory Service Bulletin No. 342G. No defects noted and all required clamps are in place and no line defects noted. Next inspection due at 2819.2 Hobbs.
- C/W AD 84-26-02 by replacing right and left engine air inlet paper filters W/New (2 each) P/N P10-6590. Next replacement is due at 3219.2 Hobbs.
- Removed ELT and inspected I/A/W FAR 91.207 (d). Reinstalled and operational check was good. Next ELT battery replacement is due Dec. 2025.
- Repaired right engine alternate air door open cam by replacing loose rivets.
- Replaced right main tire and tube W/New, Goodyear Flight Custom III 6.50X10 10Ply tire P/N 650C06-3, S/N 71892263.
 Reassembled wheel W/New tube P/N 092-344-0, torqued bolts to 90 Inch LBS and serviced to 55 PSI. Leak checked good.
- · Serviced nose strut W/Nitrogen to 3.25 inches and leak check was good.
- Replaced nose mounted taxi lamps W/New (2 each) LED lamps P/N 01-0771733-20 and operational check was good.
- Found center left cowl latch receptacle loose from lower cowl. Removed lower cowl left center nut plate, installed doubler plate and new nut plate to this location. Adjusted length for proper fit of cowling halves.
- Removed in-operative, existing T.I.T. gauge and tail pipe probes. Added JPI T.I.T. option kit P/N 1210 to existing JPI EDM730.
 Installed blank plate to old gauge location. Operational check was good.
- Removed left and right gear down lock fork bolts, cleaned and inspected. No defects noted on either. Lubricated and reinstalled each.
- Replaced all landing gear hydraulic and brake caliper flex hoses W/New (16 each) manufactured and tested as a kit by PHT Inc. on invoice number 601159. Serviced landing gear power pack and performed bleeding procedure by performing several landing gear cycles. Bled right and left brakes. Operational test and leak checks of all hoses was good.
- Drained fuel completely from left wing. Replaced left fuel selector valve W/Overhauled unit P/N 3487-00-1 (492-239R) S/N 0397.
 Overhaul was performed by Dukes Aerospace Inc. on W/O number 1298, see FAA Form 8130-3 tracking number R11429 dated 01 APR 2017. Installed W/New fitting o-rings (3 each) P/N MS29512-08.
- Drained fuel completely from right wing. Physically weighed aircraft empty of usable fuel, both engines full of oil, hydraulic systems
 full and required paperwork on board. Weighed aircraft using calibrated platform scales with aircraft in level condition. New empty
 weight and balance data is as follows and is inserted to POH; New Basic Empty Weight 4957.5 LBS, New E.C.G. 123.4042, New
 Moment 611776.4 and New Useful Load 2292.5 LBS.
- I certify that this <u>Aircraft</u> was inspected I/A/W a <u>100 Hour/Annual Inspection</u> and was determined to be in Airworthy Condition.

 William Dorothy A&P 3504028 IA

SUB-TOTAL this page

TOTAL-Carry forward to next page

AIRCRAFT SN: PA-31-350 REG: N27682 AC TYPE: PIPER NAVAJO Total Times: 2706.4

- > Removed interior components for window panel refurbishment.
- > Recovered window panels utilizing ultra-leather PN DEF-GS202 Hood Stretch Columbia
- Replaced RH 1 Seat Bottom Center Insert utilizing leather PN A278 Avion Pompeii
- Recovered all single seat center isle side armrest utilizing leather PN A278 Avion Pompeii
- Repaired cracked and broken co-pilot, RH1,RH2,RH3,LH1,LH3 & emergency exit window panels Utilizing 3M-DP100 Epoxy Lot# 6187RE/6165
- Cleaned, repaired & dyed leather on lavatory seat.
- > Reinstalled interior components after refurbishment.
- ➤ All work was performed IAW AIS Inc. RSM/QCM procedures. A record of this work and documentation is on file under this repair station W/O # 729 .

Aviation Interior Services, Inc. CRS# 1ANR029B

TOTAL-Carry forward to next page

J. Gulli

3598107

July 7, 2017

Authorized Signature

Certificate #

Date

