

EAST COAST PROPELLER SERVICE, INC.
 2079 Main Street
 Lititz, PA 17543
 717-627-7407 800-875-6377
 REPAIR STATION #E65R064Y
 " Safety Through Quality "

ARTISAN FLYING CLUB
 PO BOX 10796

Acct: 616

Workorder: ER-3767
 Date: 01/24/03
 Terms: Net 0
 P.O.:

ROCHESTER, NY 14610

JOE HOOD 716-234-0270

HARTZELL HC-C2YK-1BF/F8475D-4 S/N CH36656B

MAJOR OVERHAUL. BLADES REFINISHED. PARTS ZYGLOED, MAGNAFLUXED, REPLATED. PARTS REPLACED WHERE REQUIRED. COMPLIED WITH AD'S AND SB'S LISTED ON THE YELLOW TAG. TRACKED, BALANCED, PAINTED, SET ANGLES. PROPELLER -O-TSO OUTRIGHT SALE.

REMOVAL & INSTALLATION	CADIUM PLATING		
OVERHAUL LABOR	SHOTPEENING		
A D NOTE COMPLIANCE	HUB REWORK		
INSPECT & REPAIR AS NECESSARY	DEICER BOOT INSTALL		
BLADE STRAIGHTENING	OUTSIDE LABOR		
BLADE REWORK	Misc.		
	TOTAL LABOR		\$0.00
1 HC-C2YK-1BF/F8475D-4	-O-TSO HARTZELL PROPELLER	\$4,800.00	\$4,800.00
	TOTAL PARTS		\$4,800.00
ECPS DELIVER	TRANSPORTATION		
	SUBTOTAL		\$4,800.00
	CORE CHARGE		
	DISCOUNT LABOR	-	
	DISCOUNT PARTS	-	
SALES TAX/RESALE #NO			\$0.00
	TOTAL AMOUNT DUE		\$4,800.00

PROPELLER MAINTENANCE RECORD

LEFT ENGINE

Hub Model HC-CAYK-1BF
Blade Design FB475D-4
Diameter _____
Hub Ser. No. CH 36656B
Blade Ser. Nos.
No. 1 D 73347
No. 2 D 73370
No. 3 _____
No. 4 _____
No. 5 _____
PITCH RANGE
High 34.0 Low 13.50
Feather _____ Reverse _____
Governor Model _____

RIGHT ENGINE

~~Hub Model _____
Blade Design _____
Diameter _____
Hub Ser. No. _____
Blade Ser. Nos. _____
No. 1 _____
No. 2 _____
No. 3 _____
No. 4 _____
No. 5 _____
PITCH RANGE
High _____ Low _____
Feather _____ Reverse _____
Governor Model _____~~

MAINTENANCE RELEASE

Make HARTZELL

Model HC-C29K-1BF/FB475D-4

Serial No. CH36056B

The component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and was found airworthy for return to service for work performed. Pertinent details of the repair are on file at this agency under Work Order No. ER-5769 and complies with Airworthiness Directives and Service Bulletins listed here.

3B's 11BF1364 1428 150 151A 155 159A 164C

E AD Notes 64-20-1, 74-15-2, 75-7-5 90-02-23

01-23-08 02-05-08

Manual No. 113B 133C & 202A

Total Time Repaired Forward Total Time Since O/H 0-

Date 2-4-03 Signed Shawn M. Young

EAST COAST PROPELLER SERVICE INC.

MAINTENANCE RELEASE

Make HARTZELL

Model HC-C29K-1BF/FB475D-4

Serial No. CH36056B

The component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and was found airworthy for return to service for work performed. Pertinent details of the repair are on file at this agency under Work Order No. ER-5831 and complies with Airworthiness Directives and Service Bulletins listed here.

SERVICE Bulletins - 11BF 13681

Manual No. 113B 133C & 202A

Total Time Repaired Forward Total Time Since O/H 0-

Date 11/29/02 Signed S.M. Young

EAST COAST PROPELLER SERVICE INC.

DATE
11/99

SERVICEABLE

CUSTOMER Artisan Flying Club

MFG Hartzell

COMPONENT HC-C20K-1BF/F-8475D-4

REMARKS Complete Overhaul w/Factory New Hub,

Inspected By: Reviewed, Measured, ODR Correct, BIA
of Inspected Assembled, Test, Coarse, Reset Angle, checked Torq & Bulb

ANGLES AT 30" STA. LO: 135° HI: 34.0° FEA -

REV: -


EAST COAST PROPELLER SERVICE INC.

2079 Main Street
 Lititz, PA 17543
 #E65R064Y

DESCRIPTION OF ALL OPERATIONS
 PERTAINING TO AIRWORTHINESS DIRECTIVES,
 SERVICE BULLETINS, SERVICE LETTERS,
 & MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
2-6-03		Hartzell Propeller HC-C20K-1BF/F-8475D-4, SN CH 342508 WAS COMPLETELY OVERHAUL WITH FACTORY NEW HUB INSTALLED, SEE YELLOW STRIP FOR DETAILS	
		MAINTENANCE RELEASE The component identified above was repaired and inspected in I.A.W. regulations of the FAA and was found airworthy for return to service for work performed. Pertinent details of the repair are on file at this agency under work order # <u>02-3762</u>	<u>William M. Jancy FAA</u>
		EAST COAST PROPELLER SERVICE INC. 2079 MAIN ST. LITITZ, PA 17543 FAA REPAIR STATION #E65R064Y	

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
11/29/06	0-TSOH	HARTZEL Propeller Model HC-C29K-1BF S/N CH356506, was overhauled this Date, See Remarks Tab for Details	 Randy L. Barnett General Manager
		<small> 1. This work was performed in accordance with the applicable FAA regulations, and the FAA approved the work on the basis of the information furnished and the work performed. The FAA does not guarantee the accuracy of the information furnished, nor does it warrant the quality of the work performed. The FAA is not responsible for any damage to the aircraft or its components. 2. The FAA does not certify the quality of the work performed, nor does it warrant the quality of the work performed. The FAA is not responsible for any damage to the aircraft or its components. </small>	
		EC-5831	

UNSERVICEABLE

CUSTOMER Boshart Enterprises

MFG Hartzel

COMPONENT HC-C29K-1BF / FB475D-4

REMARKS Complete Overhaul Inspected & Reentered,
Manufactured, EPPV Cement Blades Resinized Assembled Tests
Grossed Baser Angles, checked Track & Starte Balanced
ANGLES AT 30° STA. LO: 13.5° HI: 34.0 FEA -

EAST COAST PROPELLER SERVICE
2079 Mall
Littitz, PA
#E65R



EAST COAST PROPELLER SERVICE
Specializing in the repair, overhaul & sale
of all makes of propellers & governors
RANDY L. BARNETT
General Manager

DE 8/11/01 D 73367 (2)

800/875-6377 • 717/627-7407 • Fax 717/627-7409
2079 Main Street, Littitz, PA 17543

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
11/13/07	428284	SMOH: 0.00 Total: unknown Install and this propeller after overhaul by East Coast Propeller to Part PA39R-300 9V 32-7780239	AP 278 a, Janel A. G.
4/18/07		I CERTIFY THAT THIS Propeller HAS BEEN INSPECTED IN ACCORDANCE W/A Annual TYPE INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. A.D. SUMMARY TO 2007-06 CHECKED OPERATIONAL CHECK SATISFACTORY.	AP 77540206
4/3/278			
		SIGNATURE <u>Janel A. G.</u>	
		FOR REPAIR STA. B2ER14A1	
		TOTAL TIME <u>Unknown</u> TACH <u>4312.78</u>	
		DATE OF INSPECTION <u>4/18/07</u>	
		SMOH <u>29.94</u>	

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
5/13/08	452665	Total: Unknown SMOH: 243.81 Replaced Fuel spinner bulkhead. Stripped, primed, painted spinner, lubricated hubs. Dressed blades.	
		I CERTIFY THAT THIS Propeller HAS BEEN INSPECTED IN ACCORDANCE W/A Annual TYPE INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. A.D. SUMMARY TO 200808 CHECKED OPERATIONAL CHECK SATISFACTORY.	
		SIGNATURE <u>Janel A. G.</u>	
		FOR REPAIR STA. B2ER14A1	
		TOTAL TIME <u>Unknown</u> TACH <u>4526.65</u>	
		DATE OF INSPECTION <u>5/13/08</u>	