


# JORDAN PROPPELLER



## SERVICE

INC.

---

103 E. Rhapsody • San Antonio, Texas 78216 • (210) 344-3064 • (866) 344-7767 • Fax (210) 344-9433 • CRS EK2R797K

### Propeller Logbook

# PROPELLER MAINTENANCE RECORD

Hub Model PHE-234F-224F

Blade Design FC 7663-2R

Diameter 76 INCH

Hub Serial No. EB 1225

Blade Serial Nos. \_\_\_\_\_

No. 1 E 38253

No. 2 E 38228

No. 3 E 37627

No. 4 \_\_\_\_\_

No. 5 \_\_\_\_\_

## PITCH RANGE

High — Low 13.0°

Feather 83.5° Reverse —

Latch Angle 20.0°

DESCRIPTION OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES,  
SERVICE BULLETINS, SERVICE LETTERS  
& MINOR ADJUSTMENTS

DESCRIPTION OF WORK

B&G Aviation LLC

Georgetown Texas 78628 ph 512-864-7632

N4519A

ACTT:

SN# TE-806

HRM: 1613.9

Date 1/26/2023

1. Removed propeller SN# EB1225 sent out for overhaul and reinstalled on the RH engine  
This aircraft is approved for return to service in  
regards to *Work performed*

Bradley D Gray A&P 3138226

3-2-23

N4519A

Rt. Prop PHC-C3Y-2VF

Tach: 1613.9

TSMOH: 0.0

S/N: EB1225

100 hr. insp. completed this date. For current status of all A.D.'s see aircraft records. I certify this propeller has been inspected in accordance with a 100 hr. inspection and determined to be in airworthy condition.

Gary W. Shelton A&P36921751A

