



*The Standard*

# **PROPELLER LOG**

**ASA-SP-L**



The Standard Propeller Log  
SP-L

© 1994 Aviation Supplies & Academics, Inc.

**ASA-SP-L**

ISBN 978-1-56027-418-6

All rights reserved.  
Reproduction or use, without written permission,  
in any manner, is prohibited.

Published by  
Aviation Supplies & Academics, Inc.  
7005 132nd Place SE  
Newcastle, WA 98059-3153  
Website: [www.asa2fly.com](http://www.asa2fly.com)  
Email: [asa@asa2fly.com](mailto:asa@asa2fly.com)

Printed in the United States of America

19/2019

TRANSPORTATION USD \$4.95

ISBN 978-1-56027-418-6



9 781560 274186

## Propeller Record General Information

Propeller Manufacturer

McCAULEY

Model

2A34C66-NP

Type

Hub Series #

Blade #

Date of Manufacture

SERIAL # 782699

Make/Model

Aircraft Installed On:

C-182

Serial #

18260128

# JORDAN PROPELLER SERVICE, INC.

103 East Rhapsody San Antonio, Texas 78216

Certificated Repair Station No. EK2R797K

PROPELLER S/N 782699 HAS BEEN OVERHAULED

REFERENCE McCauley Manuals 720415, BOM100-11 & SPM100-8.

Blade Dwg. No. S-90AT-8 Serial No.'s K47997YS & K48008YS. C/W Service Bulletins 151-A, 152B, 184B, 227B (Torque Decal Installed) and Service Letters 1989-2C, 1991-5A, 1998-8B, 2001-1F, 2007-12, 2013-01, 2014-01J, 2014-02, 2021-3 & 2022-2.

PERTINENT DETAILS ON FILE UNDER WORK ORDER 22851

SIGNED *Barry C. Jordan* DATE 30/Apr/2022

MECHANIC MAKING INSTALLATION ON A/C MUST C/W FAR 43.9

Year:	Total Time in Service	Description
Date:		
Next Inspection Due:	Time Since Overhaul	
Mech. Cert. # or Repair Station #		



222 Airport Drive, Lockhart, TX 78644

512-398-3439

ADE INSPECTIONS, REPAIRS AND ALTERATIONS ☐

Tach 1700.0

N92282

Date 06/21/2022

Performed annual inspection IAW Cessna Service Manual. Propeller overhauled by Jordan Propeller Service. Installed with new nuts and torqued. Propeller governor overhauled by Texas Aircraft Propeller. I certify that this propeller has been inspected IAW an annual inspection and found to be in airworthy condition at this time.

*[Signature]*  
A&P/IA 3279628

Next Inspection Due:	Time Since Overhaul	
Mech. Cert. # or Repair Station #		
Year:	Total Time in Service	Description
Date:		
Next Inspection Due:	Time Since Overhaul	
Mech. Cert. # or Repair Station #		

# JORDAN PROPELLER SERVICE, INC.

103 East Rhapsody - San Antonio, Texas 78216

Certificated Repair Station No. EK2R797K

PROPELLER S/N 782699 HAS BEEN REPAIRED

REFERENCE McCauley Manual 720415

Leak Checked and Replaced Hub Mounting O-Ring To Correct Engine Oil Leakage At Crankshaft Flange.

PERTINENT DETAILS ON FILE UNDER WORK ORDER 24135

SIGNED Gary C. Jordan DATE 26/Jul/2023

MECHANIC MAKING INSTALLATION ON A/C MUST C/W FAR 43.9

## HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS ☐

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____

  

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____