44584

PROPELLER LOG BOOK



SENSENICH PROPELLER COMPANY
EAST AIRPORT ROAD
LANCASTER, PA 17601
USA

THIS LOG BOOK IS TO BE KEPT
WITH THE PROPELLER
FOR RECORDING OF ALL PROPELLER MAINTENANCE WORK PERFORMED

10/89

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
3 JUNE 94	4477.96	INSTALLED FACTORY NEW PROPELLER MIN 76EM8S5-0-62 S/N 29504K ON AIRCRAFT.	
		H & H PROPELLER SERVICE INC. 3532 AIRPORT LOOP ROAD BURLINGTON MUNICIPAL AIRPORT BURLINGTON, N. C. 27215 FAA REPAIR STATION PS4R451M 1-800-334-6437	Lowell T. Martin
Piper	28-180		
N44584			
28-7405262			
LYC	0360-A4A		

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
1 Oct 94	4520.31	Annual Inspection C/W IAW	
42.35	S NEW	Service Manual RD Smith IA2228094	
1 Dec 95	TAC 4631.54	Annual Inspection C/W	
	This tac time & date.	Roger D. Smith	
153.58	S NEW	IA 2228094	

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
1 Feb 96	4651.54	Painted Prop & Checked Torque RD Smith A&P	2228094
15 JAN 97 - 1-29-97	4735.0	Removed Prop from Engine S/N L-103	
257.04 SNEW		69-36A & Reinstalled on Engine S/N RL-29834-36A Factory Overhaul from Lycoming 0 SMOH ON Eng	
		Annual Inspection Due this Date Time & Date RD Smith IA 2228094	

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
26 Feb 98	4871.24 393.3 SNEW	Annual Inspection C/W this tac time and date. Roger Dale Smith IA 2228094	
3-11-99 539.52 SINCP New	5017.48	Annual Inspection C/W RD Smith IA 2228094	

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
2000	5197.38	Annual Inspection C/W this Tac Time +	
4/20	719.42	date. Roger Dale Smith IA 2228094	
	SNEW		
4 MAY			
2001	5332.0	ANNUAL INSPECTION C/W this TAC TIME+	
854.04	SINCE	DATE. William W. Hill IA 2417095 6	
NEW			
8/20/05	5776.94	100 HOUR Inspection C/W this Date+	
1041.52	SNEW	2837743 A&P/I.A.	
8/20/06	5806.08	100 Hour Inspection C/W this Date. Cleaned and Painted	
		back of Prop. Dressed Nicks in Leading edge of Prop.	
		2837743 A&P/I.A.	

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE

C&R AIRCRAFT MAINTENANCE, LLC 117 CONSTELLATION DR. CRESSON, TX. 76035
WORK (817) 512-4731 CELL (817) 308-5519

This Propeller was inspected IAW the latest Piper inspection manual and check list for a 100 hour inspection. The following maintenance was performed: Dressed nicks on Leading edge of propeller. Painted backside of propeller with flat black paint. The following new AD's were complied with: No new AD's were released from last annual. AD's checked thru week 2008-18

I CERTIFY THAT THIS *Propeller* HAS BEEN INSPECTED IN ACCORDANCE WITH A *100 hour* INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.
OKAY FOR RETURN TO SERVICE
DATE *09/13/2008* TOTAL TIME *1368.7* TACH TIME *5846.6* T.S.NEW. *1368.7*

SIGNATURE _____ **R.J.Pyles** **NO *2837743 A&P/I.A.***

01 March 2012 N44584 Tach 5895.62 TTSN 1417.73

I certify that this PROPELLOR has been inspected in accordance with an ANNUAL inspection and was determined to be in airworthy condition Scott AEP 2631919 IA

C&R AIRCRAFT MAINTENANCE, LLC 117 CONSTELLATION DR. CRESSON, TX. 76035
WORK (817) 512-4731 CELL (817) 308-5519

This Propeller was inspected IAW the latest Piper inspection manual and check list for a 100 hour inspection. The following maintenance was performed: Removed propeller and replace the forward bulkhead plate with TCB65804-00 Composite part IAW STC SA00945AT (See 337 this date). Reinstalled propeller and torque bolts to 63 ft.lbs. and safety wired with .040 SS wire. The following new AD's were complied with: No new AD's were released from last annual. AD's checked thru week 2009-22

I CERTIFY THAT THIS *Propeller* HAS BEEN INSPECTED IN ACCORDANCE WITH A *100 hour* INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.
OKAY FOR RETURN TO SERVICE
DATE *09/13/2009* TOTAL TIME *1381.6* TACH TIME *5859.5* T.S.NEW. *1381.6*

SIGNATURE _____ **R.J.Pyles** **NO *2837743 A&P/I.A.***

C&R AIRCRAFT MAINTENANCE, LLC 117 CONSTELLATION DR. CRESSON, TX. 76035
WORK (817) 512-4731 CELL (817) 308-5519

This Propeller was inspected IAW the latest Piper inspection manual and check list for a 100 hour inspection. The following maintenance was performed: Removed propeller spinner for Inspection, rechecked torque on bolts on the forward bulkhead plate to 63 ft.lbs. and safety wired with .040 SS wire. The following new AD's were complied with: No new AD's were released from last annual. AD's checked thru week 2010-23

I CERTIFY THAT THIS *Propeller* HAS BEEN INSPECTED IN ACCORDANCE WITH A *100 hour* INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.
OKAY FOR RETURN TO SERVICE
DATE *11/14/2010* TOTAL TIME *1394.78* TACH TIME *5872.68* T.S.NEW. *1394.78*

SIGNATURE _____ **R.J.Pyles** **NO *2837743 A&P/I.A.***