



Ultimate
Engines

C.R.S. YCTR978K
MENA, ARKANSAS 71908
501-304-5422



The Standard
ENGINE LOG

ASA-SE-2

YEAR	RECORDING TACH	TODAY'S FLIGHT	TOTAL TIME IN	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of
-------------	-----------------------	-----------------------	----------------------	---

Report Produced By: Peter Lo Bello at Ultimate engines Address: 106 Elk Dr., Mena, AR 719 Phone: 501-394-5422

Airworthiness Directive Compliance Record

File ID: **EATON ENGINE**

USARL Research Date: 10/05/2000

Manufacturer Teledyne Continental	Model IO-520-BB	Part # : Not Specified Serial # : 232743.R
---	---------------------------	---

AD Number Effective date	Description	Complied Date Time	Status Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 2. Cert. Type 3. Cert. Num. 4. Author. by
79-05-09 03/12/1979 ⓐATP	To Prevent The Possible Loss Of Oil Pressure Indication ⓐATP	09/27/00	NA per engine serial number.	Once ⓐATP		1. Ultimate engines 2. Repair Station 3. YCTR973K 4. Sam Bass Signature:
80-01-04 01/25/1980 ⓐATP	To Prevent Failure Of Cylinder Holddown Flanges ⓐATP	09/27/00	NA- New Superior cylinders installed.	Once ⓐATP		1. Ultimate engines 2. Repair Station 3. YCTR973K 4. Sam Bass Signature:
81-24-06 11/23/1981 ⓐATP	To Prevent Possible Fuel Leakage And Potential Fire Hazard ⓐATP	09/27/00	NA per fuel pump serial number and date of manufacture (E088506B).	Recur ⓐATP		1. Ultimate engines 2. Repair Station 3. YCTR973K 4. Sam Bass Signature:
86-13-04 R3 02/24/1988 ⓐATP	To Prevent Possible Cylinder Head To Barrel Separation, Engine Failure And/Or ⓐATP	09/27/00	NA- New Superior cylinders installed.	Recur ⓐATP		1. Ultimate engines 2. Repair Station 3. YCTR973K 4. Sam Bass Signature:
87-12-12 L 07/02/1987 ⓐATP	Superseded by 87-14-02 ⓐATP	09/27/00	Superseded	Once ⓐATP		1. Ultimate engines 2. Repair Station 3. YCTR973K 4. Sam Bass Signature:
87-14-02 10/05/1987 ⓐATP	To Prevent Possible Starter Adapter Shaftgear Failure, Which Could Result In L ⓐATP	09/27/00	NA- Air conditioner not installed.	Once ⓐATP		1. Ultimate engines 2. Repair Station 3. YCTR973K 4. Sam Bass Signature:

YEAR	RECORDING	TODAY'S	TOTAL	Description of Inspections, Tests, Repairs and Alterations
------	-----------	---------	-------	--

Report Produced By: Peter Lo Bello at Ultimate engines Address: 106 Elk Dr., Mena, AR 719 Phone: 501-394-5422

Airworthiness Directive Compliance Record File ID: **EATON LH MAG**

USARL Research Date: 10/05/2000

AD Number Effective date	Description	Complied Date Time	Status Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 2. Cert. Type 3. Cert. Num. 4. Author. by
Manufacturer Bendix Corporation		Appliance Category Magnetos		Model S-1200 SERIES		
Part # : 10-349220-5 Serial # : J049112FR						
73-07-04 10/11/1973	Superseded by 94-01-03	09/27/00	Superseded	Once		1. Ultimate engines 2. Repair Station 3. YCTR973K 4. Sam Bass
EATP	EATP			EATP	Signature	
74-26-09 12/24/1974	S-20,-200,-1200 Series Magnets	09/27/00	NA per magneto model and part number.	Once		1. Ultimate engines 2. Repair Station 3. YCTR973K 4. Sam Bass
EATP	EATP			EATP	Signature	
78-09-07 R3 01/17/1983	Superseded by 96-12-07	09/27/00	Superseded	Recur		1. Ultimate engines 2. Repair Station 3. YCTR973K 4. Sam Bass
EATP	EATP			EATP	Signature	
82-13-01 06/28/1982	Magneto And Engine Malfunction	09/27/00	NA per magneto serial number.	Recur		1. Ultimate engines 2. Repair Station 3. YCTR973K 4. Sam Bass
EATP	EATP			EATP	Signature	
82-20-01 06/14/1983	To Prevent Failure Of Impulse Coupling Due To Improperly Heat Treated (Soft) F	09/27/00	NA per model and serial number.	Once		1. Ultimate engines 2. Repair Station 3. YCTR973K 4. Sam Bass
EATP	EATP			EATP	Signature	
94-01-03 R2 06/28/1995	To Prevent Magneto Failure And Subsequent Engine Failure	09/27/00	NA per magneto serial number.	Once		1. Ultimate engines 2. Repair Station 3. YCTR973K 4. Sam Bass
EATP	EATP			EATP	Signature	

YEAR	RECORDING	TODAY'S	TOTAL	Description of Inspections, Tests, Repairs and Alterations
------	-----------	---------	-------	--

Report Produced By: Peter Lo Bello at Ultimate engines Address: 106 Elk Dr., Mena, AR 719 Phone: 501-394-5422

Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

Airworthiness Directive Compliance Record File ID: **EATON LH MAG**

USARL Research Date: 10/05/2000

AD Number Effective date	Description	Complied Date Time	Status Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 2. Cert. Type 3. Cert. Num. 4. Author. by
Manufacturer Bendix Corporation		Appliance Category Magnetos		Model S-1200 SERIES		
Part # : 10-349220-5 Serial # : J049112FR						
94-06-09 05/20/1994	To Prevent Injury Or Death To Ground Personnel Due To A Non-Grounded Magneto	09/27/00	NA per magneto serial number.	Once		1. Ultimate engines 2. Repair Station 3. YCTR973K 4. Sam Bass
EATP	EATP			EATP	Signature	
96-12-07 07/18/1996	To Prevent Magneto Failure And Subsequent Engine Failure	09/27/00	NA - non-impulse coupling magneto.	Recur		1. Ultimate engines 2. Repair Station 3. YCTR973K 4. Sam Bass
EATP	EATP			EATP	Signature	
						Signature
						Signature
						Signature

YEAR	TOTAL	Reference of Major Repairs and Major Alterations To
-------------	--------------	--

Report Produced By: Peter Lo Bello at Ultimate engines Address: 106 Eik Dr., Mena, AR 719 Phone: 501-394-5422

Airworthiness Directive Compliance Record File ID: **EATON RH MAG**

USARL Research Date: 10/05/2000

AD Number Effective date	Description	Complied Date Time	Status Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 2. Cert. Type 3. Cert. Num. 4. Author. by
Manufacturer Bendix Corporation		Appliance Category Magnetos		Model S-1200 SERIES		Part # : 10-349200-6 Serial # : J039104FR
73-07-04 10/11/1973	Superseded by 94-01-03	09/27/00	Superseded	Once		1. Ultimate engines 2. Repair Station 3. YCTR973K 4. Sam Bass
EATP	EATP			EATP	Signature	
74-26-09 12/24/1974	S-20,-200,-1200 Series Magnetos	09/27/00	NA per magneto model and part number.	Once		1. Ultimate engines 2. Repair Station 3. YCTR973K 4. Sam Bass
EATP	EATP			EATP	Signature	
78-09-07 R3 01/17/1983	Superseded by 96-12-07	09/27/00	Superseded	Recur		1. Ultimate engines 2. Repair Station 3. YCTR973K 4. Sam Bass
EATP	EATP			EATP	Signature	
82-13-01 06/28/1982	Magneto And Engine Malfunction	09/27/00	NA per magneto serial number.	Recur		1. Ultimate engines 2. Repair Station 3. YCTR973K 4. Sam Bass
EATP	EATP			EATP	Signature	
82-20-01 05/14/1983	To Prevent Failure Of Impulse Coupling Due To Improperly Heat Treated (Soft) F	09/27/00	NA per model and serial number.	Once		1. Ultimate engines 2. Repair Station 3. YCTR973K 4. Sam Bass
EATP	EATP			EATP	Signature	
94-01-03 R2 06/28/1995	To Prevent Magneto Failure And Subsequent Engine Failure	09/27/00	NA per magneto serial number	Once		1. Ultimate engines 2. Repair Station 3. YCTR973K 4. Sam Bass
EATP	EATP			EATP	Signature	

YEAR	A.D. NUMBER	TOTAL TIME IN SERVICE	Airworthiness Directives Chronological Listing of Compliance and Method of Compliance
-------------	--------------------	------------------------------	---

Report Produced By: Peter Lo Bello at Ultimate engines Address: 106 Eik Dr., Mena, AR 719 Phone: 501-394-5422

Airworthiness Directive Compliance Record File ID: **EATON RH MAG**

USARL Research Date: 10/05/2000

AD Number Effective date	Description	Complied Date Time	Status Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 2. Cert. Type 3. Cert. Num. 4. Author. by
Manufacturer Bendix Corporation		Appliance Category Magnetos		Model S-1200 SERIES		Part # : 10-349200-6 Serial # : J039104FR
94-06-09 05/20/1994	To Prevent Injury Or Death To Ground Personnel Due To A Non-Grounded Magneto	09/27/00	NA per magneto serial number.	Once		1. Ultimate engines 2. Repair Station 3. YCTR973K 4. Sam Bass
EATP	EATP			EATP	Signature	
96-12-07 07/18/1996	To Prevent Magneto Failure And Subsequent Engine Failure	09/27/00	NA - non-impulse coupling magneto.	Recur		1. Ultimate engines 2. Repair Station 3. YCTR973K 4. Sam Bass
EATP	EATP			EATP	Signature	
Signature						
Signature						
Signature						
Signature						