



The Standard

PROPELLER LOG

ASA-SP-L

SERVICEABLE PARTS TAG

Customer Order No. T. EATON Work Order No. 6670

Customer Name FERRIS AIR SERVICES

JORDAN PROPELLER SERVICE INC.

103 EAST RHAPSODY SAN ANTONIO, TEXAS 78216
Certificated Repair Station No. EK2R797K

PROPELLER S/N 665294 HAS BEEN REPAIRED

AND/OR OVERHAULED I/AW MANUAL No. 720415.

MODIFIED HUB TO "OIL-FILLED" CONFIGURATION

AND OVERHAULED PROPELLER. % S.B.'S 42-1, 49-3,

118, 150, 196B, 204, 205B & 218.

PERTINENT DETAILS ON FILE UNDER W.O. 6670

SIGNED Sary Jordan DATE 11-03-00

MECHANIC MAKING INSTALLATION ON A/C MUST C/W FAR 43.9

gulation, ground
return to service.



The Standard

PROPELLER LOG

ASA-SP-L