

Date 03/13/2023 Make Model Textron (Beech) A36

Tail # N3116W

Serial # E-499

Airworthiness Directive Compliance Report

Airframe Hours:

Misc:

Engine: Continental IO-550-B

S/N: 686054

Hours:


Propeller: Hartzell PHC-C3Y Series

S/N:

Hours:

AD#	Category	Subject	Amend #	Eff Date	Rec	Remarks
Date/Hours Compliance	Next Due	Name	Signature	Cert#		
Airframe: Textron (Beech) A36						
70-12-02	Airframe	Center Seat Tracks	39-1001	06/09/70		N/A per S/N
		Kyle W. Stoup				
71-24-10	Airframe	Security of Control Wheel	39-1693	08/01/73		N/A per S/N
		Kyle W. Stoup				
72-11-02	Airframe	Engine Fuel Interruption	39-1449	05/20/72		N/A per S/N
		Kyle W. Stoup				
73-14-03	Airframe	Landing Gear Shock Strut Piston	39-1679	07/06/73		N/A per S/N
		Kyle W. Stoup				
74-03-02	Airframe	Landing Gear Strut Pistons	39-1777	02/05/74		N/A per S/N
		Kyle W. Stoup				
74-12-02	Airframe	Aft Facing Seats	39-1857	06/05/74		N/A per S/N
		Kyle W. Stoup				
74-24-03	Airframe	Strobe Light System	39-2016	11/22/74		N/A affected part not installed.
		Kyle W. Stoup				
75-05-02	Airframe	Engine Oil	39-2095	02/21/75	Yes*	N/A STC not installed
		Kyle W. Stoup				
76-22-02	Airframe	Lap Belt Assembly	39-2909	06/02/77		N/A per S/N
		Kyle W. Stoup				
79-01-01	Airframe	Screws in the Control System	39-3386	01/08/79		PCW-6/4/1979
		Kyle W. Stoup				
84-09-01	Airframe	Window Emergency Egress	39-4847	05/25/84		PCW-per AD 76-04-07-9/16/1976
		Kyle W. Stoup				
87-18-06 R1	Airframe	Seat Recline Actuator Handle	39-5837	02/05/88		N/A per S/N
		Kyle W. Stoup				
88-20-01	Airframe	Firewall Material	39-6017	10/19/88		N/A per S/N
		Kyle W. Stoup				
88-21-02	Airframe	Seat Tracks	39-6028	10/31/88		N/A per S/N
		Kyle W. Stoup				
91-17-01	Airframe	Elevator Trim Tab Actuators	39-7099	11/25/91		PCW per SB2399 on 5/1/1991
		Kyle W. Stoup				
91-20-08	Airframe	Fresh Air Blower Housing	39-8042	10/31/91		N/A per S/N
		Kyle W. Stoup				
92-18-11	Airframe	Landing Gear Circuit	39-8356	10/19/92		N/A per S/N
		Kyle W. Stoup				
93-03-02	Airframe	Loran Receiver System	39-8501	03/12/93		N/A per S/N
		Kyle W. Stoup				
93-24-03	Airframe	Rudder Forward Spar	39-8752	01/21/94	Yes*	PCW-5/7/2003, no repetitive inspections required.
		Kyle W. Stoup				
95-04-03	Airframe	Wing Carry Through Frame Inspection	39-9155	04/07/95	Yes	PCW-11/1/2019-next due Tach 572.1
		Kyle W. Stoup				
97-14-15	Airframe	Cabin and Utility Door Handle	39-10073	09/02/97		PCW-5/20/1998
		Kyle W. Stoup				
99-09-15	Airframe	Flight Control Mechanism	39-11148	05/18/99		N/A per S/N
		Kyle W. Stoup				
00-20-14	Airframe	Firewall Seal	39-11925	11/28/00		N/A per S/N
		Kyle W. Stoup				
00-24-04	Airframe	Rudder Control Cable System	39-12011	01/05/01		N/A per S/N
		Kyle W. Stoup				
01-08-06	Airframe	V-Band Exhaust Clamp	39-12185	06/07/01	Yes	N/A affected part not installed.
		Kyle W. Stoup				
01-11-03	Airframe	Blower Motor Circuit	39-12244	07/29/01		N/A per S/N
		Kyle W. Stoup				
01-23-10	Airframe	Flag	N3116W	03/13/2023	Tach- 278.2	SNEW-278.2
03-01-01	Airframe	Flag	I certify this PROPELLER has been inspected and found to be in a AIRWORTHY condition. Inspected in accordance with the scope and detail of Part 43 Appendix D using the manufacturer service manual for reference. Greased propeller with aeroshell 6. Cleaned and dressed blades. Inspected blades, hub, spinner, and backplate. Test ran aircraft, no leaks or defects noted at this time.			
07-08-08	Airframe	Lan				
08-13-17	Airframe	Circ				

Kyle W. Stoup AP 3252238



STAPLES

09-25-01	Airframe	Pilot & Copilot Shoulder Harnesses Kyle W. Stoup	39-16118	01/08/10		N/A per S/N
19-23-10	Airframe	Right Aileron Flight Control Cable End Fittings Kyle W. Stoup	39-19804	11/22/19		PCW-12/3/2019

Engine: Continental IO-550-B

86-13-04 R3	Engine	Cylinder Assemblies Pressure Test Kyle W. Stoup	39-5850	02/24/88	Yes*	N/A per S/N
87-14-02	Engine	Starter Adapter Shaftgear Kyle W. Stoup	39-5732	10/05/87		N/A per S/N
88-03-06	Engine	Oil Filter Kyle W. Stoup	39-5888	04/15/88		N/A per overhaul date
88-17-03	Engine	Starter Adapter Assembly Kyle W. Stoup	39-5943	08/10/88		N/A air conditioner not installed
91-19-03	Engine	Collapsed Oil Filter Elements Kyle W. Stoup	39-8030	09/29/91		N/A per overhaul date
93-10-02	Engine	Missing Cylinder Valve Retainer Key Kyle W. Stoup	39-8603	08/12/93		N/A per S/N
93-16-15	Engine	Fuel Pump Drive Shaft Kyle W. Stoup	39-8743	12/14/93		PCW-4/16/2018
98-01-08	Engine	Exhaust Roller Rocker Arms Kyle W. Stoup	Priority Letter	12/23/97		N/A per overhaul date
99-19-01	Engine	Crankshaft Cheek Cracks Kyle W. Stoup	39-11290	09/30/99		N/A per overhaul date
00-23-21	Engine	Crankshaft Connecting Rod Journal Failure Kyle W. Stoup	39-11994	12/12/00		N/A per overhaul date
04-08-10	Engine	ECI Reciprocation Engine Cylinder Head Cracks Kyle W. Stoup	39-13579	05/05/04		N/A per model number
07-04-19 R1	Engine	Superior Air Parts Cylinder Assemblies Kyle W. Stoup	39-15005	05/07/07		N/A per overhaul date
09-19-07	Engine	EQ3 Cylinder Head Cracks Kyle W. Stoup	39-16023	10/07/09	Yes	N/A per overhaul date
10-11-04	Engine	Hydraulic Lifter Face Wear Kyle W. Stoup	39-16309	06/16/10		PCW-4/16/2018
12-03-06	Engine	AVStar Fuel Servo Diaphragm Kyle W. Stoup	39-16947	02/24/12		N/A per overhaul date
14-05-29	Engine	(SAP) Cast Cylinder Assemblies Kyle W. Stoup	39-17801	04/25/14	Yes	N/A affected cylinders not installed
16-16-12	Engine	AEC/CMI Cylinder Assemblies Kyle W. Stoup	39-18610	09/15/16		N/A per overhaul date
22-16-03	Engine	S-1200 Series Magneto Roller Bearings Kyle W. Stoup	39-22132	08/15/22		N/A per date of overhaul
23-02-12	Engine	Intake Valve Failures Kyle W. Stoup	39-22319	02/17/23		N/A per date of cylinder installation.
23-04-08	Engine	Crankshaft Counterweight Retaining Rings Kyle W. Stoup	39-22355	02/23/23		N/A per date of overhaul

Propeller: Hartzell PHC-C3Y Series

94-17-13	Propeller	Propeller Hub Grease Fitting Hole Cracks Kyle W. Stoup	39-9008	09/15/94	Yes	N/A per serial number
01-07-03	Propeller	BASCO Serviced Propellers Kyle W. Stoup	39-12168	06/04/01		N/A prop not serviced by BASCO
03-13-17	Propeller	T and W Serviced Propellers Kyle W. Stoup	39-13219	07/18/03		N/A prop not serviced by T and W
05-14-11	Propeller	Southern California Propeller Serviced Propellers Kyle W. Stoup	39-14188	08/17/05		N/A prop not serviced by Southern California Propeller
06-24-07	Propeller	Oxford Aviation/CSE Aviation Serviced Propellers Kyle W. Stoup	39-14836	01/03/07		N/A prop not serviced by Oxford
07-26-09	Propeller	Fatigue Cracks Kyle W. Stoup	39-15311	01/30/08		N/A per overhaul date

Appliance: Power Plant - Ignition - Switches

76-07-12	Appliance	10-357XXX, 10-126XXX, 10-157XXX - Switch Repair or Replacement Kyle W. Stoup	39-3024	08/30/77	Yes	CW 03/13/2022 by operational check. Next due at at Tach- 378.2
----------	-----------	---	---------	----------	-----	--