







Aircraft Record General Information							
Manufacturer PIPER Serial 28 - 2996	Model PA28~ 180 Registration Number N89735						
Date of Manufacture		The state of the s		الله .			
Engine(s) currently installed: Manufacturer LYCOMING	Model Of 3/d	7- 43 a	Sorial 1 - 911	-364			
Manufacturer							
Propeller(s) currently installed:							
Manufacturer	Mode	el	•				
HUB Model	Serial		Serial				
Blade Model	Serial	Serial	Serial _				
Blade Model	Serial	Serial	Serial				

YEAR 20 DATE	TOTAL TIME IN SERVICE	Hangar 18 Aviation LTD N8973J Piper PA-28-180 SN 28-2996 Tach 5386.22 ACTT: 5386.22 Accomplished annual inspection IAW Part 43 Appendix D RE Piper PA-28-180 inspection checklist. ELT RE 91,207 Complied with AD 76-07-12. Removed and replaced main tires and RH tire tube. Serviced brake reservoir. Resecured interior door handle closeout. 91.413 check is due. Aircraft was found to be in airworthy condition. James 1 Protex 2665709 A&P/IA 19 July 2020	YEA 20 _ DAT	SEVAN AVIATION, INC. 1880 S AIRPORT ROAD WICHITA, KS 67209 CRS KG2R951K LOG ID# 9917 20-July-2020 WO# 72434/2 N8973J S/N 28-2996 PIPER PA-28-180 TACH 5386.8 Pg 1/1 COMPLIED WITH A VFR CERTIFICATION IN ACCORDANCE WITH FAR 91.413 AND PART 43 APPENDIX F. THE AIRCRAFT OR COMPONENT ID NITIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION AND IS AIRWORTHY, RELATED TO THE WORK PERFORMED. KG2R951K MICHAEL GROS, INSPECTOR Date

REC	UIREMEN	TS OF F	AR 23.1325,	FAR 91.217, FAR 91.	411, and FAR								
91.4			plished as fol				is is				YEAR	RECORDING	TODA
(a)				ture NARCO			appliance curren n and is	O at	for	1054	20	TACH	FLIGH
				erial Number <u>1736</u>			appi n a	6 C		* SA	DATE		
				AW FAR 43 APPEND	OIX		or with atio	20	M2-	Form	-		
	F. Reinstal						ller, ce istra	at 1	216 le Ne 259	9			Sent
(b)				e UNITED			opel dan min	on file	XXX XXX 388			1	-
				Number <u>3H 743</u>	from		pre cor Adj	1 C	Z Cert				
				20,000	_ feet IAW		gine n ac on	te te	h prese			STRATION: N89	73J
				lled Altimeter.	~ ·		eng d ir iati	Da Da		(SS	MOD	EL: PA28-180	1
(c)	Performed	correspo	ndence chec	k to 20,000 F	for		raft Scte	inspection Dat	Zi bori	Addre		REPLACE	, D ALL O.
				Model A			airc nspe eral vice	in c		3		SERVICED	
(d)			2919	IAW FAR 43 AP O AS PER FAR 23.132			me, ns in Fed	of th	une)	_		• ALL WOR	
(u) (e)				Fransponder(s) and Alt			wz wz be	rder	A STATE OF				
(0)				AC 43.13-1B Chapte			, ai ove of t	deta Ord	Station O			John Gea	arhart
	Sec. 1, 2 &		Reference it	710 43.13-1B Chapte			raft ab ns c for 1	der G	Static (Repair	l., , ,		1	1
	,				Form # SAI050		airc ified atio	ortin D di	A 19			A.C.	$/\sim$
							The airc identified regulation	Pe statio	Signe		(/ (
 						-	i i i i	rs Z	S			A&P3138	8384
												Í.	
 				L									

Sentinel Aviation, LLC.	KMXA	MANILA, AR

Entries must be endorsed with Name, Rating and Certificate Number of Technician or

Description of Inspections, Tests, Repairs and Alterations

Repair Facility. (See back pages for other specific entries.)

REGISTRATION: N8973J	TACH: 5451	HOBBS: 2449.7	DATE: 12-01-2020

- PLACED ALL O-RINGS AND SEALS IN NOSE STRUT. RVICED STRUT WITH MIL-H-5606 AND NITROGEN

TODAY'S TOTAL

FLIGHT TIME IN

SERVICE

L WORK PERFORMED IAW PIPER PA28-180 SERVICE MANUAL NO LEAKS NOTED.

kP3138384

YEAR 20	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE		ns, Tests, Repairs and Alterations Name, Rating and Certificate Number of Technician or	YEAR 20
Tango	Charlie	Aviati	on LLC		1 t	DATE
3093 Mit Airframe Piper PA Tach: 54' On this 54' due Sep 2 wheel bea travel. Re: Removed cracked d Removed defects no AD2020-2	chell Drive M September : 28-180 78.18 te completed a 023. Serviced b arings. Found th moved tore ste and replaced c oubler with nev carpet and inst oted, due again	alden Mo 27, 2021 In Annual ir rake resen irottle cable ering rod b entral vacu v p/n 6237: alled new c @ tach tim	nspection, Che roir and lubrica e loose, secure oots and repla um filter with it 3-001. Reinstal tarpet kit from	eck ELT IAW FAR91.207(d), replaced cated IAW Piper PA28 lube chart. Refed throttle cable in instrument paneaced with new p/n 453-158 boots. Refed alleron with existing hardware. In SCS Interiors p.o# W13818 job nuromplied with AD2013-02-13 stabilate	N8973J S/N 28-2996 Total Time: 5478.18 I ELT battery pack p/n BP1010, next battery replacement placed bracket air filter BA-3. Jacked aircraft and packed all el. Cleaned, lubricated and adjusted cabin heat valve cable Replaced misc 1 inch scat duct under instrument panel. er filter p/n Arb3-5-1. Removed left aileron and replaced . Replaced duct to carburetor with new p/n 565-466 duct. mber 46704-01. Complied AD69-22-02 R2 control yokes, no or cable, next due 6478.18 or Sep 2028 and complied with 28 no other new AD's due at this time, see AD compliance	Tar 3093 Airfra Piper Tach: On thi

Ferance Gromer AP3690972

I certify this aircraft had been inspected in accordance with an Annual inspection and was determined to be in a reworth condition.

Tango Charlie Aviation LLC 3093 Mitchell Drive Malden Mo 63863 (573) 281-2227 Airframe November 10, 2021 Piper PA28-180 Tach: 5490.52 On this date removed JPI 900 unit for repair by JPI Instruments. Reinstalled EDM-900 serial# 4224 after software upgrade. Test ran aircraft with no defects noted at this time. N8973J 04-05-22 Tach 5542.3 Airframe Log

Description of Inspections, Tests, Repairs and Alterations

Repair Facility. (See back pages for other specific entries.)

Installed new nose tire Goodyear Flight Special II600-6 6ply and new Michelin tube.

Secured cabin door armrest. Robert Denny Alexander A& 2125366

Entries must be endorsed with Name, Rating and Certificate Number of Technician or

N89731

S/N 28-2996

Total Time: 5490.52

RECORDING TODAY'S TOTAL

FLIGHT

TIME IN

SERVICE

TACH

TIME

PEAR TIME N8973J 08-08-22 Tach 5551.6 Installed new alternator belt p/n MC73965-015. Installed new L/H Forward upper cowl	YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
Teflon bushing p/n 05-07443. Installed new L/H wing strut plug p/n 04-04120. Robert Denny Alexander A&P2125366 10-21-2022 Tach 5551.6 TT 5551.6 N8973J PA-28-180 S/N 28-2996 Checked ELT IAW FAR 92.207. Installed new brake linings both brakes. Installed new inboard and outboard brake plates on L/H gear caliper. Installed new o rings in both brake calipers. Installed new outboard bearing and race on R/H wheel. Tightened all torque main gear link bolts. Cleaned fuel screen. Lubed airframe. Installed new BA-103 engine air filter. C/W AD 69-22-02 R2 control yokes. Due each 100 hours. C/W standby vacuum AD 99-24-10 para (b)(1)(2). Due each 12 and 24 months. All work accomplished IAW Piper PA-20-180 Service Manual. I certify that this Airframe has been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition. Robert Denny Alexander A&P2125366		+ ACCORI	9-21-2022 FY THAT DANCE W	? TAIS AIRC VITH AN A	CLOG ENTRY ACH READING 5551.6 TOTAL TIME 5551.6 CRAFT HAS BEEN INSPECTED IN NNUAL INSPECTION AND HAS BEEN RWORTHY CONDITION. DONALD MCDANIEL A&P, 2163416 IA