

Date 06/05/2023 Make Model Piper PA-18A

Tail # N8481D Serial # 18-6194

Airworthiness Directive Compliance Report

Airframe Hours:

Misc:

Engine: Lycoming O-360-C2A

S/N: L-8234-36A

Hours: 364.1

AD#	Category	Subject	Amend #	Eff Date	Rec	Remarks
<small>Date/Hours Compliance</small>	<small>Next Due</small>	<small>Name</small>	<small>Signature</small>	<small>Cert#</small>		
Airframe: Piper PA-18A						
53-04-01	Airframe	Control Stick Attachment		04/01/53		P/C/W Visual
		Armando Delacruz		3623160		
59-10-08	Airframe	Gas Tank Cap Vent		07/15/59		P/C/W Visual
		Armando Delacruz		3623160		
60-10-08	Airframe	Fuel Selector Valve	149	07/15/60	Yes	P/C/W
3-01-03		Armando Delacruz		3623160		
62-02-05	Airframe	Rudder Cable Attachment Lug	386	01/23/62		P/C/W at rebuild
		Armando Delacruz		3623160		
68-05-01	Airframe	Exhaust Mufflers	39-726	03/31/68	Yes*	Complied with by Inspection
6/5/2023	Tach 364.1	Armando Delacruz		3623160		
72-01-07	Airframe	Failure of Engine Mount	39-1434	04/17/72		Not Applicable
		Armando Delacruz		3623160		
78-10-03	Airframe	Fuel Venting Modification	39-3212	05/23/78		Previously Complied, cub crafter system
		Armando Delacruz		3623160		
85-06-04	Airframe	Fuel Tank Drain Valves	39-5021	05/04/85		P/C/W
		Armando Delacruz		3623160		
15-08-04	Airframe	Wing Lift Strut Forks	39-18140	06/03/15	Yes	P/C/W sealed struts installed
3-01-03		Armando Delacruz		3623160		

Engine: Lycoming O-360-C2A

59-10-07	Engine	Cylinder Baffle Clamps		07/01/59		New Installed at OH
2/27/03	Tach 0	Armando Delacruz		3623160		
64-16-05	Engine	Oil Seal Failure in AC Fuel Pumps	765	07/10/64		Pump not installed
		Armando Delacruz		3623160		
66-20-04	Engine	Oil Filter Adapter Gasket	39-277	08/27/66		replaced with new at OH
2/27/03	Tach 0	Armando Delacruz		3623160		
73-23-01	Engine	Piston Pin Cracks From Grinding	39-2804	01/13/77		N/A by Serial No.
		Armando Delacruz		3623160		
75-08-09	Engine	Oil Pump Drive Shaft and Impeller	39-3013	08/18/77		replaced with new at OH
2/27/03	Tach 0	Armando Delacruz		3623160		
87-10-06 R1	Engine	Rocker Arm Assembly	39-6293	09/01/89		p/c/w with at OH
2/27/03	Tach 0	Armando Delacruz		3623160		
90-04-06 R1	Engine	Propeller Governor External Oil Line	39-6915	05/28/91		Not Applicable
		Darin Hart		3488815		
92-12-05	Engine	Piston Pin Failure	39-8265	07/10/92		p/c/w with at OH
2/27/03	Tach 0	Armando Delacruz		3623160		
93-11-11	Engine	Diaphragm Fuel Pumps Overhauled (by AAI) - Remove Affected Pump and Replace	39-8584	06/21/93		Not Applicable
		Darin Hart		3488815		
95-07-01	Engine	Superior Air Parts Connecting Rod Bolts	39-9183	04/12/95		p/c/w with at OH
2/27/03	Tach 0	Armando Delacruz		3623160		
96-09-10	Engine	Oil Pump Impeller Failure	39-9586	07/15/96		p/c/w with at OH
2/27/03	Tach 0	Armando Delacruz		3623160		
97-15-11	Engine	Piston Pin Failure	39-10085	08/12/97		p/c/w with at OH
2/27/03	Tach 0	Armando Delacruz		3623160		
98-02-08	Engine	Crankshaft Corrosion Pits	39-10291	03/30/98	Yes	New crankshaft at OH
2/27/03	Tach 0	Armando Delacruz		3623160		
98-17-11	Engine	Crankshafts Installed by Nelson Balancing Service	39-10713	10/19/98		Not Applicable
		Darin Hart		3488815		
04-10-14	Engine	Crankshaft Gear Retaining Bolt	39-13644	06/25/04	Yes	Not Applicable
		Darin Hart		3488815		
06-10-21	Engine	ECI Connecting Rods	39-14604	06/22/06		Not Applicable
		Darin Hart		3488815		
06-12-07	Engine	ECI Cylinder Assemblies	39-14632	07/11/06		Not Applicable
		Darin Hart		3488815		
07-04-19 R1	Engine	Superior Air Parts Cylinder Assemblies	39-15005	05/07/07		Not Applicable
		Darin Hart		3488815		
09-26-12	Engine	ECI Cracked Cylinder Assemblies	39-16151	02/04/10	Yes	Not Applicable
		Darin Hart		3488815		
12-19-01	Engine	Crankshaft Replacement	39-17196	10/24/12		Not Applicable
		Darin Hart		3488815		
17-15-11	Engine	Connecting Rod Failure	39-18988	08/15/17		Not Applicable
		Darin Hart		3488815		

20-25-12 Engine
5-19-2021 Tech 335.9

Crankshaft Assembly Failures
Dale Faulkner

39-23154

01/15/21
1993252

p/cw