TACOMING A Textron Company

652 Oliver Street Williamsport, PA 17701 U.S.A

570/323-6181

AND MAINTENANCE RECORD **ENGINE LOG**

RECORD OF LYCOMING

0-360-C1G L-41858-36E

SERIAL

MODEL

SSP-1872-1 DETAILING TIME FROM FROM JULY 15 20 11 HOURS October 1994 HOURS

© 1994 by Textron Lycoming "All Rights Reserved"

NEW RECIPROCATING ENGINE CERTIFICATE

Regulations. No further run-in is required. All Applicable Federal Aviation and tested as prescribed by LYCOMING specifications and Federal Aviation time of manufacture. This is to certify that the engine as described herinafter has been manufactured run-in Airworthiness Directives and Lycoming Service Bulletins have been complied with at SERIAL N

(AUTHORIZED REPRESENTATIVE) LYCOMING ENGINES

Williamsport, PA 17701 U.S.A

Lycoming Engines is a division of Aveo Corporation. Aveo Corporation is a wholly owned subsidiary of Textron Inc. ©2010 Avco Corporation All Rights Reserved.

652 Oliver Street

Propeller MTV-15-B/203-58

Hub Serial No. [102]3

Form No. 777-C (Rev. 6/10)

NOITE DESCRIPTION

LIAGIN	FINGING DESCRIPTION	
lfgr. LYCOMING	Place Williamsport, PA 17701	1 Date 7 _ / 5 ~ 20 / /
ype	Model () - 3/0() - (1 (-	Serial No. 41858-21
ated H.P. 180		Weight (Dry) 297LBS
ated R.P.M. 2700	Max. R.P.M. 2700	Oil Pressure 900CT
ore 5,125		Displacement 3(al. ()Cu. In.
ompression Ratio S. S. 1	ō	
eduction Gear Ratio		

Blade Design 203-58	Blade Serial No. ACA - 41780	Blade Serial No.A
Max. Hub H.P.	Max. Blade H.P.	
Pitch	Diameter	Length
Name		
Address		

ENGINE LOG

Serial No. 1-41858 - 3105

Signature

License

This engine s/n: L-41858-36E, model O-360-C1G was installed on this affectaft, s/n: 543-2611, model 8GCBC this date

Hrs Min

Tach Time: 0.6

REPAIRS - ADJUSTMENTS - SERVICE - REMARKS

for AMERICAN CHAMPION AIRCRAFT

Page Total Total to Date Brought Forward

> Certificate Number MUST be Shown Certificated Mechanic, and his Rating and All Repair Data Must Bear the Endorsement of a

> > A.H.Theobald, C.I

CRS F35R977Y

in airworthy condition. Reference Fox River Aviation Enterprises Inc. CRS F35R977Y been inspected in accordance with a 100 hour inspection and has been determined to be

work order #002587.

engine, exhaust system and control rigging. Checked Ads, AD 2004-10-14 C Cranks gear

bolt due upon prop strike. AD 2012-03-07 Mixture control sleeve billet carb. NA by part

with 8 qt. Aeroshell 50 weight mineral oil. Cleaned and gapped spark plugs. Inspected

performed #1-78, #2-79, #3-78, #4-78. Replaced air filter BA8103. Checked mag timing Changed oil and filter CH48109-1. Inspected old filter no metal found. Serviced engine

number. Run-up performed satisfactory and no leaks found. I certify that this engine has

Date: 7/15/2011

100 Hour inspection completed this date in accordance with SM-701. Compression test

4-3-12 Tach Time: 17.9 N380K

DOG	
Serial No.	

	ST be Shown.	Certificate Number MUST be Shown.	vard	Brought Forward	
	All Repair Data Must Bear the Endorsement of a	All Repair Data Must Be		Page Total	
)ER 12-2632	SHOP ORDER 12-2632	A&P 2797711 10/30/2012	MATHEW MCKENY, A&	
	MANUALS.	4 & LYCOMING SERVICE	MAINTENANCE COMPLETED IN ACCORDANCE WITH ACA & LYCOMING SERVICE MANUALS	MAINTENANCE COMPLETED IN ACC	
	4SKET, AN900-16.	STALLED WITH NEW GA	COMPRESSION CHECK 1,7480 2,7680 3,7680 47,7400 COMPRESSION CHECK 1,7480 2,7680 3,7680 17,7400 NEW FILTER, CHAB109+, INSTALLED, SUMP SCREEN INSTALLED WITH NEW GASKET, AN900-16 SERVICED WITH 7,0TS PHILLIPS XC20/50W	COMPRESSION CHECK 1-74/80 2-76/80 3-76 NEW FILTER, CH49109-1, INSTALLED. SUMF SERVICED WITH 7 QTS PHILLIPS XC20/50W	
		TACH: 47.7 E ETT: 47.7 MP SCREEN.	N380K MODEL: 86CBC SN: 543-2011 TACH: LYCOMING MODEL: 0-360-C16 SN: L41888-36E ETT: DRAINED OIL, REMOVED & INSPECTED OIL FILTER & SUMP SCREEN	N380K MODEL LYCOMING MODEL DRAINED OIL, REMOVI	
Licen Numt	Constitution of the consti		CHANDLER AIR SERVICE 1675 E RYAN RD CHANDLER AZ 8528 ENGINE LOG ENTRY		Date

Lotal to Date

ENGINE

Time

1 SAN FORWARD FORWARD SAN FORMAND FOR AND	Date	Hrs Min	ERVICE - R
Tagatal	12-13	63 0	complied with As ANNUAL
to and the state of the state o			
to de so			COMPRISSION #1 7/20 #2 7/20 #3
Long de Fa			#4 12/so, Inspected and Replied
Apply Type to d			when
App / Lagrand			Inspected mother to defects noted
App /x.			complied with AD Riving the B
Institud			2013-06 NONE APP/ I CILIK
1 to be 4			_
			1/

Page Total Brought Forward Total to Date		Re Cheebood a	French Car Report	Cambrand, Cheeked lovel	filter to 15 fx 4	03-13 96.7 Drawned and mental. Longued	Date Hrs Min REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	ENG
All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.	dad Swan	Re church air love, OK at	From well CH48109-1	head level.	Dilling X-C 20w-50, added 1209	mores frequed	SERVICE - REMARKS Signature License Number	ENGINE LOG Serial No.
rage Total Brought Forward Brought Forward Total to Date All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.	John Miller Aviation, Inc. Merrill, Wisconsin 715-536-2024	Signed John Miller A&P2218445AI	I certify that this Engine has been inspected IAW a 100 Hour Inspection and was determined to be in airworthy condition.	Compression test and the results were as follows: (1) 79/80 (2) 80/80 (3) 78/80 (4) 80/80. Completed run up and found engine to operate to specs and be free of leaks.	C/W a 100 Hour Inspection of this Engine this date. Changed oil and filter. Cut filter and found OK at this time. Installed 7 quarts of 20W50 Phillips and 11 oz. of Cam Guard. Completed a	Date: 5/18/2014 Tach: 121.5 A/C T.T. 121.5 Eng. TSN: 121.5 Prop TSN: 121.1	Date Date Date Engine Log Entry N380K	

C 351 51-10		6-1-15	Date	
582		68.2	Time Hrs Min	
Page Total Brought Forward Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.	I CERTIFY THAT THIS ENGLISE HAS EEDS INSPECTED IN ACCORDANCE WITH THE ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRMORTHY CONPITION, APZZSEGG IA	61-15 158,2 COMPRESSION CHECKED #1 18 #2 160 #3 160 #4 460	REPAIRS - ADJUSTMENTS - SERVICE - REMARKS Signature	ENGINE LOG Serial No.
a Juny			License Number	
		6.8.4	Date	
	7) CE	180.3	Time Hrs Min	
Page Total Brought Forward Cotal to Date A CC CC COTA COTA COTA COTA COTA COTA	AND GAPPED PLUGS OLIK, CHECKED ALL CERTIEF THAT THIS INSPECTED IN ACCORDANCE INSPECTED IN AC	COMPROSSIDULHECK	REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	ENGINE LOG
All Repair Data Pertificated Me Pertificate Num		1 4 0	ARKS	G
MASSES H All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.	WE LIB	#2 1%		Serial No.

License

ENGINE LOG

REPAIRS - ADJUSTMENTS - SERVICE - REMARKS

Serial No.

Signature

101116 180

Date

Hrs Min Time

Certificated Mechanic, and his Rating and Certificate Number MUST be Shown. All Repair Data Must Bear the Endorsement of a

Page Total Brought Forward Total to Date

ENGINE LOG

			•								6		
H											74-17	Date	7
						WAS	//OA	1000			197,9	Hrs Min	Time
Total to Date	Brought Forward	Page Total				FOUND TO BE IN A	CCORDANCE WITH TO	SULLIAN LAD	PLUGS, CHECKED CON	CHECKER TITITOG (NO CHANGE	COMPRESSION CHERE	BEPAIRS ADJUSTMENLYS SHRVICE I	CHARLET DIO TIL
Certificate Number MUST be Shown.	Certificated Mechanic, and his Rating and	All Renair Data Must Bear the Endorsement of a	182258607/A	Tout Molenson	000	N ARMORTHY CONDITION	THE ANNUAL INSPECTION AND	S ANGINE HAS KEED INSPIRITED	CLASS. CHECKED CONTROLS, MIL APPLIANTE MY COMP WITH	CHANGE) CLOMED + CARROD	KOD # 1 160 #2 1/60 #3 1/60 #4 1/60	MARKSI Number	18 License

_	П	1	
2			
1)	
()	
c	n		
ALIGI IA			
Ž	-		

2018

Hrs Min

ime

REPAIRS - ADJUSTMENTS - SERVICE - REMARKS

Signature

Date

Hrs Min Time

CHANGED OIL AND FILTER ! CHANGE INDUSTION ATR FILTER HICIPS 20-8X CONDT

O TIMING, NO CHANGE FROM LAST

BE WAN AIRWRIAY CONDITIO CERTIFY THAT THIS BUGINE AS KEEN Brought Forward Page Total Total to Date JUNIECTIONS ALL APPLICABLE ADS CONPIN UM TO 8-23-18 WES, CHECKED ALL ONGINE, CONTROLS AND E WITH THE ROWURL INSPUTI Certificated Mechanic, and his Rating and All Repair Dafa Must Bear the Endorsement of a Certificate Number MUST be Shown. 180 CLEANED AND GAPPED J INSPECTED

ENGINE LOG

REPAIRS - ADJUSTMENTS - SERVICE - REMARKS

Serial No.

Signature

License

Total to Date	Brought Forward	Page Total	Gerald A. Kasuske	2	negligible, Installation of this FAA-PMA an STC or Form 337.	Installed Reiff Preheat System on engine	Date 05/11/2010 N380K Tach 2/1 2
Certificate Number MUST be Shown.	Certificated Mechanic, and his Rating and	All Repair Data Must Bear the Endorsement of a	Kasuske	M J- M sun A&P 1996565	instruction. Hot band cylinder neating system and notstrip our sump neater: were change negligible. Installation of this FAA-PMA parts is a minor attention and does not require an STC or Form 337.	Installed Reiff Preheat System on engine accordance to Reiff Preheat System installation	O Aircraft TT 241 2

Time REPAIRS - ADJUSTMENTS - SERVICE - REMARKS Signature Number	DR 5/05/2020 Lycoming 0-360_C1G S/N 41858-36E Tach 272.1 TTE 272.1 Inspected engine IAW FAR Appendix "D". LY-CON Rebuilding Co. Bored the cylinders 10 thousands, Had cylinders port and polished. Installed new pistons
3-2019 Lycoming 0-360-C1G S/N 41858-36E Tach 260.0 TTE 260.0 pected engine IAW FAR Appendix "D". Checked compression #1 78/80, #2 76/80, #2 76/80, #4 78/80. Checked timing 25 BTC. Cleaned and rotated plugs. Did not	cylinders 10 thousands, Had cylinders port and polished. Installed new pistons and rings. See LY-CON work order 56567 for work done on each cylinder. Checked compression #1 80/80, #2 79/80, #3 80/80, #4 78/80. Cleaned and gapped plugs. Cleaned oil and fuel screen. Did not changed oil at this time do
nge oil at this,do to owners request. I certify that this engine has been inspected in accordance with a 100 hr. inspection and was determined to be in	to owners request. I certify that this engine has been inspected in accordance with a 100 hr. inspection and was determined to be in airworthy condition.
airworthy condition. A. M. A&P 1996565	airworthy condution. A. M. A. P. 1996565
Total to Date Certificate Number MUST be Shown.	Page Total All Repair Data Must Bear the Endorsement of a Brought Forward Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.

ENGINE LOG

Serial No.

Signature

Hrs Min

REPAIRS - ADJUSTMENTS - SIRVICE - REMARKS

REPAIRS - ADJUSTMENTS - SERVICE - REMARKS

Date

Time

04/15/2021 Lycoming 0-360-C1G S/N 41858-36E Tach 644.2 TTE 644.2

Inspection and was determined to be in airworthy condition.

service per work performed

Brought Forward Page Total Total to Date

All Repair Data Must Bear the Endorsement of Certificate Number MUST be Shown. Certificated Mechanic, and his Rating and

keith W. Sellers A&P 450311664

4-19-23 N380K Hobbs 542.9 Tach Time: 757.6 Removed P/N 800075 S/N 10424555 Oil Cooler and replaced with P/N 20002. S/N B23-19196-17. Ground run leaked checked performed and no leaks noted at this time. Aircraft is approved to return to

Keith W. Sellers A/P 450311664 I/A Kat W. S. Mer

Appendix "D". Checked compression #1 79/80 #2 79/80 #3 77/80 #4 79/80. Cleaned and rotated spark 08/14/2022 Lycoming O-360-C1G S/N 41858-36E Tach: 728.5 TTE 728.5 Inspected engine I/A/W FAR 43 plug and set timing 25 BTC. I certify that this engine has been inspected in accordance with an annua

Set "E" gap on mags and set timing 25 BTC airworthy condition

Brought Forward Page Total Total to Date

> Certificate Number MUST be Shown All Repair Data Must Bear the Endorsement of Certificated Mechanic, and his Rating and

oil. Checked compression all cylinders 76/80 or better. Installed 8 new REM37BY spark plugs. Installed 4 new set of new rings P/N SL7401-SCP010. Added 8 qts. Phillips 20W-50 mineral Inspected engine IAW FAR 43 Appendix "D". Installed 4 new pistons P/N SL75089A P010 with a 100 hr. Inspection and was determined to be in I certify that this engine has been inspected in accordance Gerald A. Kastisk

ENGINE LOG

Serial No

Signature

License

	ENGINE LOG	Serial No.
Time		License
wo: WO_97		Engine - page 1 of 1
	Redline Aviation - P.O. Box 8108 - Amarillo, Texas 79114 - 806-206-6525	
N380K TACH: 763.3	LYCOMING, 0-360 SERIES, S/N: ENGINE SN TBD Se	September 26, 2023
Performed an An	Performed an Annual Inspection in accordance with 14 CFR43 Appendix D	
Reinstall e Checked c replaced g PHILLIPS 18MM, Ins Ads Check	 Reinstall engine cowling, remove and inspect gasculator, remove and inspect exhaust for leaks. Checked compression #1 80/80 #2 80/80 #3 80/80, Removed regapped plugs cleaned and replaced ackets. Replaced art filter. Drain oil and replace and inspect oil filter. Installed (8) PN PHILLIPS XC20W-50. PHILLIPS XC20W-50, Installed (8) PN 07-00877 - SPARK PLUG GASKET 18MM, Installed PN AA48108-2 - OIL FILTER, Installed P/N BA-8103-1 - BRACKETT AIR FILTER. Ads Checked with T DATA 2023-20. 	haust for leaks. I plugs cleaned and r., Installed (8) P/N R. PLUG GASKET KETT AIR FILTER.
With respect to the are on file with R	With respect to the work performed, this engine is approved for return to service. Details of work performed are on file with Redline Aviation under work order: WO_97.	s of work performed

							1	Date Hrs Min
Total to Date	Brought Forward	Page Total						REPAIRS - ADJUSTMENTS - SERVICE - REMARKS
All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.							REMARKS	
e shown.	his Rating and	he Endorsement of a						Signature