



9519 Airport Drive, Hanger 19
Visalia, CA 93277

Propeller

DATE: 6/5/17

MODEL: D3A34C401/90DFA-2

TACH: 226.5

REG: N44TU

S/N: P4014808-09

- 1 INSTALLATION OF NEW PROPELLER D3A34C401/90DFA-2, S/N: 160588 IN ACCORDANCE WITH P. PONK SUPPLEMENTAL TYPE CERTIFICATE NUMBER SA0344WI. SEE 337 DATED 6/5/17.
- 2 REMOVE AND REINSTALL PROPELLER GOVERNOR C290D3-J/T19, S/N: 781667 AFTER RESEAL BY WEST COAST GOVERNOR SERVICE UNDER WORK ORDER NUMBER 417.

Signature &
Certificate
Number

6161


RAPHAEL LOPEZ - A&P 2709706

S/N: 160588
with an Annual inspection


CHRISTIAN MUNOZ - A&P 3559458

Current Manufacturers Maintenance

PERTINENT DETAILS ON FILE: W.O. 44T060517

in accordance with approved data and regulations of the Federal Aviation Administration and is approved for return to service.



Pertinent details of the repair are on file at this repair station under **Work Order#: W3304719**

Signed:  JA3272314 for Seaplanes North
(Signature of Authorized Representative)

FAA Repair Station number 5FAR575C Seaplanes North
3830 Aircraft Drive Anchorage, AK 99502

PROPELLER ASSEMBLY LOG

PAGE NUMBER _____

Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
			 5407 Honey Dew Terrace Austin, TX 78749		
	Tach 485.7		N44TU	04/19/2024	
Performed annual inspection IAW Cessna maintenance manual. Checked hub for cracks. Checked blades. I certify that this propeller has been inspected IAW an annual inspection and found to be in airworthy condition at this time.					
 A&P/IA 3279628					
	259.2				

