
# AIRCRAFT TECHNICAL RECORD

Section 3. ENGINE LOG



# Section 3A: Engine Service and Maintenance Log

DATE	TIM	IE RUN	TIME SINCE OVERHAUL					NAME/ SIGNATURE	LICENCE:
1 1	нои	RS min	HOURS	min	S u b Total	TOTAL	DESCRIPTION OF WORK PERFORMAL (INSPECTION, REPAIRS, REPLACEMENT)	STORATORE	AMO/ACA
BROUGHT FORWARD		-	2	.9			REPLACEMENT)	agent flend	DA RO6
MAR 1 8 7014	_	_	2	.9			TIMES BROUGHT FORWARD AND TRANSCRIED FROM DAIA GMGH PRODUCTION TEST FLIGHT LOGS		
			-				FROM DAIA GMGH THE	2901A E. Spri	MX Aero Global LLC ing St. Long Beach, CA 90806

Engine

N143NG

Model: E4-A S/N: E4-A-00193 Date: 12 May 2015

Hobbs Time: 57.6 Total Time: 42.2 Work Order: S-15-00085

Performed annual inspection using Diamond DA40 AMM 05-20-20 Annual Inspection form as a guide to comply with the inspection requirements of FAR 43 Appendix D.

Complied with 100hr./ 12 month fuel system inspection in accordance with Austro Engine Doc. No. E4 08 04, Ch. 05-20-13. Complied with 100hr / 12 month fuel filter replacement by installing new filter P/N WF724-3 in accordance with Austro Engine Doc. No

Complied with 100hr / 12 month waste gate controller inspection in accordance with Austro Engine Doc. No. E4 08 04, Ch. 81-00-30. Complied with 100hr / 12 month engine cooling system inspection in accordance with Austro Engine Doc. No. E4 08 04, Ch. 05-20-18. Complied with 100hr / 12 month V ribbed belt inspection in accordance with Austro Engine Doc. No. E4 08 04, Ch. 05-20-08, Complied with 100hr / 12 month cylinder head drain inspection in accordance with Austro Engine Doc. No. E4 08 04, Ch. 05-20-12. Complied with 100hr / 12 month exhaust system inspection in accordance with Austro Engine Doc. No. E4.08.04, Ch. 05-20-16. Complied with 100hr / 12 month engine zonal inspection in accordance with Austro Engine Doc. No. E4 08 04, Ch. 05-20-20. Complied with 100hr / 12 month engine harness and sensors inspection in accordance with Austro Engine Doc. No. E4 08.04, Ch. 05-20-

Complied with 100hr / 12 month EECU readout in accordance with Austro Engine Doc. No. E4.08.04, Ch. 05-20-05. Readout data sent to Austro Engines and Diamond.

Complied with 100hr / 12 month engine oil change in accordance with Austro Engine Doc. No. E4.08.04, Ch. 05-20-09 Drained oil from engine crankcase and serviced engine with 6 liters of Aersoshell Diesel Ultra 5W30 engine oil

Complied with 100hr / 12 month gearbox filter inspection in accordance with Austro Engine Doc. No. E4.08 04, Ch. 85-10-30. Complied with 100hr / 12 month gearbox oil inspection in accordance with Austro Engine Doc. No. E4.08.04, Ch. 85-10-20. Serviced gearbox with Aeroshell Spirax 75W-80 oil.

Complied with 100hr / 12 month engine oil filter change by installing new filter from 100hr kit P/N E4A-52-000-KIT in accordance with Austro Engine Doc. No. E4.08.04, Ch. 79-00-70.

Complied with 100hr / 12 month oil separator breather line inspection, no defect noted. All work done in accordance with Austro Engine EMM 05-20-19

Accomplished all required operational and functional checks with satisfactory results. Ground performance run good, no leaks noted

I certify that this Engine has been inspected in accordance with an Annual inspection and is determined to be in an airworthy condition Pertinent details are on file under the above work order.

Engine

N143NG Model: E4-A S/N: E4-A-00193 Date: 6 Jun 2016



Olathe KS 66062 (913) 782-0530 FAA Repair Station #AMYR171C

Hobbs Time: 83,9 Tach Time: 62.3 Total Time: 62.3 Work Order: S-16-00157

Complied with an Annual Inspection using Diamond DA40NG AMM 05-28-00 and 05-28-50 Inspection forms as guides to comply with the inspection requirements of FAR 43 Appendix D.

Complied with 12month/100hr Austro AE300 cooling system inspection per Austro EMM 05-20-18

Complied with 12month/100hr Austro AE300 zonal inspection per Austro EMM 05-20-20.

Complied with 12month/100hr Austro AE300 exhaust system inspection per Austro EMM 05-20-16.

Complied with 12month/100hr Austro AE300 waste gate controller inspection per Austro EMM 81-00-30. Complied with 12month/100hr Austro AE300 cylinder head drain inspection per Austro EMM 05-20-12.

Complied with 12month/100hr Austro AE300 engine fuel system inspection per Austro EMM 05-20-13. Complied with 12month/100hr Austro AE300 engine fuel system inspection per Austro Emin up-20-13.

Complied with 12month/100hr Austro AE300 engine fuel filter replacement by installing new filter P/N WF724-3 per Austro Engine doc E4 08 04 cb 05-20-14.

Complied with 12month/100hr Austro AE300 V ribbed belt inspection per Austro EMM 05-20-08.

Complied with 12month/100hr Austro AE300 engine harness and sensor inspection per Austro EMM 05-20-03.

Complied with 12month/100hr Austro AE300 oil separator breather line inspection per Austro EMM 05-20-19

Complied with 12month/100hr Austro AE300 gearbox oil inspection per Austro EMM 85-10-30. Serviced with Aeroshell Spirax 70W80 per Austro EMM 85-10-20. Serviced with Aeroshell Spirax 70W80 per Austro EMM 85-10-20.

Complied with 12month/100hr Austro AE300 engine oil and oil filter change by draining oil and removing old filter. Examined oil filter, no unusual contamination found. Serviced engine with 6 liver of filter change by draining oil and removing old filter. Examined oil filter no unusual contamination found. Serviced engine with 6 liters of Aeroshell Ultra 5W30 and installing new filter P/N E4A-52-000-KIT per Austro EMM05-20-09 and 79-00-70

Complied with 12month/100hr Austro AE300 EECU readout and download per Austro EMM 05-20-05.

Accomplished all required operational and functional checks with satisfactory results. Ground performance run good, no leaks noted

I certify that this Engine has been inspected in accordance with an Annual inspection and is determined to be in an airworthy condition. Pertinent details are on file under the above work order.

Olathe KS 66062 (913) 782-0530 FAA Repair Station #AMYR171C Mesoplay



Date: 6/16/17 N143NG S/N: 40.N143 Engine: Austro E4 S/N: E4-A-00193 Total Time: 222.1 Hobbs: 288.3

MX Aero Global LLC 2901A E. Spring St. Long Beach, CA 90806 Main: 562.912.4263 Cell: 562.881.5345



rmed 100 Hour Inspection using DA40NG AMM as a guide

- Replaced gearbox oil filter with P/N E4A-70-000-806 IAW MME4-08-04 05-20-07. Acquired Regions on three with Fire care removed days introduced to
   Replaced engine oil with Shell Diesel Ultra IAW DA40NG AMM 12-10-00.
- Replaced gear oil with Shell Spirax ATF ZM IAW DA40NG AMM 12-10-00. Performed coolant system pressure test IAW DA40NG AMM 75-00-00. 6 Performed coolant system pressure test IAW DA4UNG AMM 75-00-00
  7 Performed injector cover zonal inspection IAW MM E4.08.04. Next due by 522.1
  8. Performed alternator inspection IAW MM E4.08.04. Next due by 522.1

- ADs current to biweekly revision 2017-12.
- 10. Performed ground run operational and leak check.

I certify this engine has been inspected IAW an Annual Inspection and was deteri AP3492477 IA David Seastead

Ben's Motorworks

DATE

1119 W. Commonwealth Ave Hanger D28 Fullerton Ca 92833 71 4-396-6090

MODEL Diamond DA40NG A/C S/N

1/17/2018 N#

A/C TT 35 Hobbs

336.4 442

MODEL Austro Engine E4 ENG S/N E4-A-00193 DESCRIPTION OF WORK

Drained engine oil, Replaced cartrige oil filter with PN A-640-180-01-09. Refiled with 7 qts of Aeroshell Deisel Ultra. Inspected oil filter no metal found. Washed engine, test ran. No leaks CERT # AP IA 2698724

SIGNED Benjamin M Kellogg



Date: 6/6/18 N143NG S/N: 40.N143 Engine: Austro E4 S/N: E4-A-00193 Total Time: 413.7 Hobbs: 544.6

MX Aero Global LLC 2901A E. Spring St. Long Beach, CA 90806 Main: 562.912.4263



Performed 100 Hour inspection using DA40NG AMM as a guide

- 2. Replaced oil filter with kit P/N E4A-52-000-KIT.
- Replaced engine oil with Shell Diesel Ultra IAW DA40NG AMM 12-10-00. Performed coolant system pressure test IAW DA40NG AMM 75-00-00.
- 5. ADs current to biweekly revision 2018-11.
- 6. Performed ground run operational and leak check

I certify this engine has been inspected IAW an Annual inspection and was determined to be in airworthy condition

David Seastead

AP3492477 IA

ENGINE MODEL: E4 ENGINE S/N: E4-A-00193 REG NO: N143NG WORK ORDER 3371



MX Aero Global LLC

2901 East Spring St. Long Beach, Ca 90806 Phone: 562-912-4263 DATE: 7/9/2019 A/C TSN: 591.5 ENG TT 591.5 **TSMOH** HOBBS: 786.

## Engine Entries

(Tach 591.5) Complied with 100Hr/Annual inspection using Diamond Aircraft DA40NG AMM chapter 5 and FAR part 43 Appendix D as checklist as a guide. Engine oil has been drained, old oil filter and using 100Hr life. guide Engine oil has been drained, old oil filter removed and inspected with no defects noted. Engine serviced with Shell Diesel ultra oil using 100Hr kit 2019-11. Performed injector cover inspection, no squawks found during inspection. Used Austro Engine serviced with Shell Diesel ultra oil using 100Hr kit 2019-11. Performed injector cover inspection, no squawks found during inspection. Used Austro Engine MM CH: 85-00-11, 85-00-12; as a guide for complete with AD 2018-07-16 for water and unique for the service of the service removal and installation. Complied with AD 2018-07-16 for wastegate controller p/n E4A-41-120-000 and spring clip p/n E4A-41-100-801 replacement next compliance of this AD is due to the part of the AD is due to the part of the AD is due to the per Paia-US with MSB-E4-022/5 Para. 2.1 as a guide.
next compliance of this AD is due at tach 841.5. Removed and Replaced Turbocharger w/BPA as a unit due to internal leak, P.N. E4A-00-410-000 and all corresponding hardware, using Austro Engine MM CH. 78-00-12 as a guide, post operational and leak check now good.

I certify that this Aircraft has been inspected in accordance with 100Hr/Annual inspection checklist and was determined to be in airworthy condition.

Work Order: 3371

Printed by EBis 3 (datcomedia.com)

# Section 3A: Engine Service and Maintenance Log

DATE	TIME RUN	TIME SINCE OVER		CY	CLES							T	
1 1	HOURS min	HOURS	_	S u b Total	TOTAL		DESCRIPTION OF WORK PERFORMENT (INSPECTION, REPAIRS, REPLACEMENT)				NAME/ SIGNATURE	LICENC AMEOR AMO/ACA	
BROUGHT -								The state of the s			0,0,	AMO/ACA	
ı's Motorworks	,	-	'	'	'	1							
	langer D28 Fullerton Ca 9	2833 714-396-609	0					ENGINE MODEL E4-A	Waterford Aviation, Inc.	And the second section of the section	DATE 05 February 2021	-	
	4/1/2019 <u>N#</u>	N14NG		A/C T	T 50	34.9		ENGINE S/N E4-A-0018	6548 Highland Rd		A/C TSN 699 5 ENG TT 699 5		
	A40NG A/C S/N			35				WORK ORDER 6381-02-2021	Suite 900 Waterford, MI 48327		TSMOH TACH 699 5		
	ine E4 ENG S/I	<u>V</u> E4-A-0019	3						Phone 248-724-2400				
SCRIPTION OF V								Engine Entries	corocating Engine Supercharger by Insta	illation of wastegate control rod fail-safe bridge and ne	w spring loaded circlip IAW		
•	eplaced cartrige of							Terminating Action section	on 2.1 of Austro Engine MSB-E4-022/5. N	o further action required.			
keroshell Deisel U SNED Benjamin M	Iltra. Inspected oil	filter no met	al four		_		aks.	a spragate year	1				
NED Benjamin M	Kellogg,			CERT	# AP IA 26	98724		DATE 05 February, 2	021 SIGNED		Work Order: 6381-02-2021		
		1	_	1	7	_		DATE COTTON	Luke A&P 3695185	Printed	by EBis 3 (datcomedia.com)		
-						•			// S. J.		in a regionary color through a retrief profess their control regions in a control profession of the color of		
ENGINE MOD	DEL: E4 E4-A-00193	1 m		obal LLC			DATE. 7/24/2019	ENGINE MODEL		Premier Aircraft Service, Inc.		DATE: 3/26/2	
REG NO N1 WORK ORDE	43NG (1899≥	2901 East Long Bea	ach. Ca	90806			ENG TT 593 4	ENGINE S/N. E4-A-00193 REG. NO. N143NG	Promise	3804 Falcon Way W		A/C TSN: 70	
	~	Phone: 5	62-912-	4263			HOBBS 791 4	WORK ORDER: 0291	Aircraft Service	Hangar 18S Fort Worth, TX 76106		HOBBS: 96	
Engine En									All Craft Service	Phone: 562,881,5345			
connector kit	P.N. E4A-95-R11-000	using AE300 MM	CH: 24-0	00-11 and 71-	50-902 as guides	Performed 300	w alternator P.N. E4A-91-400-000 and HR maintenance on Gearbox oil and filter by E4A-7C-000-806 using AE300 MM CH	Engine Entries Replaced charge tube clar	***				
85-10 as Ref	erence. Performed inject	tor cover inspecti	ion, no s	guawks found	during inspection	Used Austro F	E4A-76-000-806 using AE300 MM CH Engine MM CH 85-00-11, 85-00-12, as a Id 600 HR Inspection on Two Mass Flywhel,		ain connection o-rings and gaskets				
								Replaced alternator belt E-					
18-11-05-02-	-00013 using AE300 MN	CH. 73-00-40 at	s referen	ce Performed	ops check, HPP for	mp. Replaced inctions as it st	IM CH 85-10-60 as reference Porformed Lunt with Pn L 64A-30-000-000 S N hould no leaks present Performed 600 HR Lystem with 6 liters of Glysantin Protect yystem, no leaks present Performed ops						
Plus G48 P.N.	N. 10012425 using DA	40NG MM CH 12	-10 as a	reference. Pe	informed pressure t	est of cooling s	t system with 6 lifers of Glysantin Protect system, no leaks present. Performed ops 4. (Tach 593.4) Performed 600 HR	DATE: 3/28/2021	SIGNED:				
maintenance reference P	e of replacing the High P reformed ops check, HP	ressure Pump. Re	eplaced should r	unit with P.N.	E4A-30-000-000 S	N: 18-11-05-0	4 (lach 593.4) Performed 500 HR 22-00013 using AE300 MM CH 73-00-40 αs ———————————————————————————————————	DATE: 3/20/2021		Work Order: 029			
							11954		David Seastead, License: A	1-04924// IA	Printed by EBis	3 (datcomedia.com	
DATE 7/2	M/2010	CICNED	. 2	X		-							
DATE 112	4/2019	SIGNED	48F (21	8987			Work Order 3371	ENGINE MODEL	٨				
			1	1		1	Printed by EBis 3 (datcomedia.com).	ENGINE S/N: E4-A-00193 REG. NO: N143NG	OP.	Premier Aircraft Service, Inc. 3804 Falcon Way W		DATE: 6/4/2021 A/C TSN: 747.3	
	_	×~						WORK ORDER: 0295	Aircraft Service		ENG TT: 747.3 HOBBS: 1019.7		
		GENE	RAL	AVIALIO	ON co., INC.			Engine Entries					
								Performed 100 Hours Inc.	tion using DA40NG AMM as a guide				
	9/9/202	0: N143NG D	iamon	DA40 S/	N 40.N143 Ta	ch/Hobbs:6	559.2898.4	<ul> <li>Changed oil and filter. Servi</li> <li>Inspected gearbox magnetic</li> </ul>		a			
		ur inspectiom	77.11.0	37.3	O ZZEOZZ								
		ce oil filter wi	ith p/n	kit E4A-52	-00-KIT.			DATE 6/4/2021	**	determined to be in airworthy condition.			
		ced fuel filter						UNITE 0/4/2021	SIGNED:		Work Order: 0295		
		ced oil with 7 018-07-16 du			tra 5W30 oil.				David Seastead, License: AP:	3492477 IA	Printed by EBis 3 (	(datcomedia.com)	
					iced inaccordanc	e with the Di	amond DA 40 NG	ENGINE MODEL					
	maint	enance manual	100 ho	ur inspectio	n checklist and h			ENGINE MODEL ENGINE S.N. E4-A-00193 REG. NO: N143NG WORK ORDER: 0398	$\overrightarrow{OD}$ .	Premier Aircraft Service, Inc.		DATE: 8/17/2021 A/C TSN: 843.8	
	airwo	orthy condition	at this t	ime.				WORK ORDER: 0396	Tremier	3804 Falcon Way W Hengar 18S Fort Worth, TX 76106		ENG TT: 843.8 HOBBS: 1151.1	
								Engine Entries	Aircraft Service	Phone: 562.881,5345			
Larry Vidal A&P# 2713446 IA								Engine Entries  Performed 100 Hour inspection using DA40NG AMM as a guide Changed oil and filter. Serviced engine with Aproximation and the Committee of the Co					
	(714) 526-6611							<ul> <li>Changed oil and filter. See</li> <li>Inspected gearbox magne</li> </ul>	ection using DA40NG AMM as a guide viced engine with Aeroshell Diesel UI tic chin collector	e tra			
												_	
								DATE: 8/17/2021	specied IAW an Annual Inspection and was	s determined to be in airworthy condition.			
THIS PAC	GE	+	-	+-		+		W1112021	SIGNED		1	Work Order: 0396	
TOTALS		+				4			Ched Cox, License: AP378	2800 IA	Printed by EBis 3 (	(datcomedia.com)	
PREVIOU	S												
TOTAL	LS												
SINCE	NEW					CARRY	FORWARD to Top of Next Page					l	

DATE	TIME RU	N.	TIME SINCE OVERH	AUL	CYCLES		
1 1	HOURS	min	HOURS	min	Sub Total	TOTAL	
BROUGHT _		<b>—</b>					

DESCRIPTION OF WORK PERFORME (INSPECTION, REPAIRS, REPLACEMENT)

ENGINE MODEL: AE300 ENGINE S/N: E4-A-00193 REG. NO: N143NG WORK ORDER: 0409



Premier Aircraft Service, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345 DATE SSZZI AC TSN 8023 ENG TT 8023 HOBBS 12167

### **Engine Entries**

- · Performed 300hr injector cover zonal inspection
- · Performed 300hr alternator inspection
- · Replaced gear oil and filter
- · Replaced fuel injectors · Replaced air filter

DATE: 9/9/2021

SIGNED: Chad Cox. License: AP3782800 IA

Work Order (409

Printed by EBis 3 (datoomeda.com)

Make: Diamond

Diamond. Model: DA40 NG FLEET & AVIATION SERVICES

Diamond Fleet & Aviation Services LCC

5070 S. Collins suite 205, Arlington, TX 76018 Phone: 817-575-7828

Date: 10/07/2021 Hobbs: 1,286.4 --A/C TSN: 942.1 ENG TT: 942.1

Engine entry:

S/N: 40.N143

REG NO: N143ng

- Performed 100 hour inspection using DA40ng AMM as a guide
- Change oil (Aeroshell Diesel Ultra) and oil filter
- Performed ground run operation and leak check

I certify this engine has been inspected IAW a 100 hour inspection and was determined to be in a airworthy condition.

Date: 10/07/2021

SIGNED: austin Paden AP: 4494928

ENGINE MODEL: AE300 ENGINE S/N: E4-A-00193 REG. NO. N143NG WORK ORDER: 0502



Premier Aircraft Service, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345

**Engine Entries** 

- . Performed 100 Hour Inspection using DA40NG AMM as a guide
- Changed oil and filter. Serviced engine with Aeroshell Diesel Ultra
- Inspected gearbox magnetic chip collector
- Replaced induction hose
- Performed 1000Hr timing chain inspection

I certify this engine has been inspected in accordance with \$100 Hour Inspection and was determined to be in airworthy condition

DATE: 12/23/2021

ead, License: AP3492477 (A

Printed by EBis 3 (datcom

SINCE NEW

CARRY FORWARD to Top of Next Page

wo: N143NG 2022.06.22 Scheduled



Diamond Fleet & Aviation Services - 5070 S. Collins S. Suite 205 - Arlington, TX 76018 - 9012474808

N143NG HOBBS: 1547.6 Austro Engine, E4-A, S/N: E4-A-00193 TTSN: 1133.6

July 14, 2022

SMOH: 1133.6

1 100 Hour Inspection - Completed ICW Annual Inspection. Next due @ 1231.4 TACH.

2. Annual Inspection - Inspections Completed IAW DA40NG AMM, AE300 EMM & FAR 43 Appendix D. Drained and serviced engine with 7 quarts Aeroshell Diesel Ultra. Removed, inspected, and replaced engine oil filter. Drained and serviced gearbox with 3 quarts Shell Spirax 75w80. removed and replaced transmission oil filter. ADs complied with through current bi-week. Next due July 2023.

3. Turbocharger compressor wheel oil seal leaking into compressor vanes and charge air tubing - Removed turbocharger (p/n K16-904-6 s/n UB50298702-00071) and installed new-serviceable turbocharger (p/n same s/n 50051565-

00030) IAW AE300 EMM current revision. Leak/Ops check ok.

With respect to the work performed, this engine has been found to be in an airworthy condition and is approved for return to service. Details of work performed are on file with Diamond Fleet & Aviation Services under work order: N143NG 2022.06.22 Scheduled.

Michael Smith A&P/IA 3906663

ENGINE MODEL. AE300 ENGINE S/N: E4-A-00193 REG. NO: N143NG WORK ORDER: 0712

remier Aircraft Service

Premier Aircraft Service, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345 A/C TSN: 1202.2 ENG TT: 1202.2 HOBBS: 1640.7

**Engine Entries** 

· Replaced oil and filter. Serviced with Aeroshell Diesel Ultra

Inspected gearbox chip collector
 Performed 300hr gearoil and filter change

Performed 300hr Injector Cover Zonal Inspection Performed 300hr Alternator Inspection

Replaced alternator brush pack E4A-91-410-000

Replaced HPP with new E4A-30-000-BHY S/N 22-02-15-02-00118

Replaced WGA spring clip

Changed coolant

Replaced flywheel with new E4B-73-000-000-KIT S/N 06408

· Replaced crank seal E4A-13-000-000

Replaced oil baffle panel E4A-51-000-401

Replaced gearbox input shaft seal E4A-70-000-825

DATE: 11/18/2022 SIGNED Chad Cox, License: AP3782800 IA

Work Order: 0712 Printed by EBis 3 (datcomedia.com)

ENGINE MODEL AE300 ENGINE S/N. E4-A-00193 REG. NO: N143NG WORK ORDER: 0736



Premier Aircraft Service, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881,5345 DATE: 1/4/2023 A/C TSN: 1228.4 ENG TT: 1228.4 HOBBS: 1676.5

Engine Entries

DATE: 1/4/2023

\* RSB-E4-028 Replaced fuel pressure sensor

SIGNED: David Seastead, License: AP3492477 IA

Work Order: 0736

Printed by EBis 3 (datcomedia.com)

### Premier Aircraft Service, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345

MAKE Diamond MODEL DA40NG Promier REG. NO: N143NG

3804 Falcon Way W Hangar 18S Fort Worth TX 76106

W/O #: 1563 DATE: 10-22-2025 ENG TT: 1461.5 Tach: 1461.5 Hobbs: 1990.2

Engine E	ntrie
----------	-------

WORK ORDER: 0789

· Replaced governor with overhauled P-853-16 S/N 20G754-K/G

DATE: 2/27/2023

SIGNED:

Chad Cox, License: AP3782800 IA

Printed by EBis 3 (datconeda con

DATE 5/2021

ACTS/ 1001

ENG 17 1307 1 HOBBS 1784 9

Inspected gearbox chip collector I certify this engine has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.

S/N: 40.N143

ENGINE MODEL: AE300

ENGINE S/N: E4-A-00193 **Engine Entries** 

ENGINE MODEL. AE300 ENGINE S/N E4-A-00193 REG NO N143NG WORK ORDER: 0836

remier Aircraft Service

Premier Aircraft Service, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345 DATE: 10-22-2025

SIGNED: \

David Seastead

Changed gearbox oil. Serviced with Shell Spirax S6 GXME

Performed 100 Hour Inspection using DA40NG AMM as a guide Changed oil and filter. Serviced engine with Aeroshell Diesel Ultra

WORK ORDER: 1563

Printed by EBIS (EBISCloud.com) License: AP3492477 IA

### **Engine Entries**

· Changed oil and filter. Serviced engine with Aeroshell Diesel Ultra

Inspected gearbox magnetic chip collector

DATE: 5/2/2023

SIGNED

David Seastead, License: AP3492477 IA

Work Order EE%

DATE 8/3/2023

AIC TSN 130

ENG TT 1307 HOEBS 150

Printed by EBis 3 (datcomedia.com)

ENGINE MODEL AE300 ENGINE S/N E4-A-00193 REG. NO: N143NG WORK ORDER: 0905



3804 Falcon Way W

Premier Aircraft Service, Inc.

Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345

### **Engine Entries**

Performed 100 Hour Inspection using DA40NG AMM as a guide

Changed oil and filter Serviced engine with Aeroshell Diesel Ultra
 Inspected gearbox magnetic chip collector

I certify this engine has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.

DATE: 8/3/2023

SIGNED:

David Seasteed, License: AP3492477 IA

Work Order (1985

Printed by EBis 3 (datcomedia.com)

ENGINE MODEL: AE300 ENGINE S/N: E4-A-00193 REG NO N143NG WORK ORDER: 1160



Premier Aircraft Service, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76109 Phone: 562 881.5345

### **Engine Entries**

- Performed 100 Hour Inspection using DA40NG AMM as a guide

. Changed oil and filter. Serviced engine with Aeroshell Diesel Ultra

Inspected gearbox magnetic chip collector

I certify this engine has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.

DATE: 9/17/2024



Printed by EBis 3 (datcomedia or

		David Seastead, License: AP3492477-IA									
	_							_			
								L			
THIS PAGE TOTALS											
PREVIOUS TOTALS											
TOTALS SINCE NEW											

CARRY FORWARD to Top of Next Page