

AD NOTES COMPLIANCE RECORD

AD#	Applicable S.B. # & Subject	Date & Hours @ Comp.	Method of Compliance	One Time	Recurring	Next Comp. @ Hrs/Date	Authorized Signature & Number
54-21-01	AC diaphragm type fuel pumps		N/A per MFG date	X			Boyd Roberts A&P 1980389
59-10-07	Cylinder baffle clamps		N/A, correct retainers installed	X			Boyd Roberts A&P 1980389
62-19-03	Propeller attach bolts		N/A per S/N	X			Boyd Roberts A&P 1980389
63-14-03	Oil pump drive shaft		N/A per S/N		X		Boyd Roberts A&P 1980389
63-22-03	Marvel Schebler carburetors		P/C/W "V" Stamped on data plate	X			Boyd Roberts A&P 1980389
64-06-06	Control wheels		N/A per S/N		X		Boyd Roberts A&P 1980389
64-16-05	Oil seal failure		N/A per fuel pump P/B	X			Boyd Roberts A&P 1980389
65-06-06	Fuel quantity gauge sender		P/C/W S/B 223, not due any longer		X		Boyd Roberts A&P 1980389
66-14-03	Crankshaft idler shaft		S/B 308 C/W at O/H	X			Boyd Roberts A&P 1980389
66-20-04	Oil filter adaptor gasket		N/A	X			Boyd Roberts A&P 1980389
67-12-06	Inspect tubes for corrosion		P/C/W	X			Boyd Roberts A&P 1980389
67-20-04	Main Landing gear torque link		P/C/W per S/B 248	X			Boyd Roberts A&P 1980389
67-26-02	Fuel selector valve		P/C/W S/B 253	X			Boyd Roberts A&P 1980389
67-26-03	Fuel system screens and filters		N/A per S/N		X		Boyd Roberts A&P 1980389
69-15-01	Control wheel pin		N/A per S/N	X			Boyd Roberts A&P 1980389
69-22-02 R2	Failure of control wheel	5211	C/W by inspect for cracks, none found		X	5311	Boyd Roberts A&P 1980389
69-24-03	Marvel Schebler carburetors		N/A per model	X			Boyd Roberts A&P 1980389
70-18-05	Landing gear torque link bolts		P/C/W S/B 248	X			Boyd Roberts A&P 1980389
70-26-04 R2	Stabilizer balance weight tube		P/C/W by install of P/N 69623-02, no longer due		X		Boyd Roberts A&P 1980389
71-14-06	Prevent grounding of magnetos		P/C/W	X			Boyd Roberts A&P 1980389
72-06-05 R2	Marvel Schebler carburetors		P/C/W	X			Boyd Roberts A&P 1980389
72-08-06	Main Landing gear torque links	5211	C/W by inspect torque links per S/L 600, Par C1		X	5711	Boyd Roberts A&P 1980389
72-14-07	Stabilator hinge fittings		P/C/W	X			Boyd Roberts A&P 1980389
72-15-02 R1	Prestolite alternator fans	5211	C/W by inspect, not applicable, Aerotech alternator		X	5311	Boyd Roberts A&P 1980389
72-17-05	Electric trim switch		N/A per S/N	X			Boyd Roberts A&P 1980389
73-23-01	Piston pin failures		P/C/W	X			Boyd Roberts A&P 1980389
73-23-01 R4	Piston pin failures		N/A per S/N	X			Boyd Roberts A&P 1980389
74-09-04	Rear seat belt installation		N/A per S/N	X			Boyd Roberts A&P 1980389
74-18-06	Fuel quantity placards		N/A per S/N	X			Boyd Roberts A&P 1980389

AD#	Applicable S.B. # & Subject	Date & Hours @ Comp.	Method of Compliance	One Time	Recurring	Next Comp. @ Hrs/Date	Authorized Signature & Number
74-19-01	Outer wing spars		N/A per S/N	X			Boyd Roberts A&P 1980389
75-02-03	Nose wheel fork assembly		N/A, not modified	X			Boyd Roberts A&P 1980389
75-08-09	Oil pump		P/C/W	X			Boyd Roberts A&P 1980389
75-08-09 R3	Oil pump		N/A per S/N	X			Boyd Roberts A&P 1980389
75-24-02	Loose seats		N/A per S/N		X		Boyd Roberts A&P 1980389
76-02-07	Prestolite alternators		N/A per model		X		Boyd Roberts A&P 1980389
76-07-12	Bendix switches	12-19	C/W by check for grounding		X	12-20	Boyd Roberts A&P 1980389
76-07-12 R1	Bendix switches	5211	C/W by inspect for grounding		X	5311	Boyd Roberts A&P 1980389
76-18-04	Fuel valve		N/A per S/N	X			Boyd Roberts A&P 1980389
77-01-01	Fuel quantity gage		N/A per S/N	X			Boyd Roberts A&P 1980389
77-12-01	Fuel system		N/A, previously modified to cancel A/D		X		Boyd Roberts A&P 1980389
77-23-03	Rod end bearings		N/A per S/N	X			Boyd Roberts A&P 1980389
78-23-01	Fuel drain assembly	5211	C/W by inspect cover assy.		X	5311	Boyd Roberts A&P 1980389
79-22-02	Fuel leakage		N/A per S/N	X			Boyd Roberts A&P 1980389
80-25-07 R1	Stewart Warner oil coolers		P/C/W at oil cooler O/H	X			Boyd Roberts A&P 1980389
81-18-04 R2	Oil pump		See A/D 96-09-10	X			Boyd Roberts A&P 1980389
86-17-01	Ammeter replacement		N/A per S/N	X			Boyd Roberts A&P 1980389
87-10-06 R1	Rocker arm assemblies		N/A per S/N	X			Boyd Roberts A&P 1980389
89-04-02	Facet carburetors		N/A per S/N	X			Boyd Roberts A&P 1980389
91-14-22	Crankshaft gear retaining bolt		See A/D 2004-10-14	X			Boyd Roberts A&P 1980389
92-12-05	Piston pin failure		N/A per O/H date	X			Boyd Roberts A&P 1980389
93-05-21	AC, Textron, Rajay fuel pumps		See A/D 93-11-11	X			Boyd Roberts A&P 1980389
93-11-11	AC, Textron, Rajay fuel pumps		N/A per S/N	X			Boyd Roberts A&P 1980389
93-18-03	Precision carburetors		See A/D 98-01-06	X			Boyd Roberts A&P 1980389
93-19-04	Precision carburetors		N/A per model	X			Boyd Roberts A&P 1980389
95-07-01	Connecting rod bolts		N/A per assembly date	X			Boyd Roberts A&P 1980389
95-26-13	Oil cooler hoses	6-18 tach:5180	Replaced hoses 6-18 with type "D" hoses, not due anymore		X		Boyd Roberts A&P 1980389
96-09-10	Oil Pumps		P/C/W	X			Boyd Roberts A&P 1980389
96-10-03	Flap handle		P/C/W	X			Boyd Roberts A&P 1980389
97-01-03	Piston pin		See A/D 97-15-11	X			Boyd Roberts A&P 1980389

AD#	Applicable S.B. # & Subject	Date & Hours @ Comp.	Method of Compliance	One Time	Recurring	Next Comp. @ Hrs/Date	Authorized Signature & Number
97-15-11	Piston pin		N/A per Model	X			Boyd Roberts A&P 1980389
98-01-06	Precision carburetors		N/A per model		X		Boyd Roberts A&P 1980389
99-04-04	Magneto impulse coupling		N/A		X		Boyd Roberts A&P 1980389
99-05-09	Damaged induction air filter		P/CW	X			Boyd Roberts A&P 1980389
PL2002-18-51	Prevent the reduction or loss of engine power or external fuel leaks		See A/D 2003-05-01	X			Boyd Roberts A&P 1980389
PL2002-20-51	Prevent loss of all engine power and possible forced landing		See A/D 2002-23-06	X			Boyd Roberts A&P 1980389
2002-23-06	CORRECTION - Prevent loss of all engine power and possible forced landing		See A/D 2004-05-24	X			Boyd Roberts A&P 1980389
2003-05-01	Prevent reduction or loss of engine power or external fuel leaks		N/A, not installed	X			Boyd Roberts A&P 1980389
2004-05-24	Prevent loss of all engine power and possible forced landing		Due at engine sudden stoppage or O/H	X			Boyd Roberts A&P 1980389
2004-10-14	CORRECTION - Prevent loosening or failure of the crankshaft gear retaining bolt		Due at engine sudden stoppage or O/H	X			Boyd Roberts A&P 1980389
2005-19-11	Prevent failure of the crankshaft		N/A per O/H date	X			Boyd Roberts A&P 1980389
2005-26-10	To prevent loss of engine power due to cracks in the cylinder assemblies		N/A, none installed	X			Boyd Roberts A&P 1980389
2006-10-21	CORRECTION - To prevent fatigue failure of the connecting rod and a possible uncommanded shutdown of the engine.		P/CW	X			Boyd Roberts A&P 1980389
2006-12-07	To prevent loss of engine power due to cracks in the cylinder assemblies		P/CW	X			Boyd Roberts A&P 1980389
2006-20-09	To prevent failure of the crankshaft		See A/D 2012-19-01	X			Boyd Roberts A&P 1980389
2008-19-05	To prevent loss of engine power due to cracks at the head-to-barrel interface in the cylinder assemblies and possible engine failure caused by separation of a cylinder head		See A/D 2009-26-12		X		Boyd Roberts A&P 1980389
2009-26-12	To prevent loss of engine power due to cracks at the head-to-barrel interface and possible engine failure caused by separation of a cylinder head		N/A, no cylinder replaced since O/H		X		Boyd Roberts A&P 1980389
2010-15-10	To detect and correct any incorrectly assembled control wheel shafts		P/CW	X			Boyd Roberts A&P 1980389
2012-03-07	To address a "machined-from-billet" HA-6 carburetor having a loose mixture control sleeve that rotated in the carburetor body		N/A	X			Boyd Roberts A&P 1980389
2012-19-01	To prevent failure of the crankshaft		N/A per O/H date		X		Boyd Roberts A&P 1980389
2013-02-13	To prevent failure of the horizontal stabilator control system and could result in loss of pitch control	12-19 tach:5211	CW by inspect per A/D		X	2026 tach 7211	Boyd Roberts A&P 1980389

AD#	Applicable S.B. # & Subject	Date & Hours @ Comp.	Method of Compliance	One Time	Recurring	Next Comp. @ Hrs/Date	Authorized Signature & Number
2017-14-04	Oil Cooler Hose Asembly TSO Requirements	5180	P/C/W, has type "D" hoses		X		Boyd Roberts A&P 1980389
2017-16-11	Engine Connecting Rod Assemblies Integrity		N/A	X			Boyd Roberts A&P 1980389
2018-02-05	Placard, Fuel Selector Cover Placards Improper Installation		C/W by inspect per A/D	X			Boyd Roberts A&P 1980389