

**N27682**  
**Aircraft Status Report**  
**10/27/2023**

**N27682 Owner: D and R Hobbs**

**Address: 202 W. Walnut St. Rogers, AR 72756**

	Make	Model	Serial	TIS	Hobbs	TSOH
<b>Airframe</b>	Piper	PA31-350	31-7852105	11087.6	3385.8	N/A
<b>Engine Right</b>	LYC	LTIO-540-J2BD	L-2610-68A	8685.6	3385.8	906.2/4-15-2015
<b>Engine Left</b>	LYC	TIO-540-J2BD	L-11253-61A	3628.2	3385.8	1632.0/11-3-2010
<b>Governor Right</b>	McCauley	DCFUS290D10/T8	S/N 060025	2367.4	3385.8	906.2/4-8-2015
<b>Governor Left</b>	McCauley	DCFUS290D10/T8	S/N 060030	2367.4	3385.8	906.2/4-8-2015
<b>Prop. Right</b>	Hartzell	HC-C4YR-2L/FJC7663DB-6Q	FH1095	2367.4	3385.8	906.2/4-8-2015
<b>Prop. Left</b>	Hartzell	HC-C4YR-2/FJC7663DB-6Q	FH1118	2367.4	3385.8	906.2/4-8-2015
<b>Mag. Left Dual</b>	TCM	10-682910-13	K081243	UKN	3385.8	266.4/2-9-2021
<b>Mag. Right Dual</b>	TCM	10-622910-18	C-02051	UKN	3385.8	266.4/2-9-2021
<b>500 HR Mag Insp.</b>	TCM	Left Right	K081243 C-02051		3385.8	266.4/2-9-2021 266.4/2-9-2021
<b>Aircraft Battery</b>	Concorde	RG24-20	41103150	266.4/2-9-2021	3369	266.4/2-9-2021
<b>L/G Selector Cable</b>	Life Limit	4000 Hours		2833.1	Replacement due at 11660.7 AFTT	
<b>Combustion Heater "Heater Hobbs"</b>	C&D	CD45K, P/N CD14048-1	1277	Overhauled at 512.5 HH	750.3	238.1/1-15-2015

	Date Accomplished	Total Total Time	Hobbs Time	Date Due	Total Total Time	Hobbs Time
<b>Annual/100 Hr. Insp.</b>	6/13/2023	11,070.80	3369	Jun. 2024	11,170.80	3469
<b>Oil Change/Filter Insp.</b>	6/13/2023	11,070.80	3369	6 Months	11,095.80	3394
<b>ELT Battery</b>	12/12/2019	10656.6	2954.8	Sept. 2025	N/A	N/A
<b>Static System</b>	4/4/2022			Apr. 2024	N/A	N/A
<b>Altimeter Cert.</b>	4/4/2022			Apr. 2024	N/A	N/A
<b>Transponder</b>	4/4/2022			Apr. 2024	N/A	N/A
<b>Encoder</b>	4/4/2022			Apr. 2024	N/A	N/A

Recurring A.D.s	Compliance Time Hobbs	Due Time Hobbs
<b>82-27-13 R2</b> Split Flap Condition	3369.0/6-13-2023	3469
<b>84-26-02</b> Paper Air Filter	3260.8/5-1-2022	3760.8
<b>98-08-18</b> Elevator Bungee Spring	3385.8/10-27-2023	4385.8
<b>98-09-25</b> Lower Spar Splice Plate	N/A	13,000 AFTT
<b>2003-24-07</b> Rudder Tube Corrosion	3369.0/6-13-2023	Jun. 2024
<b>2009-13-06 R1</b> Baggage Door Latch	3385.8/10/13/2023	3485.8/Life Limited Parts 3730.8
<b>2004-10-14C</b> Crankshaft Gear Bolt	Left 1753.8/11-3-2010 Right 2479.6/4-15-2015	Prop. Strike or Suddend Stop...
<b>2015-19-07</b> Fuel Injection Lines RT & LT	3369.0/6-13-2023	3469.0 or next nozzle MX
<b>2013-10-4C</b> Exhaust Inspection RT & LT	3369.0/6-13-2023	3429.0/Nov. 2023