_	05/13/2024 CCX-2300 S/N: CCX-2300-00 TTAF: 50.3 100 HOUR inspect blades, & spinner for hub with Nyco GN	TSNI ion complic or defects -	ming IO-390-I L-1894-80E EW: 50.3	ncing FAR 43	Tach: 50.3 Hartzell 3C1-R430A1W S/N: SM82 TSNEW: 50.3 App. D & Hartzell maintware & safeties inspected	enance manuals. Inspected hub, for proper installation. Lubricated	
_ _ _	Airworthiness Directives checked & complied with through Biweekly 2024-09 NO AD's APPLY TO THIS PROPELLER Engine run & ops checks satisfactory. With regards to the work performed above, I certify this propeller is found to be in an airworthy condition at this time & is returned to service.						
	Tyson Mauldin 350	7743'5 A&P	IA				
	39			· ·			Page 1