

MCCAULEY™




**PROPELLER
OPERATOR'S
MANUAL
&
LOG**



**MPC-10, MPC-11, MPC-12,
MPC-13, MPC-14, MPC-15,
CMM500-1**

PROPELLER ASSEMBLY LOG

PAGE NUMBER _____

| Date | Total Time | Time Since Overhaul | Aircraft Model & Registration Number | Maintenance Service History | Signature & Certificate Number |
|----------|---|---|--------------------------------------|---|---|
| 10/25/16 |  |  | D3A34C401-C S/N 160773 | THIS PROPELLER WAS MANUFACTURED NEW AT McCAULEY PROPELLER SYSTEMS. INSPECTED AND FOUND TO BE AIR-WORTHY ON THIS DATE. |  |



AIR PLAINS SERVICES

N5412N

WO: 032039

03/10/2017

CRS: MNYR085K

Prop Log Eng. Prop TT: 0.0, A/C TT: 2340.1

Installed McCauley 3 Blade propeller **D3A34C401/90DFA-8** in accordance with Air Plains Services STC **SA00727WI** into Cessna 182 N5412N, SN: 18267763.

Propeller Serial #: **160773**

This Propeller was inspected in accordance with current regulations of the FAA and is approved for return to service.

Signed  Inspector CRS# MNYR085K



AIR PLAINS SERVICES

N5412N

WO: 032040

03/10/2017

CRS: MNYR085K



Propeller Log TT: 0.0, A/C TT: 2340.1

I certify that this Propeller has been inspected IAW an ANNUAL inspection and was determined to be in airworthy condition.

*Signed  Certificate#: MNYR085K

*WO#: 032040 TT: 2340.1 Date: March 10, 2017

| Date | Total Time | Time Since Overhaul | Aircraft Model & Registration Number | Maintenance Service History | Signature & Certificate Number |
|------|------------|---------------------|--------------------------------------|-----------------------------|--------------------------------|
|------|------------|---------------------|--------------------------------------|-----------------------------|--------------------------------|

| | | | | | | |
|--|--|--|----------|----------|---|------------|
|  | Specialized Aero LLC. 2285 Airport Drive San Marcos, Texas 78666 Phone: 512-392-4534 Fax: 512-392-4514 Station No. 7SLR322B | | Reg. No. | N5412N | Tach Time | 17.2 |
| | | | Make | McCauley | Model | D3A34C401 |
| | | | Prop S/N | 160773 | Nationality | USA |
| | Prop Log | | | | | |
| | | | W.O No. | 173530 | | |
| Removed propeller to facilitate engine removal due to off-airport landing in field. No damage to this propeller noted. Reinstalled prop in original position in accordance with Cessna 182R Service Manual. Ops check good. | | | | | | |
| This task has been performed in accordance with current regulations of the FAA and aircraft has been approved for return to service for work the performed. Pertinent details of this action are on file at this repair station under Work Order No. 173530. | | | | |  | |
| | | | | | Rogers Hunter CSR 7SLR322B | 10/20/2017 |

| | | | | | |
|--|--|--|--|--|--|
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

Gafford Aero, Inc.

PROPELLER ASSEMBLY LOG

PAGE NUMBER

1833 Airport Dr., San Marcos, TX 78666
(512) 396-3323 gaffordaero@austin.rr.com

PROP Log

Date: 3/22/2018

Aircraft
N: 5412N

Tach: 39.0

TT: 39.0

Signature &
Certificate
Number

Inspected the prop hub and blades, the spinner and the bulkhead, no defects noted.
I certify this propeller has been inspected IAW an **annual** inspection and was determined to
be in airworthy condition.



Kenneth Medcalf
A&P 452760326 IA

Gafford Aero, Inc.

1833 Airport Dr., San Marcos, TX 78666
(512) 396-3323 gaffordaero@austin.rr.com

PROP Log

Date: 4/1/2019

N: 5412N

Tach: 86.2

TT: 86.

Inspected the prop hub and blades, the spinner and the bulkhead, no defects noted.
I certify this propeller has been inspected IAW an **annual** inspection and was determined to
be in airworthy condition.


Kenneth Medcalf A&P 452760326 IA

Gafford Aero, Inc.
1833 Airport Dr., San Marcos, TX 78666
(512) 396-3323 info@gaffordaero.com

PROP Log Date: 5/7/2020 N: 5412N Tach: 148.3 TT: 148.3

Inspected the prop hub and blades, the spinner and the bulkhead, no defects noted.
I certify this propeller has been inspected IAW an **annual** inspection and was determined to be in airworthy condition.

Kenneth Medcalf
Kenneth Medcalf A&P 452760326 IA

| | |
|--|--------------------------------------|
| | |
| | |
| | Signature & Certificate Number |
| | |
| | |
| | |

| | | | |
|--|--|--|--|
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

Gafford Aero, Inc.
1833 Airport Dr., San Marcos, TX 78666
(512) 396-3323 info@gaffordaero.com

PROP Log Date: 5/28/2021 N: 5412N Tach: 186.0 TT: 186.0

Inspected the prop hub and blades, the spinner and the bulkhead, no defects noted.
I certify this propeller has been inspected IAW an **annual** inspection and was determined to be in airworthy condition.

Kenneth Medcalf
Kenneth Medcalf A&P 452760326 IA

PROPELLER ASSEMBLY LOG

PAGE NUMBER _____

| Date | Total Time | Time Since Overhaul | Aircraft Model & Registration Number |
|------|------------|---------------------|--------------------------------------|
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

Gafford Aero, Inc.
1833 Airport Dr., San Marcos, TX 78666
(512) 396-3323 info@gaffordaero.com

PROP Log Date: 6/7/2022 N: 5412N Tach: 216.9 TT: 216.9

Inspected the prop hub and blades, the spinner and the bulkhead, no defects noted.
I certify this propeller has been inspected IAW an **annual** inspection and was determined to be in airworthy condition.

Kenneth Medcalf
Kenneth Medcalf A&P 452760326 IA

Gafford Aero, Inc.
1833 Airport Dr., San Marcos, TX 78666
(512) 396-3323 info@gaffordaero.com

PROP Log Date: 7/7/2023 N: 5412N Tach: 244.1 TT: 244.1

Inspected the prop hub and blades, the spinner and the bulkhead, no defects noted.
I certify this propeller has been inspected IAW an **annual** inspection and was determined to be in airworthy condition.

Kenneth Medcalf
Kenneth Medcalf A&P 452760326 IA