THIS SERVICE RECORD shall accompany the propeller equipment at all times. When equipment is installed as part of an Aircraft or engine, this record shall be maintained concurrently with and become a part of the Aircraft and Engine Service Records.

## PROPELLER MAINTENANCE RECORD

Position	PITCH RANGE
Propeller Model # C2 YR-IN/	NG8301-5 High/Feather
Propeller S/N	Start Lock
Blade Design	Low
Blade S/N's	Reverse
No. 1	
No. 2	Aircraft Manufacturer American Champton
No. 3	11 CA 20
No. 4	S/N 543-2011
No. 5	Registration
No. 6	

Date	ate Propeller TSN TSO		A/C Hrs			
5-13-19	0.0	0.0	260.0	Fostelled propeller on ACA, N380K 5/N543-2011		
				Fostolled propeller on ACA N380K 5/N543-2011		
100						
			6-13-2	I certify that this propeller has been inspected in accordance with a 100 hr. inspection and was determined to be in airworthy condition.  A&P 1996565		
				Gerald A. Kasuske		
				artzell HC-C2YR-IN/NG8301-3 Tach 272.1 TTP 12.1  ppeller IAW FAR Appendix "D".  I certify that this propeller has been inspected in accordance with a 100 hr. inspection and was determined to be in airworthy condition.  A&P1996565		
				Gerald A. Kasuske		
			7			
				Hartzell HC-C2YR-IN/NG8301-3 Tach 644.2 TTP 384.2 peller IAW FAR 43 Appendix "D".  I certify that this propeller has been inspected in accordance with a 100 hr. Inspection and was determined to be in airworthy condition.  Gerald A. Kasuske		
	Apper	ndix "D"	. I certify	c-C2YR-IN/NG8301-3 Tacn 728.5 TTP 468.5 Inspected propeller I/A/W FAR 43 that this propeller has been inspected in accordance with a annual Inspection and n airworthy condition.    Columbia		
	_	wo: WO_9	97	Propeller - page 1 of 1		
$\neg$	-			eso Fe		
	$ \vdash$			Redline Aviation - P.O. Box 8108 - Amarillo, Texas 79114 - 806-206-6525		
	Pe Ad	ds Check	an Annual	Inspection in accordance with 14 CFR43 Appendix D.  ATA 2023-20.  Fage  Page		