

**HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS**

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	Mech. Cert. # or Repair Station # _____
Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	Mech. Cert. # or Repair Station # _____

Propeller: Hartzell PHC-C3YF-1RF  
 Hub S/N: EE 4100B

AMR SERVICE  
 Propeller TSC

Performed the following maintenance:  
 1. Complied with an Annual Inspection refering to this propeller has been inspected in accordance with FAR Part 43.11 service.

Authorized Sign \_\_\_\_\_

Next Inspection Due: \_\_\_\_\_ End \_\_\_\_\_

Mech. Cert. # or Repair Station # \_\_\_\_\_