

Textron (Cessna) 182S

**Airworthiness Directives
Compliance Report**

Date: 4/4/2026

Tail #: N940MA

Airframe: Textron (Cessna) 182S

S/N: 182-80360

Hours:

Engine: Lycoming IO-540-AB1A5

S/N:









Hours:

Propeller: McCauley B2D34C Series



S/N:

Hours:








Airframe: Textron (Cessna) 182S

AD#	Category	Subject	Amdt#	Eff Date	Recurring
2013-11-11	Airframe	Engine Oil Pressure Switch	39-17471	08/01/13	Yes
Date/Hours at Compliance: 5/15/2015 1425.0		Method of Compliance: PCW next due at ACTT: 4425.0		Name: Jonathan donahue	
Next Due Date/Hours: ACTT: 4425.0		Signature: 		Cert#: A&P 3407736 IA	
2008-26-10	Airframe	Alternate Static Air Source Selector Valve	39-15776	01/05/09	
Date/Hours at Compliance: 1/05/09		Method of Compliance: PCW		Name: Jonathan donahue	
Next Due Date/Hours:		Signature: 		Cert#: A&P 3407736 IA	
2008-10-02	Airframe	Alternate Static Air Source Selector Valve	39-15508	05/12/08	
Date/Hours at Compliance: 3/26/2025 ACTT: 2199.8		Method of Compliance: NA by S/N		Name: Jonathan donahue	
Next Due Date/Hours:		Signature: 		Cert#: A&P 3407736 IA	
2008-02-18	Airframe	BRS Parachute System Pick-Up Collar Support and Retaining Screws	39-15348	02/28/08	
Date/Hours at Compliance: 3/26/205 ACTT: 2199.8		Method of Compliance: NA by effective equipment not installed		Name: Jonathan donahue	
Next Due Date/Hours:		Signature: 		Cert#: A&P 3407736 IA	
2007-05-10	Airframe	Crew Seat Back Cylinder Lock	39-14971	04/11/07	
Date/Hours at Compliance: 3/26/2025 ACTT: 2199.8		Method of Compliance: NA by PN not installed		Name: Jonathan donahue	
Next Due Date/Hours:		Signature: 		Cert#: A&P 3407736 IA	
2004-15-18	Airframe	KAP 140 Autopilot	39-13752	09/12/04	
Date/Hours at Compliance: 3/26/2025 ACTT: 2199.8		Method of Compliance: NA Effective part not installed		Name: Jonathan donahue	
Next Due Date/Hours:		Signature: 		Cert#: A&P 3407736 IA	
2000-02-14	Airframe	Engine Exhaust Mufflers	39-11532	03/17/00	Yes
Date/Hours at Compliance: 3/26/2025 ACTT: 2199.8		Method of Compliance: NA by SN		Name: Jonathan donahue	
Next Due Date/Hours:		Signature: 		Cert#: A&P 3407736 IA	
98-16-04	Airframe	Angle Stiffener On Wing	39-10679	09/21/98	
Date/Hours at Compliance: 3/26/2025 ACTT: 2199.8		Method of Compliance: NA STC not installed at this time.		Name: Jonathan donahue	
Next Due Date/Hours:		Signature: 		Cert#: A&P 3407736 IA	











Name: Textron (Cessna) 182S

AD#	Category	Subject	Amdt#	Eff Date	Recurring
98-01-14	Airframe	Engine Exhaust Muffler	39-10292	02/23/98	
Date/Hours at Compliance: 3/26/2025 ACTT: 2199.8		Method of Compliance: NA by SN		Name: Jonathan donahue	
Next Due Date/Hours:		Signature: 		Cert#: A&P 3407736 IA	
Notes:					
98-01-01	Airframe	Placard in Cockpit	39-10287	02/02/98	
Date/Hours at Compliance: 3/26/2025 ACTT: 2199.8		Method of Compliance: NA BY SN		Name: Jonathan donahue	
Next Due Date/Hours:		Signature: 		Cert#: A&P 3407736 IA	
Notes:					










Engine: Lycoming IO-540-AB1A5

AD#	Category	Subject	Amdt#	Eff Date	Recurring
2026-04-11	Engine	Connecting Rod Failure	39-23271	04/08/26	Yes
Date/Hours at Compliance: 4/4/2026 2341.13		Method of Compliance: NA by date of eng		Name: Jonathan donahue	
Next Due Date/Hours:		Signature: 		Cert#: A&P 3407736 IA	
Notes:					
2024-21-02	Engine	Connecting Rod Failure	39-22869	12/05/24	Yes* (Terminating Action)
Date/Hours at Compliance: 3/26/25 ACTT: 2199.8		Method of Compliance: NA by PN and date of OH		Name: Jonathan donahue	
Next Due Date/Hours:		Signature: 		Cert#: A&P 3407736 IA	
Notes:					
2017-16-11	Engine	Connecting Rod Failure	39-18988	08/15/17	
Date/Hours at Compliance: 3/26/25 ACTT: 2199.8		Method of Compliance: NA by SN		Name: Jonathan donahue	
Next Due Date/Hours:		Signature: 		Cert#: A&P 3407736 IA	
Notes:					
2015-19-07	Engine	Fuel Injector Fuel Lines and Clamps	39-18269	11/03/15	Yes
Date/Hours at Compliance: 4/4/26 2341.13		Method of Compliance: Inspected lines and clamps, determined to be in a satisfactory condition at this time. Next Due 4/202 or ACTT: 2441.13		Name: Jonathan donahue	
Next Due Date/Hours: ACTT: 2441.13		Signature: 		Cert#: A&P 3407736 IA	
Notes:					
2012-19-01	Engine	Crankshaft Replacement	39-17196	10/24/12	
Date/Hours at Compliance: 5/14/2015 1425		Method of Compliance: PCW		Name: Jonathan donahue	
Next Due Date/Hours:		Signature: 		Cert#: A&P 3407736 IA	
Notes:					
2012-03-06	Engine	AVStar Fuel Servo Diaphragm	39-16947	02/24/12	
Date/Hours at Compliance: 3/26/25 ACTT: 2199.8		Method of Compliance: NA BY PN		Name: Jonathan donahue	
Next Due Date/Hours:		Signature: 		Cert#: A&P 3407736 IA	
Notes:					
2009-26-12	Engine	ECi Cracked Cylinder Assemblies	39-16151	02/04/10	Yes
Date/Hours at Compliance: 3/26/25 ACTT: 2199.8		Method of Compliance: NA by No ECi cylinders installed at this time		Name: Jonathan donahue	
Next Due Date/Hours:		Signature: 		Cert#: A&P 3407736 IA	
Notes:					


Wycoming IO-540-AB1A5

Category	Subject	Amdt#	Eff Date	Recurring
09-02-03	Engine RSA-5 or RSA-10 Series - Fuel Injection Servo Plug Gasket	39-15793	02/09/09	Yes* (Terminating Action)
Date/Hours at Compliance: 3/26/25 Method of Compliance: CW by visual inspection			Name: Jonathan donahue	
ACTT: 2199.8				
Next Due Date/Hours: ACTT: 2249.8			Signature: 	
Notes:			Cert#: A&P 3407736 IA	
2007-04-19 R1	Engine Superior Air Parts Cylinder Assemblies	39-15005	05/07/07	
Date/Hours at Compliance: 3/26/25 Method of Compliance: NA by PN			Name: Jonathan donahue	
ACTT: 2199.8				
Next Due Date/Hours:			Signature: 	
Notes:			Cert#: A&P 3407736 IA	
2006-12-07	Engine ECi Cylinder Assemblies	39-14632	07/11/06	
Date/Hours at Compliance: 3/26/25 Method of Compliance: NA by NO ECi cyl installed at this time.			Name: Jonathan donahue	
ACTT: 2199.8				
Next Due Date/Hours:			Signature: 	
Notes:			Cert#: A&P 3407736 IA	
2005-19-11	Engine Crankshaft Failures	39-14276	10/21/05	
Date/Hours at Compliance: 3/26/25 Method of Compliance: NA by Date			Name: Jonathan donahue	
ACTT: 2199.8				
Next Due Date/Hours:			Signature: 	
Notes:			Cert#: A&P 3407736 IA	
2004-10-14	Engine Crankshaft Gear Retaining Bolt	39-13644	06/25/04	Yes
Date/Hours at Compliance: 3/26/25 Method of Compliance: Due at prop strike or sudden stoppage			Name: Jonathan donahue	
ACTT: 2199.8				
Next Due Date/Hours:			Signature: 	
Notes:			Cert#: A&P 3407736 IA	
2004-05-24	Engine Crankshaft Gear Retaining Bolts	39-13519	03/30/04	
Date/Hours at Compliance: 4/7/2008 1186.1 Method of Compliance: PCW			Name: Jonathan donahue	
ACTT: 2199.8				
Next Due Date/Hours:			Signature: 	
Notes:			Cert#: A&P 3407736 IA	
2003-14-03	Engine Rotary Fuel Pump Leaks	39-13222	08/14/03	Yes* (Terminating Action)
Date/Hours at Compliance: 3/26/25 Method of Compliance: NA by effected pump not installed			Name: Jonathan donahue	
ACTT: 2199.8				
Next Due Date/Hours:			Signature: 	
Notes:			Cert#: A&P 3407736 IA	
2002-19-03	Engine Crankshaft Failure	39-12883	09/20/02	
Date/Hours at Compliance: 3/26/25 Method of Compliance: NA stc not installed at this time.			Name: Jonathan donahue	
ACTT: 2199.8				
Next Due Date/Hours:			Signature: 	
Notes:			Cert#: A&P 3407736 IA	
98-17-11	Engine Crankshafts Installed by Nelson Balancing Service	39-10713	10/19/98	
Date/Hours at Compliance: 3/26/25 Method of Compliance: NA by PN and SN			Name: Jonathan donahue	
ACTT: 2199.8				
Next Due Date/Hours:			Signature: 	
Notes:			Cert#: A&P 3407736 IA	
96-23-03	Engine High Pressure Fuel Pumps	39-9826	12/17/96	
Date/Hours at Compliance: 3/26/25 Method of Compliance: NA by DOM			Name: Jonathan donahue	
ACTT: 2199.8				
Next Due Date/Hours:			Signature: 	
Notes:			Cert#: A&P 3407736 IA	

Engine: Lycoming IO-540-AB1A5

AD#	Category	Subject	Amdt#	Eff Date	Recurring
96-09-10 Date/Hours at Compliance: 4/7/2008 1186.1 Next Due Date/Hours: Notes:	Engine	Oil Pump Impeller Failure Method of Compliance: PCW Signature: 	39-9586	07/15/96	Name: Jonathan donahue Cert#: A&P 3407736 IA
93-11-11 Date/Hours at Compliance: 3/26/25 ACTT: 2199.8 Next Due Date/Hours: Notes:	Engine	Diaphragm Fuel Pumps Overhauled (by AAI) - Remove Affected Pump and Replace Method of Compliance: NA by PN installed Signature: 	39-8584	06/21/93	Name: Jonathan donahue Cert#: A&P 3407736 IA
92-12-05 Date/Hours at Compliance: 4/7/2008 1186.1 Next Due Date/Hours: Notes:	Engine	Piston Pin Failure Method of Compliance: PCW Signature: 	39-8265	07/10/92	Name: Jonathan donahue Cert#: A&P 3407736 IA
79-04-05 Date/Hours at Compliance: 3/11/2008 1186.1 Next Due Date/Hours: Notes:	Engine	Bendix RSA Series Fuel Injectors Diaphragm Method of Compliance: PCW Signature: 	39-3570	09/26/79	Name: Jonathan donahue Cert#: A&P 3407736 IA
78-23-10 Date/Hours at Compliance: 4/7/2008 1186.1 Next Due Date/Hours: Notes:	Engine	Bendix RSA Series Fuel Injector Bellows Seal Method of Compliance: PCW Signature: 	39-3333	11/07/78	Name: Jonathan donahue Cert#: A&P 3407736 IA
75-09-15 Date/Hours at Compliance: 4/7/2008 1186.1 Next Due Date/Hours: Notes:	Engine	Bendix Fuel Injector Flow Divider Cover Gasket Method of Compliance: PCW Signature: 	39-2187	04/30/75	Name: Jonathan donahue Cert#: A&P 3407736 IA
75-08-09 Date/Hours at Compliance: 4/7 Next Due Date/Hours: Notes:	Engine	Oil Pump Drive Shaft and Impeller Method of Compliance: PCW Signature: 	39-3013	08/18/77	Name: Jonathan donahue Cert#: A&P 3407736 IA
66-20-04 Date/Hours at Compliance: 4/7/2008 1186.1 Next Due Date/Hours: Notes:	Engine	Oil Filter Adapter Gasket Method of Compliance: PCW Signature: 	39-277	08/27/66	Name: Jonathan donahue Cert#: A&P 3407736 IA
63-14-03 Date/Hours at Compliance: 4/7/2008 1186.1 Next Due Date/Hours: Notes:	Engine	Oil Pump Drive Shaft Method of Compliance: PCW Signature: 	583	07/06/63	Yes* (Terminating Action) Name: Jonathan donahue Cert#: A&P 3407736 IA


Propeller: McCauley B2D34C Series

AD#	Category	Subject	Amdt#	Eff Date	Recurring
2006-24-07 Date/Hours at Compliance: 3/26/2025 ACTT: 2199.8 Next Due Date/Hours: Notes:	Propeller	Oxford Aviation/CSE Aviation Serviced Propellers Method of Compliance: NA By Not serviced by Oxford Aviation Limited, doing business as CSE Aviation Signature: 	39-14836	01/03/07	Name: Jonathan donahue Cert#: A&P 3407736 IA

Appliance: Cabin Safety Belts

AD#	Category	Subject	Amdt#	Eff Date	Recurring
2025-16-09	Appliance	Rotary Buckles P/N 1111475 & 1111548-01 - Defective Buckle Screws	39-23107	09/22/25	

Date/Hours at Compliance: *4/4/26*
Next Due Date/Hours:
Notes:


Method of Compliance: *NA Not Installed*
Signature: 

Name: Jonathan donahue
Cert#: A&P 3407736 IA

Appliance: Large Aircraft Seats






AD#	Category	Subject	Amdt#	Eff Date	Recurring
2025-12-02	Appliance	3A063 Series Seats - Unexpected Movement of Pilot and Co-Pilot Seats	39-23060	06/30/25	

Date/Hours at Compliance: *4/4/26*
Next Due Date/Hours:
Notes:


Method of Compliance: *NA by PC*
Signature: 

Name: Jonathan donahue
Cert#: A&P 3407736 IA



Rayley B2D34C Series

AD#	Category	Subject	Amdt#	Eff Date	Recurring
2003-13-17	Propeller	Southern California Propeller Serviced Propellers Method of Compliance: NA By NOT last returned to service by Southern California Propeller Service of Inglewood, CA., Signature: 	39-14188	08/17/05	Name: Jonathan donahue Cert#: A&P 3407736 IA
2199.8		Next Due Date/Hours:			
2003-13-17	Propeller	T and W Serviced Propellers Method of Compliance: NA by NOT returned to service by T and W Propellers, Inc. of Chino, CA, Signature: 	39-13219	07/18/03	Name: Jonathan donahue Cert#: A&P 3407736 IA
2199.8		Next Due Date/Hours:			
91-15-04	Propeller	Blade Threaded Retention Area Method of Compliance: NA by PN installed Signature: 	39-7067	08/07/91	Name: Jonathan donahue Cert#: A&P 3407736 IA
2199.8		Next Due Date/Hours:			
82-27-02 R1	Propeller	Dye Penetrant Inspection For Blade Shank Area Cracks Method of Compliance: NA by mod and Sn Signature: 	39-4564	02/22/83	Name: Jonathan donahue Cert#: A&P 3407736 IA
2199.8		Next Due Date/Hours:			
70-04-01	Propeller	Blade Damage Method of Compliance: NA by PN Signature: 	39-939	02/20/70	Name: Jonathan donahue Cert#: A&P 3407736 IA
2199.8		Next Due Date/Hours:			

Appliance: Avionics Navigational

AD#	Category	Subject	Amdt#	Eff Date	Recurring
2025-07-01	Appliance	AC32 Digital Air Data Computers (ADCs) - Replacement Method of Compliance: <i>NA not installed</i> Signature: 	39-23002	05/15/25	Name: Jonathan donahue Cert#: A&P 3407736 IA
		Date/Hours at Compliance: <i>4/4/26</i>			
		Next Due Date/Hours:			

Appliance: Cabin Oxygen

AD#	Category	Subject	Amdt#	Eff Date	Recurring
2026-03-09	Appliance	Oxygen - Affected PBE May Not Supply Oxygen When Donned Method of Compliance: <i>NA Not Installed</i> Signature: 	39-23258	03/12/26	Name: Jonathan donahue Cert#: A&P 3407736 IA
		Date/Hours at Compliance: <i>4/4/26</i>			
		Next Due Date/Hours:			
2025-26-06	Appliance	Incorrect Donning Procedures for Portable Breathing Equipment (PBE) Method of Compliance: <i>NA Not Installed</i> Signature: 	39-23228	01/14/26	Name: Jonathan donahue Cert#: A&P 3407736 IA
		Date/Hours at Compliance: <i>4/4/26</i>			
		Next Due Date/Hours:			

Textron (Cessna) 182S

**Airworthiness Directives
Compliance Report**

Date: 3/26/2025	Tail #: N940MA	
Airframe: Textron (Cessna) 182S	S/N: 182-80360	Hours:
Engine: Lycoming IO-540-AB1A5	S/N:	Hours:
Propeller: McCauley B2D34C Series	S/N:	Hours:

Airframe: Textron (Cessna) 182S

AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Rec	Date/Hours Next Due	Signature and Number
2013-11-11 08/01/13 Airframe	Engine Oil Pressure Switch	5/15/2015 1425.0	PCW next due at ACTT: 4425.0	Yes	ACTT: 4425.0	Jonathan donahue A&P 3407736 IA
2008-26-10 01/05/09 Airframe	Alternate Static Air Source Selector Valve	1/05/09	PCW			Jonathan donahue A&P 3407736 IA
2008-10-02 05/12/08 Airframe	Alternate Static Air Source Selector Valve	3/26/2025 ACTT: 2199.8	NA by S/N			Jonathan donahue A&P 3407736 IA
2008-02-18 02/28/08 Airframe	BRS Parachute System Pick-Up Collar Support and Retaining Screws	3/26/205 ACTT: 2199.8	NA by effective equipment not installed			Jonathan donahue A&P 3407736 IA
2007-05-10 04/11/07 Airframe	Crew Seat Back Cylinder Lock	3/26/2025 ACTT: 2199.8	NA by PN not installed			Jonathan donahue A&P 3407736 IA
2004-15-18 09/12/04 Airframe	KAP 140 Autopilot	3/26/2025 ACTT: 2199.8	NA Effective part not installed			Jonathan donahue A&P 3407736 IA
2000-02-14 03/17/00 Airframe	Engine Exhaust Mufflers	3/26/2025 ACTT: 2199.8	NA by SN	Yes		Jonathan donahue A&P 3407736 IA
98-16-04 09/21/98 Airframe	Angle Stiffener On Wing	3/26/2025 ACTT: 2199.8	NA STC not installed at this time.			Jonathan donahue A&P 3407736 IA
98-01-14 02/23/98 Airframe	Engine Exhaust Muffler	3/26/2025 ACTT: 2199.8	NA by SN			Jonathan donahue A&P 3407736 IA
98-01-01 02/02/98 Airframe	Placard in Cockpit	3/26/2025 ACTT: 2199.8	NA BY SN			Jonathan donahue A&P 3407736 IA

Engine: Lycoming IO-540-AB1A5

AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Rec	Date/Hours Next Due	Signature and Number
2024-21-02 12/05/24 Engine	Connecting Rod Failure	3/26/25 ACTT: 2199.8	NA by PN and date of OH	Yes*		Jonathan donahue A&P 3407736 IA
2017-16-11 08/15/17 Engine	Connecting Rod Failure	3/26/25 ACTT: 2199.8	NA by SN			Jonathan donahue A&P 3407736 IA
2015-19-07 11/03/15 Engine	Fuel Injector Fuel Lines and Clamps	3/26/25 ACTT: 2199.8	Inspected lines and clamps, determined to be in a satisfactory condition at this time. Next Due 4/2026 or ACTT: 2299.8	Yes	ACTT: 2299.8	Jonathan donahue A&P 3407736 IA
2012-19-01 10/24/12 Engine	Crankshaft Replacement	5/14/2015 1425	PCW			Jonathan donahue A&P 3407736 IA
2012-03-06 02/24/12 Engine	AVStar Fuel Servo Diaphragm	3/26/25 ACTT: 2199.8	NA BY PN			Jonathan donahue A&P 3407736 IA
2009-26-12 02/04/10 Engine	ECi Cracked Cylinder Assemblies	3/26/25 ACTT: 2199.8	NA by No ECi cylinders installed at this time	Yes		Jonathan donahue A&P 3407736 IA
2009-02-03 02/09/09 Engine	RSA-5 or RSA-10 Series - Fuel Injection Servo Plug Gasket	3/26/25 ACTT: 2199.8	CW by visual inspection	Yes*	ACTT: 2249.8	Jonathan donahue A&P 3407736 IA
2007-04-19 R1 05/07/07 Engine	Superior Air Parts Cylinder Assemblies	3/26/25 ACTT: 2199.8	NA by PN			Jonathan donahue A&P 3407736 IA
2006-12-07 07/11/06 Engine	ECi Cylinder Assemblies	3/26/25 ACTT: 2199.8	NA by NO ECi cyl installed at this time.			Jonathan donahue A&P 3407736 IA
2005-19-11 10/21/05 Engine	Crankshaft Failures	3/26/25 ACTT: 2199.8	NA by Date			Jonathan donahue A&P 3407736 IA
2004-10-14 06/25/04 Engine	Crankshaft Gear Retaining Bolt	3/26/25 ACTT: 2199.8	Due at prop strike or sudden stoppage	Yes		Jonathan donahue A&P 3407736 IA

2004-05-24 03/30/04 Engine	Crankshaft Gear Retaining Bolts	4/7/2008 1186.1	PCW			Jonathan donahue A&P 3407736 IA
2003-14-03 08/14/03 Engine	Rotary Fuel Pump Leaks	3/26/25 ACTT: 2199.8	NA by effected pump not installed	Yes*		Jonathan donahue A&P 3407736 IA
2002-19-03 09/20/02 Engine	Crankshaft Failure	3/26/25 ACTT: 2199.8	NA stc not installed at this time.			Jonathan donahue A&P 3407736 IA
98-17-11 10/19/98 Engine	Crankshafts Installed by Nelson Balancing Service	3/26/25 ACTT: 2199.8	NA by PN and SN			Jonathan donahue A&P 3407736 IA
96-23-03 12/17/96 Engine	High Pressure Fuel Pumps	3/26/25 ACTT: 2199.8	NA by DOM			Jonathan donahue A&P 3407736 IA
96-09-10 07/15/96 Engine	Oil Pump Impeller Failure	4/7/2008 1186.1	PCW			Jonathan donahue A&P 3407736 IA
93-11-11 06/21/93 Engine	Diaphragm Fuel Pumps Overhauled (by AAI) - Remove Affected Pump and Replace	3/26/25 ACTT: 2199.8	NA by PN installed			Jonathan donahue A&P 3407736 IA
92-12-05 07/10/92 Engine	Piston Pin Failure	4/7/2008 1186.1	PCW			Jonathan donahue A&P 3407736 IA
79-04-05 09/26/79 Engine	Bendix RSA Series Fuel Injectors Diaphragm	3/11/2008 1186.1	PCW			Jonathan donahue A&P 3407736 IA
78-23-10 11/07/78 Engine	Bendix RSA Series Fuel Injector Bellows Seal	4/7/2008 1186.1	PCW			Jonathan donahue A&P 3407736 IA
75-09-15 04/30/75 Engine	Bendix Fuel Injector Flow Divider Cover Gasket	4/7/2008 1186.1	PCW			Jonathan donahue A&P 3407736 IA
75-08-09 08/18/77 Engine	Oil Pump Drive Shaft and Impeller	4/7	PCW			Jonathan donahue A&P 3407736 IA
66-20-04 08/27/66 Engine	Oil Filter Adapter Gasket	4/7/2008 1186.1	PCW			Jonathan donahue A&P 3407736 IA
63-14-03 07/06/63 Engine	Oil Pump Drive Shaft	4/7/2008 1186.1	PCW	Yes*		Jonathan donahue A&P 3407736 IA

Propeller: McCauley B2D34C Series						
AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Rec	Date/Hours Next Due	Signature and Number
2006-24-07 01/03/07 Propeller	Oxford Aviation/CSE Aviation Serviced Propellers	3/26/2025 ACTT: 2199.8	NA By Not serviced by Oxford Aviation Limited, doing business as CSE Aviation			Jonathan donahue A&P 3407736 IA
2005-14-11 08/17/05 Propeller	Southern California Propeller Serviced Propellers	3/26/2025 ACTT: 2199.8	NA By NOT last returned to service by Southern California Propeller Service of Inglewood, CA.			Jonathan donahue A&P 3407736 IA
2003-13-17 07/18/03 Propeller	T and W Serviced Propellers	3/26/2025 ACTT: 2199.8	NA by NOT returned to service by T and W Propellers, Inc. of Chino, CA.			Jonathan donahue A&P 3407736 IA
91-15-04 08/07/91 Propeller	Blade Threaded Retention Area	3/26/2025 ACTT: 2199.8	NA by PN installed			Jonathan donahue A&P 3407736 IA
82-27-02 R1 02/22/83 Propeller	Dye Penetrant Inspection For Blade Shank Area Cracks	3/26/2025 ACTT: 2199.8	NA by mod and Sn			Jonathan donahue A&P 3407736 IA
70-04-01 02/20/70 Propeller	Blade Damage	3/26/2025 ACTT: 2199.8	NA by PN			Jonathan donahue A&P 3407736 IA