

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-C3YF-1RF

PROPELLER S/N EE 4394B

LOGBOOK # 1

THIS SERVICE RECORD shall accompany the propeller equipment at all times. When equipment is installed as part of an Aircraft or engine, this record shall be maintained concurrently with and become a part of the Aircraft and Engine Service Records.

PROPELLER MAINTENANCE RECORD

Position _____

PITCH RANGE

Propeller Model PHC-C3YF-1RF

High/Feather _____

Propeller S/N EE 4394 B

Start Lock _____

Blade Design F8068

Low _____

Blade S/N's

Reverse _____

No. 1 JB4329

No. 2 JB4328

Aircraft Manufacturer BEECHCRAFT

No. 3 JB4330

Aircraft Model F33A

No. 4 _____


S/N CE-1039

No. 5 _____


Registration N69302

No. 6 _____

Spinner Assembly Part No. _____

Date	Proprietor	A/C	Description of all operations pertaining to Airworthiness Directives, Repairs, Overhaul, Major or Minor Repairs, etc.
	PROP MODEL: PHC-C3YF-1RF PROP S/N: EE-4394B REG. NO: 6559 WORK ORDER: 4115	 Chuck's Aircraft, LLC. 6200 Aviation Dr. AC101 Austin Executive Airport Pflugerville, TX 78660 Phone: 512-610-3111	DATE: 4/1/2021 A/C TSN: 3073.92 PROP TT: 625.32 TSPOH: TACH: 1342.12
Prop Entries Inspected hub, blades, spinner and backplate.... Removed from engine, s/n: 271760-R and installed propeller on engine, s/n: 569967. Replaced o-ring with new p/n: C-3317-228, torqued fasteners per M/M.			
Technicians Who Worked On The Items Listed Above: Nicholas Bownds			
This propeller has been inspected in accordance with a 100-hour inspection and is approved for return to service.			
DATE: 4/1/2021	SIGNED:  Nicholas Bownds, A&P: 4318510		Work Order: 4115 Printed by EBis 3 (datcomedia.com)

	PROP MODEL: PHC-C3YF-1RF PROP S/N: EE-4394B REG. NO: 6559 WORK ORDER: 4699	 Chuck's Aircraft, LLC. 6200 Aviation Dr. AC101 Austin Executive Airport Pflugerville, TX 78660 Phone: 512-610-3111	DATE: 4/2/2022 A/C TSN: 1407.71 PROP TT: 690.91 TSPOH: TACH: 1407.71
Prop Entries Profiled propeller blades as necessary. Serviced propeller hub with Aeroshell #6. Inspected spinner, hub and backplate.			
Technicians Who Worked On The Items Listed Above: Zach Young			
This propeller has been inspected in accordance with a 100-hour inspection and is approved for return to service.			
DATE: 4/2/2022	SIGNED:  Zach Young, A&P: 4063779		Work Order: 4699 Printed by EBis 3 (datcomedia.com)

	PROP MODEL: PHC-C3YF-1RF PROP S/N: EE-4394B REG. NO: 6559 WORK ORDER: 5355	 Chuck's Aircraft, LLC. 6200 Aviation Dr. AC101 Austin Executive Airport Pflugerville, TX 78660 Phone: 512-610-3111	DATE: 5/25/2023 A/C TSN: 3171.5 PROP TT: 714 TSPOH: TACH: 3171.5
Prop Entries Inspected hub, blades, spinner and backplate.			
Technicians Who Worked On The Items Listed Above: Colin Gangi			
This propeller has been inspected in accordance with a 100-hour inspection and is approved for return to service.			
DATE: 5/25/2023	SIGNED:  Colin Gangi, A&P: 4213181		Work Order: 5355 Printed by EBis 3 (datcomedia.com)

	PROP MODEL: PHC-C3YF-1RF PROP S/N: EE-4394B REG. NO: 6559 WORK ORDER: 5953	 Chuck's Aircraft, LLC. 6200 Aviation Dr. AC101 Austin Executive Airport Pflugerville, TX 78660 Phone: 512-610-3111	DATE: 8/16/2024 A/C TSN: 3171.5 PROP TT: 714 TSPOH: TACH: 3171.5
Prop Entries Inspected hub, blades, spinner, and back plate.			
Technicians Who Worked On The Items Listed Above: Reagan Penniman			
This propeller has been inspected in accordance with a 100-hour inspection and is approved for return to service.			
DATE: 8/16/2024	SIGNED:  Zach Young, A&P: 4063779		Work Order: 5953 Printed by EBis 3 (datcomedia.com)

