YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Re… …a… …terations Entries must be endorsed with Name, Re… …er… Number of Technician or R… Facility. (See back pages for other spec…
DATE				

A/C Reg: N844ES
Make: CubCrafters
Model: CC11-160
S/N: CC11-00146

TAC•AERO

75 Airport Road
Fredericksburg, Tx
78624
(844) FLY-CUBS

Date: 09/02/2026
Tach: 458.1
Total Hrs: 458.1

Performed Condition Inspection on Airframe on this date. Cleaned, inspected and lubricated all pulleys, bellcranks, rollers, hinges and bearings. Function checked ELT battery IAW 91.207(d). Expiration date: 01/2028. Cleaned fuel filters. Inspected exhaust system. Replaced induction air filter. Removed and replaced PS-1221S ignition back-up battery; next due 09/2027. Removed tailwheel assembly; cleaned and inspected; greased, assembled, and installed. Cleaned, inspected, and greased main wheel bearings. Inspected and serviced brake system. Removed and replaced SC97410-001 L/H lower aileron cable. Checked aileron travel and cable tension. Run-up, leak check. Operational check. Good.

I certify that this aircraft has been inspected IAW CubCrafters manual SSC10000AMM Rev E and has been determined to be in a condition for safe operation.

David Land

David Land A&P 3140576 IA

YEAR: ____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	**Description of Inspections, Tests, Repairs and Alterations** Entries must be endorsed with Name, Rating and Certificate Number of Technician Facility. (See back pages for other specific entries.)
				A/C Reg: N844ES Make: CubCrafters Model: CC340 S/N: CC340-00050 TAC·AERO 75 Airport Road Fredericksburg, Tx 78624 (844) FLY-CUBS Date: 09/02/2026 Tach: 458.1 Total Hrs: 458.1 Performed Condition Inspection on engine on this date. Compressions: #1 74 #2 73 #3 74 #4 72. Performed oil change. Insp oil filter element for contaminants, no contaminants found. Installed new AA48108-2 oil filter and filled engine with 5 qts of P Victory 20W-50 oil. Replaced all eight spark plugs. Removed and replaced #s 1 and 3 75906 valve cover gaskets. Remove replaced #s 1 and 3 SP50208-001 induction flange o-rings. Performed ground run and leak check; Good. I certify that this engine has been inspected IAW CubCrafters manual SSC10000 Rev E and has been determined to b condition for safe operation. David Land David Land A&P 3140576 IA

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

	Total Time in Service	Description
Year		

Dat

Nex
Due

A/C Reg: N844ES
Make: Catto
S/N: 06111714

TAC·AERO

75 Airport Road
Fredericksburg, Tx
78624
(844) FLY-CUBS

Date: 08/27/2025
Tach: 426.6
TT Prop: 426.6

Yea

Performed Condition Inspection IAW Catto service manual. I certify that this propeller has been inspected IAW scope and detail of 14 CFR part 43 Appendix D and has been determined to be in a condition for safe operation.

Dat

Hugh Pittman A&P 3803946

Nex
Due:

| Overhaul

A/C Reg: N844ES
Make: Catto
Model: Glass/Composite
S/N: 06111714

TAC·AERO

75 Airport Road
Fredericksburg, Tx
78624
(844) FLY-CUBS

Date: 09/02/2026
Tach: 458.1
Total Hrs: 458.1

Year:

Date:

Next Ins
Due:

Performed Condition Inspection on propeller on this date. I certify that this propeller has been inspected IAW Catto manual CATTO-CPX-01 Rev 3 and has been determined to be in a condition for safe operation.

David Land

David Land A&P 3140576 IA