
The Standard
AIRCRAFT LOG
ASA-SA-1

Wultsberg Electronics Division
6400 Wilkinson Dr. Prescott, AZ 86301
(928)708-1550
LOG BOOK ENTRY Sept. 2, 2011
E.L.T. BATTERY
REPLACEMENT DATE

www.beaconregistration.noaa.gov
Exp. 01/22/2023
ADCC4 04810 00315
If activated, call the AFRCC at
1-800-851-3051

The Standard
AIRCRAFT LOG

ASA-SA-1

The Standard Aircraft Log
SA-1

© 1993–2000 Aviation Supplies & Academics, Inc.

ISBN 1-56027-419-0
978-1-56027-419-3
ASA-SA-1

All rights reserved.
Reproduction or use, without expressed permission,
in any manner, is prohibited.

Published by
Aviation Supplies & Academics, Inc.
7005 132nd Place SE
Newcastle, WA 98059-3153
Website: www.asa2fly.com
Email: asa@asa2fly.com

Printed in the United States of America

PNR ASA-SA-1

ISBN 978-1-56027-419-3
9 781560 274193 50595

Aircraft Record General Information

Manufacturer: Cub Crafters, Inc.

Model: CC11-160

Serial Number: CC11-00146

Registration Number: N844ES

Date of Manufacture: October 8, 2010

Engine Installed: CubCrafters

Model Number: CC340

Serial Number: 00050

Propeller Installed: Catto

Model Number: 2-BLD 78" x 54"

Serial Number: 07101430

egistered Owner Record

ame	Edgar Smith	Address	PO Box 267				
ity	Goldthwaite	State	TX	From	Oct 2010	To	
lame	Bill J. Brown	Address	1907 Hwy 39				
City	Hunt	State	TX 78024	From	Sept 9, 2020	To	
Name		Address					
City		State		From		To	
Name		Address					
City		State		From		To	
Name		Address					
City		State		From		To	
Name		Address					
City		State		From		To	

Notes

YEAR: / DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

I certify that the transponder test required by 91.413 as per FAR part 43 appendix "F" has been performed.

Date 10/6/10 Model GTX-327
S/N 0781

Mary English

I certify that the static/altimeter test required by 91.411 as per FAR part 43 appendix "E" has been performed.

↘ ALTIMETER TO 30,000 ft.
↘ ALTITUDE REPORTING TEST
STATIC SYSTEM TEST
↘ INTEGRATED SYSTEM TEST

2424313

McCORMICK AIRCRAFT MAINTENANCE, LLC
C.R.S. KB6R659N
2108 W. WASHINGTON AVE.
YAKIMA, WA 98903

YEAR: / DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

Registration Number: N844ES Serial Number: CC11-00146

This aircraft was weighed and a weight and balance report was completed and filed with the aircraft's permanent records. I have inspected this aircraft and found it to be in a condition for safe operation.

Note: ELT battery replacement due on July 2016

October 8, 2010

Production Manager (Date)

YEAR: / DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

Registration Number: N844ES

Serial Number: CC11-00146

I have conducted a Production Flight Test in compliance with ASTM F2279-06. I find the aircraft to be controllable throughout the conduct of the Production Flight Test. The aircraft exhibits no hazardous operation characteristics.

BRYCE T. HUGHES
Cub Crafters Flight Test Pilot (Print name)

Total Tach Time: 1.5 hrs

Cub Crafters Flight Test Pilot (Signature)

Date: 10/8/2010

YEAR: / DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

I find this aircraft meets the requirements for the certificate requested and have issued a Special Airworthiness Certificate for the purpose of operating a Light Sport – airplane.

Next inspection is due: 11-01-2011

Signed: Frank Sneed

Date: 10-11-2010

FRANK SNEED DART309003NM
(Print name)

YEAR: / DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				I find that the aircraft meets the requirements for the certification requested and have issued an Experimental Airworthiness Light Sport Certificate dated 10-11-2010 The next condition inspection is due 11-01-2011 Frank Sneed Frank Sneed DART309003NM

YEAR: / DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				October 18, 2010 N844ES S/N CC11-00146 Tach 2.2 TT 2.2 Removed landing gear, cabane vee, lower shock struts, 6:00x6 tires and tubes, standard tailwheel assembly and seat belt/shoulder harness assemblies. Installed 3x3" extended landing gear, new cabane vee, 26" Airstreak tundra tires, 3200 tail wheel assembly, AOSS shock struts, fire extinguisher, and AmSafe airbag shoulder harness/seat belt assembly. Tested control box and reconnected. C/W SB00015 by installing new heavy wall torque tube P/N SC92101-001 with Loctite 680. Weight and Balance Report and Equipment List updated. Stan Franz ~~567906869~~A&P

YEAR:	RECORDING	TODAY'S	TOTAL	Description of Inspections, Tests, Repairs and Alterations
DATE				

MODEL:	CC11-160	DATE :	Sept 2, 2011
REGISTRATION:	N844ES	TACH :	36.7
S/N:	CC11-00146	TTSN :	36.7

Airframe

- Removed and reinstalled engine, Prop Strrke inspection done by Aero Sport Power.
- Installed new Catto 2 blade prop. 78"X54" S/N 06111714.
- Installed new spinner and backplate assembly.
- Installed new upper and lower cowlings and air scoop.
- Installed new windshield and Skylight.
- Installed new rudder. Factory covered and painted.
- Replaced 14# P/N SC 31046-001 and 22# P/N SC31046-002 Nose ribs, replaced leading edge skins on both wings, LH wing trailing edges replaced. Both wings recovered as per manufacture's specifications.
- Installed new LH Front wing strut.
- Reassembled aircraft., Installed new aileron control cables. Rigging checked to factory specifications.
- Installed new Aircraft battery.
- Installed 2# new vented fuel caps.
- Installed new Air filter CC P/N PC54108-001.

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations
DATE				Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

- Installed new left and right wing root fairings.
- Ignition Battery installed per Service Instruction No. SI0018 W&B Revised.
- Complied with Safety Alert SA0008 Dated August 10, 2011
- Complied with SI016 by installing CC P/N SC60051-001 Fuel line insert.
- Airbag seat belt annual inspection and test performed per manufactures instructions.
- ELT Battery replaced, ELT Tested in accordance with FAR 91.207
- I certify I have inspected this airframe in accordance with a condition Inspection on this date IAW FAR 43.13 Appendix D and it was determined to be in airworthy condition.

SIGNATURE : Cert #: 2587687

MODEL:	CC11-160	DATE :	Sept 14, 2011
REGISTRATION:	N844ES	TACH :	37.5
S/N:	CC11-00146	TTSN :	37.5

- Installed new oil temp probe P/N 100409-001
- Iinstalled ne EGT probe on #3 cylinder, P/N 100405-000

SIGNATURE : Cert # 2587687

YEAR: 2011 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
11/2				inspected per SB00018 - no discrepancies noted
				February 2, 2012 N- 844ES Cub Crafters mod.CC11-160 ser.CC11-00146 TTT 55.7 TTH 69.8 Remove and replace vertical lift strut bracket at wing main spar, left and right wings, and return to service. Will Dodd Will Dodd, A&P 3548327

YEAR: DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
11/20/12	TACH	63.9		Completed a condition inspection IAW FAR 4313 appendix D and it was determined to be in an airworthy condition installed new aircraft battery and ELT battery, cleaned and repacked wheel bearings.
				Thurston C Mitchell IA 3129761
7/26/14				This aircraft in condition for safe flight from T32 - COOM Tony Ly A&P FA 4501166-34

YEAR: / DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				03/13/14 TACH: 81.4 TT:81.4 N844ES Depaneled aircraft for inspection, performed inspection IAW Carbon Cub CC11-160 Aircraft Maintenance Manual. Removed ELT and tested IAW FAR 91.207(d). Serviced all fuel screens and drains as needed. Lubricated all pullies, hinges and control ends as needed. Complied with Safety Alert SA0009 Rev A. Checked and repacked wheel bearings as needed (P/N- PS-1221-S). Aircraft test ran with no leaks found. Aircraft returned to service. "I certify that this Aircraft has been inspected in accordance with Condition inspection and was determined to be in airworthy condition" IA AP3082247
10/24/14	85.1			Inspected per 5800016
2/16/15	88.6			Inspected per 5800019
5/6/15	96.7			C/w Amsafe inflatable restraint yearly Inspection IAW Amsafe ICA using test unit V23 Mark Keel AP3318125

YEAR: / DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				05/08/15 TACH: 96.7 TT: 96.7 N844ES
				Depaneled aircraft for inspection, removed ELT and tested IAW FAR 91.207(d). Performed inspection IAW Cubcrafters CC11-160 Aircraft Maintenance Manual. Serviced all fuel screens and drains as needed. Lubricated all pullies, hinges and control ends as needed. Removed and replaced aircraft battery with new SSB CTX14 unit. Removed and replaced backup ignition battery with new SLA-1020. Complied with SB00020 and SB00029 as needed by installing kits as needed. Aircraft test ran with no leaks found. Aircraft returned to service.
				"I certify that this Aircraft has been inspected in accordance with Condition inspection and was determined to be in airworthy condition"
				[illegible] AP3032247
6/8/16	TACH 110.5			C/W Annual Inspection & Glide Restraint Inspection No defects noted Approved for return to service Mech Lee AP3358125

YEAR: / DATE	

06/09/16 TACH: 110.5 TT: 110.5 N844ES

Depaneled aircraft for inspection, performed inspection IAW Cubcrafters CC11-160 Aircraft Maintenance Manual. Removed ELT and tested IAW FAR 91.207(d), reinstalled in aircraft. Serviced all fuel screens and drains as needed. Removed and replaced backup ignition battery with new SLA-1020 unit. Lubricated all pullies, hinges and control ends as needed. Removed and replaced air filter element as needed. Aircraft test ran with no leaks found. Aircraft returned to service.

"I certify that this Aircraft
was inspected Condition
in accordance with
that section and was determined
to be in airworthy condition"

6/8/16 AP3032247

epair

YEAR: / DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
6/30/16				C/W Annual IAW with Retainable Restraint Insp no defects noted Mark Reed AP 3398125

YEAR:

DATE

07/06/17 TACH: 121.1 TT: 121.1 N844ES

Depaneled aircraft for inspection, performed inspection IAW Cubcrafters CC11-160 Aircraft Maintenance Manual. Removed and replaced ELT battery, tested IAW FAR 91.207(d). Removed and replaced aircraft battery and backup ignition battery. Serviced all fuel screens and drains as needed. Lubricated all pullies, hinges and control ends as needed. Removed and replaced air filter element. Aircraft test ran with no leaks found. Aircraft returned to service.

"I certify that this Aircraft has been inspected in accordance with Condition inspection and was determined to be in airworthy condition"

AP3032247

epair

YEAR:

DATE

08-12-20 TACH: 126.1 TT: 126.1 N844ES

Depaneled aircraft for inspection, removed ELT and tested IAW FAR 91.207(d). Performed inspection IAW Cubcrafters CC11-160 Maintenance Manual. Serviced all fuel screens and drains as needed. Ops checked lights and stall warning. Lubricated all pullies, hinges and control ends. Removed and replaced air filter element. Removed and replaced both fuel sight tubes. Aircraft test ran with no leaks found. Aircraft returned to service.

"I certify that this Aircraft has been inspected in accordance with Condition inspection and was determined to be in airworthy condition"

AP3032247

lepair

YEAR: / DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				DATE: 9-23-2020 HR. MTR 131.0 TOTAL TIME FREDERICKSBURG AVIATION, LLC 465 AIRPORT ROAD FREDERICKSBURG, TX 78624 N844ES TIME STOH: SER.NO. Removed tailwheel leaf spring & replaced with new leaf spring p/n 412567-004. I certify that this Airframe has been serviced / inspected in accordance with current FAA regulations and is approved to return to service for work performed. David land A/P 3140576 I/A

YEAR: / DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				TAC-AIRD Make: CubCrafters Model: CC11-160 S/N: CC11-00146 465 Airport Road Fredericksburg TX (830) 990-9050 Date: 04/01/21 Tach Time: 167.6 Hobbs Time: Registration: N844ES Airframe Removed R/H and L/H 26" Airstreak Tires and Replaced with R/H and L/H 26" Alaska Bushweels Heavytread. Serial Numbers 21030410 and 21030412. Wheel bearings repacked, brakes inspected, all OK. I certify that this aircraft has been repaired and inspected in accordance with current FAA regulations and is approved for return to service for work performed. David Land A/P 3140576 I/A

YEAR: / DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

465 Airport Road
Fredericksburg TX
(830) 990-9050

Make: CubCrafters
Model: CC11-160
S/N: CC11-00146

Date: 07/19/2021
Tach Time: 177.9
Hobbs: 240.7
Registration: N844ES

Airframe

R&R LED Strobe Light AVE-WPSTG/R-54G. R&R Suspension System- Acme Black Ops Installed

I certify that this aircraft has been repaired and inspected in accordance with current FAA regulations and is approved for return to service for work performed.

David Land A/P 3140576 I/A David Land

YEAR: / DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

465 Airport Road
Fredericksburg TX
(830) 990-9050

Make: CubCrafters
Model: CC11-160
S/N: CC11-00146

Date: 08/04/2021
Tach Time: 183.7
Hobbs: 248.4
Registration: N844ES

R&R Tailwheel. Installed Acme Stinger Tailwheel P/N 69281. W+B updated

I certify that this aircraft has been repaired and inspected in accordance with current FAA regulations and is approved for return to service for work performed.

Steve 'Blue' Jeanes A/P 3291409

YEAR: ____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				465 Airport Road Fredericksburg TX (830) 990-9050 **Make:** CubCrafters **Date:** 09/21/2021 **Model:** CC11-160 **Tach Time:** 199.8 **S/N:** CC11-00146 **Hobbs:** 268.3 Airframe Annual Inspection **Registration:** N844ES Accomplished Condition Inspection on the Airframe, per FAR Requirements and IAW CubCrafters Manual. C/W inspection checklist. I certify that this Airframe has been serviced/inspected in accordance with current FAA regulations and with Appendix D Part 43. All work performed in accordance with CubCrafters Maintenance Manual and AC43.13.Removed, disassembled, cleaned and re-assembled tailwheel. Replaced backup ignition battery. Expires October 2022 I certify that this aircraft has been repaired and inspected in accordance with current FAA regulations and is approved for return to service for work performed. ELT Exp: 1/31/2024 Steve 'Blue' J. A/P 3291409

YEAR: ____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				Gulf Avionics, Inc. 1885 Airport Loop Road, Hangar 4 Kerrville, TX 78028 Tach Time: 284.7 Installed Garmin GDL 82 and GA 35 GPS antenna IAW Garmin installation manual 190-01810-00, Rev 6. Installed CI 105 transponder antenna. I certifytransponder have been tested as required by FAR 91.413 and found to comply with Part 43, Appendix F. Signature _____ Date 11/30/2021 A&P 3466434 IA

YEAR: / DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				465 Airport Road Fredericksburg TX (830) 990-9050 Airframe **Make:** Cub Crafters **Date:** 08/01/2022 **Model:** CC11-160 **Hobbs Time:** 329.0 **S/N:** CC11-00146 **Total Time:** 240.0 **Registration:** N844ES Installed new Earth-X EXT 680C Battery. Ops checked good. Adjusted throttle linkage to add some friction to stop creeping when in cruise. I certify that this aircraft has been repaired and inspected in accordance with current FAA regulations and is approved for return to service for work performed. Stephen Jeanes A&P 3291049

YEAR: / DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				TAC·AERO ELITE 465 Airport Road Fredericksburg Texas, 78624 Make CubCrafters Model CC11-160 S/N CC11-00146 Engine Time 279.0 Total Time 380.5 Registration N844ES Removed 26" Alaska Bushwheels and replaced with new 26" Alaska Bushwheels Blue Jeanes A&P 3291049 I/A Date: 2/23/23 Signature:

YEA

DAT

Description of Inspections, Tests, Repairs and Alterations

TAC·AERO ELITE

465 Airport Road
Fredericksburg
Texas, 78624

Make: Cub Crafters
Model: CC11-160
S/N: CC11-00146

Engine Time: 282.9
Total Time: 386.2
Registration: N844ES

Performed Condition Inspection IAW CubCrafters CC11-160 inspection checklist and FAR 43 Appendix D. Lubricated all pulleys, hinges, bellcranks, and moving parts. Inspected and tested ELT as per 91.207(d) found OK. ELT battery expires 1-2024. Removed tail wheel assy., cleaned, inspected, lubricated, and installed. Replaced ignition back up battery with new PS 1221-S battery. Inspected brake system and serviced with 5606 fluid. Inspected exhaust system and cleaned oil breather Venturi. Installed new induction air filter.

Checked Service Bulletins.

I certify that this Airframe has been inspected IAW the scope and detail of appendix D, FAR part 43 and has been determined to be in a condition for safe operation.

Blue Jeanes **A&P 3291049 I/A** Date: **3/23/23** Signature:

YEAR: DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	**Description of Inspections, Tests, Repairs and Alterations** Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
05/31/23	TACH: 318.4			N844Es

Removed left hand fuel tank due to leakage. Reinstalled repaired tank IAW Cub Crafters S10020- Rev. C. Aircraft returned to service.

AP3032247

YEAR: / DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				Airframe

Make: CubCrafters
Model: CC11-160
S/N: CC11-00146

TAC·AERO

75 Airport Road
Fredericksburg, Tx
78624
(844) FLY-CUBS

Date: 12-21-23
Tach: 355.9
Hobbs: 477.5
A/C Reg: N844ES

Installed new Internal back-up battery pn.-100096-000, sn.- 4623 in Dynon FlightDEK 180. Replaced L/H rudder return spring pn-SP91004001. Operational check. Good.

I certify that this aircraft has been repaired IAW current FAA regulations and is returned to service.

Blue Jeanes A&P 3291049 IA

YEAR: / DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				Airframe

Make: CubCrafters
Model: CC11-160
S/N: CC11-00146

TAC·AERO

75 Airport Road
Fredericksburg, Tx
78624
(844) FLY-CUBS

Date: 2-1-2024
Eng. Time: 356.7
Total Hrs: 478.7
A/C Reg: N844ES

Removed Dynon DEK 180 PN-100564-000 SN-003069 and installed Remanufactured Dynon DEK 180 PN-100564-001 SN-1736. Operational check good.

Blue Jeanes A&P 3291049 IA

YEAR:	RECORDING TACH	TODAY'S FLIGHT	TOTAL TIME IN	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE				

Cub Crafters CC11-160 DATE 4-17-24 WO# 18704 N# 844ES
TACH: 488.8

TRANSPONDER Garmin GTX327 ENCODER Dynon FlightKit D-180

The altimeter and automatic pressure altitude reporting system has been tested and inspected per FAR 91.217, and found to comply.

The transponder has been tested and inspected per FAR 91.413, and found to comply with Appendix F of Part 43.

Pippen-York, Inc.
Dba A Flying Machine Company
555 Airport Road
Fredericksburg, Texas 78624
830-997-8205 F.A.A. C.R.S. FMZR327K

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE				

Airframe

Make: CubCrafters
Model: CC11-160
S/N: CC11-00146

TAC

75 Airport Road
Fredericksburg, Tx
78624
(844) FLY-CUBS

Date: 4-19-2024
Tach: 363.8
Hobbs: 488.8
A/C Reg: N844ES

Performed Condition Inspection on Airframe on this date IAW FAR 43 Appendix D and CubCrafters inspection checklist. Cleaned, inspected and lubricated all pulleys, bellcranks, rollers, hinges and bearings. Installed new ELT battery pn-455-0012. Function checked ELT battery IAW 91.207(d). Expiration date: 1-2028. Cleaned fuel filter. Inspected exhaust system. Installed new induction air filter pn-PC54108-001. Installed new Ignition back-up battery pn- PS 1221 S. Removed tailwheel assembly, cleaned, inspected, regreased, assembled, and installed. Installed new Thrust washer pn-ABI3206-00 in tail wheel assy. Inspected and serviced brake system. C/W all relevant SB's. Checked AD compliance, no ADs applicable at this time. Run-up, leak check. Operational check. Good.

I certify that this aircraft has been inspected IAW an Annual Inspection per scope and detail of appendix D, FAR Part 43 and has been determined to be in an airworthy condition.

Blue Jeanes A&P 3291049 IA

YEAR: ____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				Airframe Make: CubCrafters Model: CC11-160 S/N: CC11-00146 TAC•TACTO 75 Airport Road Fredericksburg, Tx 78624 (844) FLY-CUBS Date: 9-12-24 Engine Hrs.: 407.1 Total Hrs.: 541.4 A/C Reg: N844ES Replaced induction air filter. Removed tailwheel assembly, cleaned, inspected, regreased, assembled, and installed with new tail wheel tire and new tube. Inspected and serviced brake system. Run-up, leak check. Operational check. Good. I certify that this aircraft has been repaired/serviced IAW current FAA regulations and has been determined to be in a condition for safe operation.. Blue Jeanes A&P 3291049 IA

YEAR: ____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

YEAR:	RECORDING TACH	TODAY'S FLIGHT	TOTAL TIME IN	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair
DAT				A/C Reg: N844ES Make: CubCrafters Model: CC11-160 S/N: CC11-00146 TAC•AERO 75 Airport Road Fredericksburg, Tx 78624 (844) FLY-CUBS Date: 08/27/2025 Tach: 426.6 Total Hrs: 426.6 Performed Condition Inspection on Airframe on this date IAW 14 CFR part 43 Appendix D and CubCrafters inspection checklist. Cleaned, inspected and lubricated all pulleys, bellcranks, rollers, hinges and bearings. Function checked ELT battery IAW 91.207(d). Expiration date: 01/2028. Cleaned fuel filters. Inspected exhaust system. Replaced induction air filter. Removed tailwheel assembly, cleaned, inspected, regreased, assembled, and installed. Inspected and serviced brake system. Replaced R/H lower aileron cable. Checked cable tension. Run-up, leak check. Operational check. Good. I certify that this aircraft has been inspected IAW a Condition Inspection per scope and detail of 14 CFR part 43 Appendix D and has been determined to be in a condition for safe operation. Hugh Pittman A&P 3803946

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE				